

ATC ASSOCIATES, INC. INDOOR AIR QUALITY FIELD REPORT

Page 1 of 6

Time: 11:00 AM LOCATION: PS 234

DATE: 6/21/02 PROJECT NO: 19125-0279

Location	Occupants	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
OUTSIDE							
MAIN ENTRANCE	0	81.5	54.2	562	1	62	0
NEXT TO MAIN DESK	0	81.5	54.2	571	1	60	0
NORTHWEST CORNER	0	82.1	40.1	601	1	62	0
WESTSIDE	0	82.1	40.1	558	1	62	0
SOUTHWEST CORNER	0	82.3	39.7	559	1	61	0
COURTYARD	0	82.2	39.8	601	1	55	0
NORTHEAST CORNER	1	82.1	45.2	610	1	55	0
MAIN ENTRANCE	3	82.1	54.1	599	1	58	0
SOUTHEAST CORNER	0	82.1	54.1	579	1	60	0
SOUTHSIDE	1	82.1	53.9	558	1	60	0
Guideline levels ASHRAE/AIHA		68 - 75°F/winter 73-79 °F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³	1 ppm

Comments:

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: *[Signature]*

Date: 6/21/02

ATC ASSOCIATES, INC. INDOOR AIR QUALITY FIELD REPORT

Page ² of ~~10~~ 6

Time: 11:30 AM


LOCATION: PS 234

DATE: 6/21/02 PROJECT NO: 19125-

Location	Occupants	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m³)	TVOCs (ppm)
CATERIA	10	69.9	56.1	809	1	25	0
Hall By Gym	2	72.1	56.1	641	1	20	0
Gym	1	70.9	57.3	618	1	29	0
MAIN FOYER	3	72.3	58.3	631	1	26	0
MAIN DESK	1	73.1	59.1	598	1	26	0
Hall By elevator	2	73.6	58.8	629	1	24	0
Hall By EXIT 1	1	73.6	58.6	641	1	19	0
Hallway 114 NEXT TO Rm	0	72.9	58.9	573	1	22	0
116		73.1	58.6	571	1	22	0
118	24	72.9	57.1	1341	1	18	0
Guideline levels ASHRAE/AIHA		68 - 75°F/winter 73-79 °F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m³	1 ppm

Comments:

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: 

Date: 6/21/02

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 3 of 6Time: 1:40 PMLOCATION: PS 234DATE: 6/21/02 PROJECT NO: 19125-

Location	Occupants	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
323	21	73.1	59.1	1117	1	22	0
325	26	72.1	58.6	1261	1	19	0
310	2	72.1	58.6	909	1	20	0
324	0	70.1	56.6	610	1	18	0
312 HALLWAY	0	70.3	56.9	586	1	16	0
316	21	69.7	57.1	620	1	17	0
318	26	69.9	56.6	1126	1	18	0
320	23	70.1	58.6	1231	1	19	0
322	20	70.2	58.6	1146	1	24	0
NEXT TO STAIRS #3 HALLWAY	0	71.1	59.1	609	1	23	0
Guideline levels ASHRAE/AIHA		68 - 75°F/winter 73-79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: K. Z. [Signature]Date: 6/21/02

ATC ASSOCIATES, INC.

Page 4 of 6

INDOOR AIR QUALITY FIELD REPORT

Time: 12:01 pm


LOCATION: PS 234

DATE: 6/21/02 PROJECT NO: 19125-

Location	Occupants	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
HALLWAY NEXT TO RM 210	0	72.1	58.6	601	1	22	0
225	21	70.6	56.9	1188	1	23	0
223	22	70.9	56.5	1135	1	26	0
NEXT TO ELEVATOR BANK 2ND FLOOR	1	69.9	54.1	570	1	19	0
214	1	70.1	56.7	626	1	18	0
206	0	71.3	58.1	586	1	16	0
206 HALLWAY	3	70.3	56.1	566	1	21	0
215	14	71.2	57.7	1055	1	20	0
211	0	71.4	57.6	607	1	20	0
201	1	72.6	58.4	710	1	20	0
Guideline levels ASHRAE/AIHA		68 - 75°F/winter 73-79 °F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³	1 ppm

Comments:

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: 

Date: 6/21/02

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 5 of 6

Time: 12²¹ pm LOCATION: PS 234 DATE: 6/21/02 PROJECT NO: 19125

Location	Occupants	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
202	1	71.1	58.1	588	1	26	0
301	6	71.6	58.6	716	1	20	0
Hallway/302	0	70.1	56.6	602	1	21	0
305	15	71.2	58.1	1247	1	21	0
304	25	72.2	58.9	1017	1	21	0
311	26	70.9	56.1	1108	1	19	0
306	0	70.8	56.1	610	1	16	0
315	22	71.1	56.1	1031	1	17	0
308	20	71.3	57.7	1017	1	24	0
319	15	70.8	57.7	1036	1	26	0
Guideline levels ASHRAE/AIHA		68 – 75°F/winter 73-79 °F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: K. Uzuda

Date: 6/21/02

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 6 of 6

Time: 12:59 pm LOCATION: PS 234

DATE: 6/21/02 PROJECT NO: 19125

Location	Occupants	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
HALLWAY NEXT TO STAIRWELL 3	0	70.3	56.6	610	1	22	0
120	0	71.1	57.7	909	1	16	0
122	0	71.6	57.6	621	1	15	0
222	26	72.2	58.6	1178	1	19	0
220	30	71.6	57.1	1159	1	21	0
HALLWAY 218	0	70.9	56.1	621	1	26	0
216	26	71.0	57.8	1033	1	19	0
212	0	71.2	59.1	581	1	19	0
229	28	73.1	58.9	1160	1	19	0
227 Hallway	1	70.1	56.1	631	1	16	0
Guideline levels ASHRAE/AIHA		68 - 75°F/winter 73-79 °F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: 

Date: 6/21/02