



AIR MONITORING DATA AND

Page 1 of 2
TURNAROUND TIME

CHAIN OF CUSTODY FORM

CT INFORMATION

7712

15718

98793-88810

☐ 2 hrs ☐ 5 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other PCIS

1. Project Name <u>PS 234M</u>		3. Project # <u>41584-0823</u>		4. Project Monitor: <u>MARK NAKHUMOVICH</u>		4c. Retainer Number: <u>HP107</u>	
2a. Project Address <u>242 Greenwich St, NY, NY 10007</u>		5. Air Sampler: <u>MARK NAKHUMOVICH</u>		6. Type: a. ☐ Background b. ☐ Pre-Abate		c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA	
6. Location: <u>ENTIRE</u>		7. ☐ PCM (0.8 micron MCE) Cassette/Fiber Manufacturer Lot #		8. ☒ TEM (0.45 micron MCE) Cassette/Fiber Manufacturer Lot # <u>01205916</u>		f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

AIR SAMPLE RECORD

11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol (liters)	16. # Fibers/Fields minus Blank	17. Fiber Conc.
	12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
16			Field Blank									
17			Field Blank									
01			First Floor-hallway	7:02	11:04	242	8.0	8.0	8.0	1936		
02			Cafeteria	7:04	11:05	241	8.0	8.0	8.0	1928		
03			Gymnasium	7:06	11:06	240	8.0	8.0	8.0	1920		
04			Auditorium	7:08	11:08	240	8.0	8.0	8.0	1920		
05			North playground	7:10	11:11	241	8.0	8.0	8.0	1928		
06			West playground	7:12	11:13	241	8.0	8.0	8.0	1928		
07			Roof-South PART	7:14	11:15	241	8.0	8.0	8.0	1928		
08			First Floor-hallway	11:04	15:05	241	8.0	8.0	8.0	1928		
09			North playground	11:11	15:13	242	8.0	8.0	8.0	1936		
10			West playground	11:13	15:14	241	8.0	8.0	8.0	1928		
11			Roof-South PART	11:15	15:17	242	8.0	8.0	8.0	1936		
12			Classroom # 211	7:18	11:18	240	8.0	8.0	8.0	1920		

CHAIN OF CUSTODY

19. Received By: <u>Y. Efsthion</u>	20. Date: <u>15/11/02</u>	21. Time: <u>16:35</u>
22. Signed By: <u>Y. Efsthion</u>		

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>ATC-TECH</u>	23. Date: <u>5.11.02</u>	24. Time: <u>21:20</u>
a. Analyzed By: <u>RRNY</u>		
b. QC By:		
c. Lab Order #:	<u>7712</u>	
25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079		

AIR MONITORING DATA
AND
CHAIN OF CUSTODY FORM

NOT INFORMATION



ENTIRE 11/5

5/11		ENTRANCE		LOCATION:		7. ☐ PCM (B. nation MCO)		8. ☒ TEM (B. 45 nation MCO)		9. Type:		☐ Pre-Abate ☐ Background ☐ Abatement		☐ OSTIA ☐ Post-Abate ☒ Ambient ☐ Environmental	
2. Project Name PS 334W		3a. Project Address 293 Greenleaf St, NY, NY 10003		3b. Project # K1584-0823		4. Project Monitor MARK NAKHUMNOVICH		4b. Air Sampler MARK NAKHUMNOVICH		4c. Rotameter Number HP107					

AIR SAMPLE RECORD

Sample ID	Pump Number	12. Sample Location:			13. Time (24 hrs clock)						14. Flow Rate (L/min)	
		12a IWA	12b DWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14d. Avg	15. Total Air Vol (liters)	
18				Field Blank								
13				Class room # 225	7:20	11:21	241	8.0	8.0	8.0	1928	
14				Class room # 218	7:22	11:23	241	8.0	8.0	8.0	1928	
15				Kinder garden	7:25	11:27	242	8.0	8.0	8.0	1936	

IN OF CUSTODY		19 Received By:		20 Date:		21 Time:	
[Signature]		[Signature]		05/11/16		16:35	
LAB INFORMATION (ATC ELAP # 10879, ATC NCLAP # 1187)		22 Lab Name:		23 Date:		24 Time:	
[Signature]		ATC - EN		5/11/16		21:20	
a. Analyzed By:		b. QC By:		c. Lab Batch #:		d. Lab Batch #:	
[Signature]		[Signature]		1712		1712	
25. Microscope Make/Serial #:		26. Microscope Make/Serial #:		27. Microscope Make/Serial #:		28. Microscope Make/Serial #:	
[Blank]		[Blank]		[Blank]		[Blank]	

REFSTATION 2893315

Y. ESTATION

Receptionist's (44677)-115