NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

ATC ASSOCIATES INC.

Page 1 of 1

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other RUSH

7280 1/720 82629-82648

PROJECT INFORMATION

1. Client:	2. Project Name / 2a. Project Address	3. Project # / 3a. Task #	4. Project Monitor: / 4a. Air Sampler:	4c. Rotameter Number:
NYC-BOE	HS ECONOMICS + Finance / 100 TRINITY PLACE NY NY	14584-865 / 00001	Kevin / FITZPATRICK	SD087

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:
3-31-02	ENTIRE SCHOOL VARIOUS LOCATIONS	Cassette/Filter Manufacture: ____ Lot #: ____	Cassette/Filter Manufacture: ____ Lot #: 9811667	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
01				Field Blank									
02				Field Blank									
03				OPEN BLANK.									
04				OUTSIDE MAIN ENTRANCE NORTHSIDE OF SIDEWALK.	7 00 AM	11 00 AM	240	8.0	8.0	8.0	1920		
05				OUTSIDE OF AUDITORIUM 1ST FLOOR LOBBY AREA.	7 02 AM	11 02 AM	240	8.0	8.0	8.0	1920		
06				7TH FLOOR STAIRWELL "B" SOUTHSIDE	7 09 AM	11 09 AM	240	8.0	8.0	8.0	1920		
07				EASTSIDE OF ROOF AREA.	7 06 AM	11 06 AM	240	8.0	8.0	8.0	1920		
08				SOUTHSIDE OF AUDITORIUM 1ST FLOOR.	7 09 AM	11 10 AM	241	8.0	8.0	8.0	1928		

CHAIN OF CUSTODY

	18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I	Kevin Fitzpatrick	M I	3.31.02	4PM
II				
III				

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:	3/31	18:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: MARK TERESEN

27. Result To: ____
Beeper/Phone #'s ____

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_002899043

NYC-WTC_000227595

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

ATC ASSOCIATES INC.

7280

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other RUSH

PROJECT INFORMATION

1. Client:	2. Project Name: H.S ECONOMICS + FINANCE	3. Project #: 14584-865	4. Project Monitor: Kevin	4c. Rotameter Number:
NYC- BOE	2a. Project Address: 100 TRINITY PLACE NYM	3a. Task #: 00001	4a. Air Sampler: FITZPATRICK	SP087

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:	
3-31-02	ENTIRE SCHOOL VARIOUS LOCATIONS	Cassette/Filter Manufacture: ____ Lot #: ____	Cassette/Filter Manufacture: ____ Lot #: 98116617	a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA
					f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
09				9TH FLOOR HALLWAY. OUTSIDE OF MENS ROOM.	7:11 AM	12:12 AM	241	8.0	8.0	8.0	1928		
10				8TH FLOOR. TEACHERS LOUNGE RM 801	7:14 AM	12:16 AM	242	8.0	8.0	8.0	1936		
11				7TH FLOOR HALLWAY. NEXT TO ROOM 703.	7:17 AM	12:17 AM	240	8.0	8.0	8.0	1920		
12				6TH FLOOR. WESTSIDE OF CLASSROOM 604.	7:21 AM	12:21 AM	240	8.0	8.0	8.0	1920		
13				5TH FLOOR HALLWAY NEXT TO CLASSROOM 503	7:24 AM	12:25 AM	241	8.0	8.0	8.0	1920		
14				4TH FLOOR. CLASSROOM 405 SOUTHSIDE.	7:27 AM	12:27 AM	240	8.0	8.0	8.0	1920		

CHAIN OF CUSTODY

	18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I	[signature]	MJ	3.31.2	4PM
II				
III				

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC	23. Date:	24. Time:
a. Analyzed By:	3/31	18:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: MARK TERSEGNI

27. Result To: ____
Beeper/Phone #'s ____

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_002899044

NYC-WTC_000227596

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other RUSH

PROJECT INFORMATION 7 of 80

1. Client:	2. Project Name: H.S ECONIMICS FINANCE	3. Project #: 14584-865	4. Project Monitor: Kevin Fitzpatrick	4c. Rotameter Number: SD087
NYC- BOE	2a. Project Address: 100 TRINITY PLACE	3a. Task #: 00001	4a. Air Sampler:	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:
3-31-02	ENTIRE SCHOOL VARIOUS LOCATIONS	Cassette/Filter Manufacture: ____ Lot #: ____	Cassette/Filter Manufacture: ____ Lot #: 9811667	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
15				3RD FLOOR HALLWAY OUTSIDE OF CLASSROOM 303	7 31 AM	11 32 AM	241	8.0	8.0	8.0	1928		
16				SOUTHSIDE OF CAFETERIA 8TH FLOOR	7 35 AM	11 35 AM	240	8.0	8.0	8.0	1920		
17				OUTSIDE OF MAIN ENTRANCE NORTHSIDE OF SIDEWALK	11 42 AM	3 42 PM	240	8.0	8.0	80	1920		
18				OUTSIDE OF AUDITORIUM 1ST FLOOR LOBBY AREA	11 44 AM	3 46 PM	242	8.0	8.0	8.0	1936		
19				7TH FLOOR STAIRWELL 'B' SOUTHSIDE	11 46 AM	3 44 PM	241	8.0	8.0	8.0	1928		
20				EASTSIDE OF ROOF AREA	11 48 AM	3 49 PM	241	8.0	8.0	8.0	1928		

CHAIN OF CUSTODY

	18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I	[signature]	MI	3,31,2	4PM
II				
III				

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:		
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager:	27. Result To: ____ Beeper/Phone #'s ____	28. Comments:
MARK TORSEKAR		

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_002899045

NYC-WTC_000227597