NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 1

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other RUSH

PROJECT INFORMATION

7315 17/20 $3342-83361

1. Client:	2. Project Name: HS ECONOMICS + Finance	3. Project #: 14581-865	4. Project Monitor: Kevin	4c. Rotameter Number:
NYC- BOE	2a. Project Address: 100 TRINITY PACE NY NY	3a. Task #: 00001	4a. Air Sampler: FitzPATRICK	SQ087

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:	
4-3-02	ENTIRE SCHOOL VARIOUS LOCATIONS	Cassette/Filter Manufacture: ____ Lot #: ____	Cassette/Filter Manufacture: 0120A16 Lot #: ____	a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
01				Field Blank									
02				Field Blank									
03				open BLANK									
04				OUTSIDE of main ENTRANCE of school	7:04 AM	11:04 AM	240	8.0	8.0	8.0	1920		
05				OUTSIDE of AUDITORIUM in 1ST FLOOR LOBBY.	7:06 AM	11:06 AM	240	8.0	8.0	8.0	1920		
06				SOUTHSIDE of ROOF AREA	7:08 AM	11:08 AM	240	8.0	8.0	8.0	1920		
07				7TH FLOOR STAIRWELL B NORTHSIDE	7:10 AM	11:10 AM	240	8.0	8.0	8.0	1920		
08				SOUTHSIDE of 1ST FLOOR AUDITORIUM	7:12 AM	11:13 AM	241	8.0	8.0	8.0	1928		

CHAIN OF CUSTODY

	18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I	[signature]	[signature]	03/04/02	17:10
II				
III				

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:	9/3	23:00
b. QC By:		
c. Lab Batch #: 7315		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: MARK TERSEGEN

27. Result To: ____
Beeper/Phone #'s ____

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_002899115

NYC-WTC_000227648

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other RUSH

PROJECT INFORMATION

1. Client:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number:
NYC- BOE	H.S ECONOMICS Finance	14584-865	Kevin	SD087
	2a. Project Address 100 TRINITY PLACE NYM	3a. Task # 00001	4a. Air Sampler: Fitzpatrick	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:	
4-3-02	ENTIRE SCHOOL VARIOUS LOCATIONS	Cassette/Filter Manufacture ____ Lot # ____	Cassette/Filter Manufacture ____ Lot # 01209916	a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
09				SOUTHSIDE of 8TH FLOOR CAFETERIA.	7:14 AM	11:15 AM	241	8.0	8.0	8.0	1928		
10				9TH FLOOR Hallway OUTSIDE of RM 904.	7:16 AM	11:16 AM	240	8.0	8.0	8.0	1920		
11				8TH FLOOR CLASSROOM NORTHSIDE RM 801	7:18 AM	11:19 AM	241	8.0	8.0	8.0	1928		
12				7TH FLOOR Hallway NEXT TO RM 702	7:20 AM	11:20 AM	240	8.0	8.0	8.0	1920		
13				6TH FLOOR CLASSROM 606 EASTSIDE	7:22 AM	11:23 AM	241	8.0	8.0	8.0	1928		
14				5TH FLOOR Hallway NEXT TO RM 501	7:26 AM	11:27 AM	241	8.0	8.0	8.0	1928		

CHAIN OF CUSTODY

	18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I	[signature]	[signature]	04/03/02	17:00
II				
III				

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:	4/5	23:00
b. QC By:		
c. Lab Batch #: 7315		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: MARK TERPSTEN

27. Result To: ____
Beeper/Phone #'s ____

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_002899116

NYC-WTC_000227649

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other RUSH

PROJECT INFORMATION

1. Client	2. Project Name	3. Project #	4. Project Monitor	4c. Rotameter Number
NYC - BOE	HS ECONOMICS + Finance	14584-865	Kevin	SD087
	2a. Project Address: 100 TRINITY PLACE NY NY	3a. Task # 00001	4a. Air Sampler: FITZPATRICK	

5. Date	6. Abatement Location	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type
4-3-02	ENTIRE SCHOOL VARIOUS LOCATIONS	Cassette/Filter Manufacture: ____ Lot #: ____	Cassette/Filter Manufacture: ____ Lot #: ____	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
15				4TH FLOOR CLASSROOM 404 SOUTHSIDE	7 28 AM	11 28 AM	240	8.0	8.0	8.0	1920		
16				3RD FLOOR HALLWAY. OUTSIDE OF CLASSROOM 404	7 30 AM	11 30 AM	240	8.0	8.0	8.0	1920		
17				OUTSIDE OF MAIN ENTRANCE OF SCHOOL	11 32 AM	3 32 PM	240	8.0	8.0	8.0	1920		
18				OUTSIDE OF AUDITORIUM ON 1ST FLOOR LOBBY.	11 34 AM	3 35 PM	241	8.0	8.0	8.0	1928		
19				SOUTHSIDE OF ROOF AREA.	11 37 AM	3 38 PM	241	8.0	8.0	8.0	1928		
20				7TH FLOOR STAIRWELL 'B' NORTHSIDE.	11 41 AM	3 41 PM	240	8.0	8.0	8.0	1920		

CHAIN OF CUSTODY

	18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I	[signature]	[signature]	03/04/02	1710
II				
III				

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:	4/5	23:00
b. QC By:		
c. Lab Batch #: 7315		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: MARC TERESEN

27. Result To: ____
Beeper/Phone #'s ____

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_002899117

NYC-WTC_000227650