



DURING SCHOOL
HOURS - 16/19

AIR MONITORING DATA AND

CHAIN OF CUSTODY FORM

RUSH

Page I of III

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard **RUSH**
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other

PROJECT INFORMATION

1. Client: NYC BOE	2. Project Name: PS 89M	3. Project #: 14584-08M	4. Project Monitor: Danret Finkley	4c. Rotameter Number: HP125
5. Date: WED 1-23-02	2a. Project Address: 801 WARREN STREET	3a. Task #: LOT # 916	4a. Air Sampler: LOT # 916	
6. Abatement Location: ROOF PLAYGROUND; 1ST FL. HALLWAY	7. ☒ PCM (0.3 micron MCE)	8. ☒ TEM (0.45 micron MCE) MULTI-METAS	9. Type: a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA
				f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. INVA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
017				Field Blank CLOSED.									
				Field Blank									
01	389932	IN side	/	CAFETERIA. S EOUND. NEAR TEACHERS KITCHEN.	7:55	12:23	268	8.0	8.0	8.0	2144		
02	389704	IN side	/	1ST FLOOR HALLWAY OUTSIDE CAFETERIA	7:56	12:25	2269 56	8.0	8.0	8.0	2152		
03	389852	OUT side	/	PLAYGROUND - NORTH. AT COLUMN NEAR BENCH.	8:59	12:28	269	8.0	8.0	8.0	2152		
04	389780	OUT side	/	PLAYGROUND SOUTH. AT COLUMN NEAR BENCH.	8:07	12:30	263	8.0	8.0	8.0	2104		
05	389807	IN side	/	GYMNASIUM RM 315.	8:26	12:33	247	8.0	8.0	8.0	1976		
06	389834	IN side	/	AUDITORIUM RM 217	8:36	12:35	229	8.0	8.0	8.0	1932		

CHAIN OF CUSTODY

18. Relinquished By: [Signature]	19. Received By: RRU	20. Date: 1/24/02	21. Time: 5:00
26. ATC Project Manager: Andreas Andreou	27. Result To: Andreas Andreou	Beeper/Phone #'s: 646-772-1153	

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date: 1/24/02	24. Time: 2:40	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: RRU	b. QC By:	c. Lab Batch #:	Analysis Methodology: PCM - NIOSH 7400A TEM - AHERA
28. Comments:			

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)



DURING School
Hours

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

RUSH

Page II of III

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other **RUSH**

PROJECT INFORMATION

1. Client: NYC BOE	2. Project Name: PS 89M	3. Project #: 14584-X	4. Project Monitor: Daniel Finkley	4c. Rotameter Number: HP125
5. Date: WED 1.13.02	2a. Project Address: 801 WARREN STREET	3a. Task #:	4a. Air Sampler:	
6. Abatement Location: ROOF PLAYGROUND, 1ST FL. HALLWAY	7. ☐ PCM (0.3 micron MCE)	8. ☒ TEM (0.45 micron MCE) MULTI-METAS	9. Type:	
1.13.02	2-5th floors	Cassette/Filter Manufacturer: LOT # 916	a. ☐ Background	c. ☐ Abatement
		Lot #: 00263916	b. ☐ Pre-Abate	d. ☐ Post-Abate
			e. ☐ OSHA	f. ☐ Environmental
				g. ☒ Ambient
				h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
018				Field Blank CLOSED									
				Field Blank									
07	389721		OUT	ROOF ABOVE 5TH floor	9:10 AM	12:46 PM	216	8.5	8.5	8.5	1836		
			Side	CENTRAL LOCATION									
08	389932		IN	1ST FLOOR HALLWAY outside	12:26 PM	4:16 PM	230	8.0	8.0	8.0	1840		
			Side	Cafeteria									
09	389852		OUT	PlayGround NORTH	12:28 PM	4:18 PM	230	8.0	8.0	8.0	1840		
			Side										
010	389780		OUT	PlayGround SOUTH	12:30 PM	4:20 PM	230	8.0	8.0	8.0	1840		
			Side										
011	389721		OUT	ROOF ABOVE 5TH floor	12:46 PM	4:36 PM	230	8.0	8.0	8.0	1840		
			Side	CENTRAL LOCATION									

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I [Signature]			
II [Signature]	R. Ruff	1/24/02	5:00
III			
26. ATC Project Manager:	27. Result To:		
Andreas Andreou	Andreas Andreou		
	Beeper/Phone #s: 646.772.1153		

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:	25. Microscope Make/Serial #:
a. Analyzed By: [Signature]	1/24/02	8:40	☐ Nikon Labophot 238913
b. QC By:			☐ Nikon Labophot 238917
c. Lab Batch #:			☐ Nikon Labophot 239079
28. Comments:	Analysis Methodology		
67-DF	PCM - NIOSH 7400A		
	TEM - AHERA		

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY 1 (1/01)



AFTERSCHOOL
HOURS

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

RUSH

Page

of

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other **RUSH**

PROJECT INFORMATION

1. Client: **NYC BOE** 2. Project Name: **PS 89M** 3. Project #: **14584-** 4. Project Monitor: **Danrel Finkley** 4c. Rotameter Number: **HP125**

2a. Project Address: **801 WARREN STREET** 3a. Task #: **101-916** 4a. Air Sampler: **Danrel Finkley**

5. Date: **WED 1-23-02** 6. Abatement Location: **PLAYGROUND, 1ST FLOOR HALLWAY** 7. ☐ PCM (0.5 micron MCE) ☒ TEM (0.45 micron MCE) **MULTI-METAS** 8. ☒ TEM (0.45 micron MCE) **MULTI-METAS** 9. Type: ☐ Background ☐ Abatement ☐ Post-Abate ☐ Pre-Abate ☐ OSHA ☒ Environmental ☒ Ambient ☐ Other

10. **1-23-02** 11. **VENTIL** 12. **PCM (0.5 micron MCE)** 13. **TEM (0.45 micron MCE)** 14. **LOT # 00263916**

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
019				Field Blank open									
				Field Blank									
012		IN SIDE		class room 226	15:20	19:10	230	8.0	8.0	8.0	1840		
				NORTH side Ventilators									
013		IN SIDE		class room 302	15:15	19:15	230	8.0	8.0	8.0	1840		
				EAST side Ventilators									
014		IN SIDE		class room 501	15:10	19:05	235	8.0	8.0	8.0	1880		
				SOUTH side Ventilators									
015		IN SIDE		2ND FLOOR HALLWAY SOUTH END	15:24	19:14	230	8.0	8.0	8.0	1840		
				TOP OF PLATFORM									
016		IN SIDE		4TH FLOOR HALLWAY SOUTH END	15:26	19:16	230	8.0	8.0	8.0	1840		
				TOP OF PLATFORM									

CHAIN OF CUSTODY

18. Relinquished By: **[Signature]** 19. Received By: **RRly** 20. Date: **1/24/02** 21. Time: **5:00**

26. ATC Project Manager: **Andreas Andreou** 27. Result To: **Andreas Andreou** Beeper/Phone #'s: **646-772-1153**

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: **ATC-TEM** 23. Date: **1/24/02** 24. Time: **8:40**

a. Analyzed By: **RRly** b. QC By: c. Lab Batch #:

25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079

Analysis Methodology: ☒ PCM - NIOSH 7400A ☒ TEM - AHERA

28. Comments:

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)