NYC 9/11 Public Portal Document

JLC ENVIRONMENTAL CONSULTANTS, INC. — **AIR SAMPLE LOG**

0410A-823

CLIENT: MAZAL GROUP LLC — PROJECT NUMBER: 01-21558-

SITE: 100 JOHN STREET — LOBBY — PROJECT MANAGER: KHAN

TECHNICIAN: ROBERTO WALLER — SIGNATURE: [signature] — DATE: 10/24/01

WHITE COPY = FILE
YELLOW COPY = LABORATORY
PINK COPY = PROJECT MANAGER

PAGE 01 OF 01

OK

SAMPLE I.D.	DESCRIPTION / LOCATION	TIME (military) start/end	TIME min	FLOW RATE start/end	FLOW RATE l/m	VOLUME (l)	FIBERS/ FIELD	RESULTS (f/cc)
SAMPLE # 001 FIELD # LAB # 08298 PUMP #	LOBBY - LEFT SIDE OF FRONT DESK	0838/1039	120	15/15	15	1863	5/100	0.001 <LOD
SAMPLE # 002 FIELD # LAB # 08299 PUMP #	MIDDLE LOBBY - LEFT SIDE OF FLOWERS' JAR - FRONT ELEVATORS	1040/1240	120	15/15	15	1863	6/100	0.002
SAMPLE # 003 FIELD # LAB # 08300 PUMP #	LOBBY - LEFT SIDE OF FRONT DESK	1241/1441		15/15	15	1863	5/100	0.001 <LOD
SAMPLE # 004 FIELD # LAB # 08301 PUMP #	MIDDLE LOBBY - LEFT SIDE OF FLOWERS' JAR - FRONT ELEVATORS	1442/1642		15/15	15	1863	4/100	0.001 <LOD
SAMPLE # FIELD # LAB # PUMP #								
SAMPLE # 005 FIELD # LAB # 08302	FIELD BLANK						0/100	FB
SAMPLE # 006 FIELD # LAB # 08303	FIELD BLANK						0/100	FB

CASSETTE	ROTOMETER	TURNAROUND TIME	TYPE	RESULTS TO
☒ PCM (0.8 MICRON MCE)	ID#	☐ 2 HRS ☐ 24 HRS	☐ PRE-ABATE ☐ OSHA	NAME
☐ TEM (0.45 MICRON MCE)	C.F. 1.085	☐ 4 HRS ☐ 48 HRS	☐ DURING ☐ ENVIRON	PH/PGR#( )
LOT #	CALIB. DATE / /	☐ 6 HRS ☐ OTHER	☐ POST-ABATE ☒ AMBIENT	DATE / / TIME :

			DATE	TIME
RELINQUISHED BY:(print) ROBERTO WALLER	(sign) [signature]		10/24/01	
RECEIVED BY:(print) MS	(sign) [signature]		10/25/01	
RELINQUISHED BY:(print)	(sign)		/ /	
RECEIVED BY:(print)	(sign)		/ /	
ENTERED BY:(print)	(sign)		/ /	
CORRECTED BY:(print)	(sign)		/ /	

LAB NAME:	METHODOLOGY	MICROSCOPE/SERIAL #	COMMENTS:
ANALYZED BY: TM	☐ PCM - NIOSH 7400.A	☐ OLYMPUS BH2/204104	
DATE: 10/25/01 TIME:	☐ TEM - AHERA	☐ OLYMPUS CHS/7C0021	
QC BY: DATE:	☐ TEM - EPA LEVEL II	28	

CONFIDENTIAL, SUBJECT TO PROTECTIVE ORDER NO. 1, JAN. 2013

NYC-WTC_000229606