NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

ANALYSIS REPORT
ASBESTOS IN AIR
Transmission Electron Microscopy

CLIENT: Department of Design and Construction - 30-30 Thomson Avenue, Long Island City, NY 11101
PROJECT ADDRESS: Stuyvesant H.S., 345 Chambers St., NY, NY 10282 Pier #25

Lab ID#	Client Sample ID#	Sample Location	Volume (liters)	Grid Openings Examined	Filter Area (mm^2)	Analytical Sensitivity (struct/cc air)	Asbestos Type(s)	Asbestos Structures (microns) 0.5-5.0	>5.0	Detected Total	Structure Density (struc/mm^2) Total	Structure Concentration (struc/cc) Total
T0202242-01	1	North Entrance of School - East	1800	6	385	0.0043	ND	0	0	0	<20.00	<0.0043
T0202242-02	2	North Entrance of School - West	1800	6	385	0.0043	ND	0	0	0	<20.00	<0.0043

Area Analyzed: 0.0600 mm^2
Grid Opening Area: 0.010 mm^2
Date Collected: 02/24/02(07:00-17:00)

Date Received: 02/24/02
Date Analyzed: 02/25/02
Date of Report: 02/25/02

Analyst: AB
Alex Barengolts

Lab Manager: David Chen

Analysis performed according to AHERA Method (EPA 40 CFR Part 763 - Appendix A).Samples will be stored for ninety (90) days and then returned to the client upon request.
Sample volume is below recommended limit of the method

AIHA #: 100269 NIST-NVLAP # : 102047 NYS-DOH ELAP#: 11273

SUBJECT TO PROTECTIVE ORDER NO.3, JULY 2009 CONFIDENTIAL,
CITY_21MC100_011815837

NYC-WTC_000229663