

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos ReportColden Corporation
Attn: David DeLalla
Robert Morris Building
100 North 17th St. 9th Fl.
Philadelphia, PA 19103

Date Received 01/04/2002 SciLab Job No. 202011202
 Date Examined 01/04/2002 P.O. # 02100
 Page 1 of 2
 RE: 02100; Battery Park City Parks Conservancy; West Thomas
 Park

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
010202-S-1	202011202-01	No	NAD

Location: North End-Raised Planter**Description:** Brown, Homogeneous, Soil (Composite)**Asbestos Types:****Other Material:** Cellulose 5. %, Fibrous glass Trace, Synthetic fibers Trace,
Non-fibrous 95. %

010202-S-2	202011202-02	No	NAD
------------	--------------	----	-----

Location: South End-Raised Planter**Description:** Brown, Homogeneous, Soil (Composite)**Asbestos Types:****Other Material:** Cellulose 3. %, Fibrous glass Trace, Synthetic fibers Trace,
Non-fibrous 97. %

010202-S-3	202011202-03	No	NAD
------------	--------------	----	-----

Location: Play Structure-East Side**Description:** Tan, Homogeneous, Soil (Composite)**Asbestos Types:****Other Material:** Cellulose 2. %, Fibrous glass Trace, Non-fibrous 98. %

010202-S-4	202011202-04	No	NAD
------------	--------------	----	-----

Location: Play Structure-West Side**Description:** Tan, Homogeneous, Soil (Composite)**Asbestos Types:****Other Material:** Cellulose 2. %, Fibrous glass Trace, Non-fibrous 98. %

CONFIDENTIAL,

CITY_21MC100_003387146

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

**SCIENTIFIC LABORATORIES, INC.**

117 EAST 30TH STREET

NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos Report


Colden Corporation
Attn: David DeLalla
Robert Morris Building
100 North 17th St. 9th Fl.
Philadelphia, PA 19103

Date Received 01/04/2002 SciLab Job No. 202011202
Date Examined 01/04/2002 P.O. # 02100
Page 2 of 2
RE: 02100; Battery Park City Parks Conservancy; West Thomas
Park

Reporting Notes:

Analyzed by: John Koubiadis

*NAD/NSD = no asbestos detected; NA = not analyzed; NA/PS = not analyzed / positive stop; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #200546-0) and ELAP PLM Analysis Protocol 198.1 for New York samples (NYSDOH ELAP Lab # 11480); Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). National Institute of Standards and Technology Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This PLM report relates ONLY to the items tested. AIHA# 102843; VT Cert # AL016055

Reviewed By: 

CONFIDENTIAL,

CITY_21MC100_003387147

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008




Customer: Colden Corporation

Workorder No. 0201-00011

To the best of my knowledge this report is true and accurate.

Authorized By:


John J. Sulkowski, Laboratory Director

Certifications:

MA: MA069

NY:1098

CT: PH0119

RI:A45

CA:205

ME:MA06

NJ: 59744

Page: 3 of 3

CONFIDENTIAL,

CITY_21MC100_003387148

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008