



Customer-Focused Solutions

1430 Broadway, 10th Fl. New York, New York 10018

Phone: (212) 221-7822 - Fax: (212) 221-7840

LMDC Air Metals Profile

Client Lower Manhattan Development Corporation
 Address One Liberty Plaza, 20th Floor
 New York, NY 10006
 Collected By D. Katehis
 Collected 8/21/2005
 Rotometer Standard

Job Number 46600-0000-00001
 Date Received 8/22/2005
 Date Analyzed 8/22/2005
 Job Location 130 Liberty Street

Lab ID 010503249-0001 Matrix Air
 Field ID M-082105-1255
 Location Washington Street/Albany Street

<u>Parameter</u>	<u>Start</u>	<u>End</u>	<u>Flow</u>	<u>Volume</u>	<u>Result</u>	<u>Units</u>	<u>MDL</u>	<u>MCL</u>	<u>Flag</u>
Barium, Total	15:59	16:01	3.95	5696	<0.88	µg/m3	0.88	500	
Beryllium, Total	15:59	16:01	3.95	5696	<0.035	µg/m3	0.035	1	
Cadmium, Total	15:59	16:01	3.95	5696	<0.035	µg/m3	0.035	2.5	
Chromium, Total	15:59	16:01	3.95	5696	<0.088	µg/m3	0.088	500	
Copper, Total	15:59	16:01	3.95	5696	<0.18	µg/m3	0.18	500	
Lead, Total	15:59	16:01	3.95	5696	<0.088	µg/m3	0.088	30	
Manganese, Total	15:59	16:01	3.95	5696	<0.13	µg/m3	0.13	1000	
Nickel, Total	15:59	16:01	3.95	5696	<0.18	µg/m3	0.18	500	
Zinc, Total	15:59	16:01	3.95	5696	<0.18	µg/m3	0.18	2500	

Lab ID 010503249-0002 Matrix Air
 Field ID M-082105-1256
 Location Albany Street/Greenwich Street

<u>Parameter</u>	<u>Start</u>	<u>End</u>	<u>Flow</u>	<u>Volume</u>	<u>Result</u>	<u>Units</u>	<u>MDL</u>	<u>MCL</u>	<u>Flag</u>
Barium, Total	16:02	16:04	4	5768	<0.87	µg/m3	0.87	500	
Beryllium, Total	16:02	16:04	4	5768	<0.035	µg/m3	0.035	1	
Cadmium, Total	16:02	16:04	4	5768	<0.035	µg/m3	0.035	2.5	
Chromium, Total	16:02	16:04	4	5768	<0.087	µg/m3	0.087	500	
Copper, Total	16:02	16:04	4	5768	<0.17	µg/m3	0.17	500	
Lead, Total	16:02	16:04	4	5768	<0.087	µg/m3	0.087	30	
Manganese, Total	16:02	16:04	4	5768	<0.13	µg/m3	0.13	1000	
Nickel, Total	16:02	16:04	4	5768	<0.17	µg/m3	0.17	500	
Zinc, Total	16:02	16:04	4	5768	<0.17	µg/m3	0.17	2500	

MDL = Minimum Detection Limit

MCL = Maximum Contaminant Level

> MCL = Exceeds Maximum Contaminant Level

Samples analyzed by EMSL Analytical, Inc.; NY ELAP ID# 10872 and 11506

Page 1 of 3



Customer-Focused Solutions

1430 Broadway, 10th Fl. New York, New York 10018

Phone: (212) 221-7822 - Fax: (212) 221-7840

LMDC Air Metals Profile

Client Lower Manhattan Development Corporation
 Address One Liberty Plaza, 20th Floor
 New York, NY 10006
 Collected By D. Katehis
 Collected 8/21/2005
 Rotometer Standard

Job Number 46600-0000-00001
 Date Received 8/22/2005
 Date Analyzed 8/22/2005
 Job Location 130 Liberty Street

Lab ID 010503249-0003 Matrix Air
 Field ID M-082105-1257
 Location Greenwich Street

<u>Parameter</u>	<u>Start</u>	<u>End</u>	<u>Flow</u>	<u>Volume</u>	<u>Result</u>	<u>Units</u>	<u>MDL</u>	<u>MCL</u>	<u>Flag</u>
Barium, Total	16:05	16:07	4	5768	<0.87	µg/m3	0.87	500	
Beryllium, Total	16:05	16:07	4	5768	<0.035	µg/m3	0.035	1	
Cadmium, Total	16:05	16:07	4	5768	<0.035	µg/m3	0.035	2.5	
Chromium, Total	16:05	16:07	4	5768	<0.087	µg/m3	0.087	500	
Copper, Total	16:05	16:07	4	5768	<0.17	µg/m3	0.17	500	
Lead, Total	16:05	16:07	4	5768	<0.087	µg/m3	0.087	30	
Manganese, Total	16:05	16:07	4	5768	<0.13	µg/m3	0.13	1000	
Nickel, Total	16:05	16:07	4	5768	<0.17	µg/m3	0.17	500	
Zinc, Total	16:05	16:07	4	5768	<0.17	µg/m3	0.17	2500	

Lab ID 010503249-0004 Matrix Air
 Field ID M-082105-1258
 Location Greenwich Street/Liberty Street

<u>Parameter</u>	<u>Start</u>	<u>End</u>	<u>Flow</u>	<u>Volume</u>	<u>Result</u>	<u>Units</u>	<u>MDL</u>	<u>MCL</u>	<u>Flag</u>
Barium, Total	16:08	16:10	4	5768	<0.87	µg/m3	0.87	500	
Beryllium, Total	16:08	16:10	4	5768	<0.035	µg/m3	0.035	1	
Cadmium, Total	16:08	16:10	4	5768	<0.035	µg/m3	0.035	2.5	
Chromium, Total	16:08	16:10	4	5768	<0.087	µg/m3	0.087	500	
Copper, Total	16:08	16:10	4	5768	<0.17	µg/m3	0.17	500	
Lead, Total	16:08	16:10	4	5768	<0.087	µg/m3	0.087	30	
Manganese, Total	16:08	16:10	4	5768	<0.13	µg/m3	0.13	1000	
Nickel, Total	16:08	16:10	4	5768	<0.17	µg/m3	0.17	500	
Zinc, Total	16:08	16:10	4	5768	<0.17	µg/m3	0.17	2500	

MDL = Minimum Detection Limit

MCL = Maximum Contaminant Level

> MCL = Exceeds Maximum Contaminant Level

Samples analyzed by EMSL Analytical, Inc.; NY ELAP ID# 10872 and 11506

Page 2 of 3



Customer-Focused Solutions

1430 Broadway, 10th Fl. New York, New York 10018

Phone: (212) 221-7822 - Fax: (212) 221-7840

LMDC Air Metals Profile

Client Lower Manhattan Development Corporation
 Address One Liberty Plaza, 20th Floor
 New York, NY 10006
 Collected By D. Katehis
 Collected 8/21/2005
 Rotometer Standard

Job Number 46600-0000-00001
 Date Received 8/22/2005
 Date Analyzed 8/22/2005
 Job Location 130 Liberty Street

Lab ID 010503249-0005 Matrix Air
 Field ID M-082105-1259
 Location Washington Street/Cedar Street

<u>Parameter</u>	<u>Start</u>	<u>End</u>	<u>Flow</u>	<u>Volume</u>	<u>Result</u>	<u>Units</u>	<u>MDL</u>	<u>MCL</u>	<u>Flag</u>
Barium, Total	16:11	16:13	3.85	5552	<0.90	µg/m3	0.9	500	
Beryllium, Total	16:11	16:13	3.85	5552	<0.036	µg/m3	0.036	1	
Cadmium, Total	16:11	16:13	3.85	5552	<0.036	µg/m3	0.036	2.5	
Chromium, Total	16:11	16:13	3.85	5552	<0.090	µg/m3	0.09	500	
Copper, Total	16:11	16:13	3.85	5552	<0.18	µg/m3	0.18	500	
Lead, Total	16:11	16:13	3.85	5552	<0.090	µg/m3	0.09	30	
Manganese, Total	16:11	16:13	3.85	5552	<0.14	µg/m3	0.14	1000	
Nickel, Total	16:11	16:13	3.85	5552	<0.18	µg/m3	0.18	500	
Zinc, Total	16:11	16:13	3.85	5552	<0.18	µg/m3	0.18	2500	

MDL = Minimum Detection Limit

MCL = Maximum Contaminant Level

> MCL = Exceeds Maximum Contaminant Level

Samples analyzed by EMSL Analytical, Inc.; NY ELAP ID# 10872 and 11506

Page 3 of 3

CITY_DEP_WORBY_CANNATA_SUBP_000117860