

516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS SCLA Stuyvesant		CONTACT: Hans Sas		SAMPLER (SIGNATURE) <i>[Signature]</i>		DATE 7/30/12		TIME 1:00		SAMPLE(S) SEALED ☒ YES ☐ NO			
PROJECT LOCATION: 345 Chambers		PROJECT # M477-1521/2398		SAMPLER NAME (PRINT) K. Morgan		CORRECT CONTAINER(S) ☒ YES ☐ NO							
				MATRIX (CIRCLE ONE) ☒ WIPE ☐ PAINT ☐ SOIL ☐ OTHER _____									
SAMPLE INFORMATION:				AREA (FT²)		SURFACE MATERIAL				LAB RESULT Neg / Fo			
LABORATORY #		SAMPLE #				LOCATION		WOOD				METAL	
	LW-01	7TH FL CORRIDOR WEST SUPPLY O/S C728		1.0			X					677.6	
	LW-02	7TH FL CORRIDOR RETURN ADJ TO C721		1.0			X					49.3	
	LW-03	7TH FL CORRIDOR EAST SUPPLY Adj #715		1.0			X					16.3	
	LW-04	7TH FL CORRIDOR EAST SUPPLY Adj #705		1.0			X					29.0	
	LW-05	F. BLANK - 1		—			—					—	
	LW-06	F. BLANK - 2		—			—					—	
Fax results 22-406-2535 516-358-2955				TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY 1/1				COMMENTS / INSTRUCTIONS GAR, AT					
RELINQUISHED BY (SIGNATURE) <i>[Signature]</i>		DATE 7/30/12		PRINTED NAME [Name]		RECEIVED BY (SIGNATURE) <i>[Signature]</i>				DATE 7/30/12		PRINTED NAME	
RELINQUISHED BY (SIGNATURE)		DATE		PRINTED NAME		RECEIVED BY LAB (SIGNATURE) <i>[Signature]</i>				DATE 7/30/12		PRINTED NAME	

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

14:30

CITY_21MC100_010236635

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-30-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE: 07-30-02
DATE RECEIVED: 07-30-02
DATE ANALYZED: 07-30-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION (µg/ft²)	DETECTION LIMIT (µg/ft²)
LW-01	20771	7th Floor Corridor West Supply O/S C728	677.6	9.0
LW-02	20771	7th Floor Corridor Return Adj. to C721	49.3	9.0
LW-03	20771	7th Floor Corridor East Supply Adj. 715	16.3	9.0
LW-04	20771	7th Floor Corridor East Supply Adj. 705	<9.0	9.0
LW-05	20771	Field Blank	<9.0 µg	9.0 µg
LW-06	20771	Field Blank	<9.0 µg	9.0 µg

NOTE 1:**THE REPORTING LIMIT (RL) IS 18.0 µg****NOTE 2:**HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft², Window sills 250 µg/ft²,
Window wells 400 µg/ft², Exterior surfaces 800 µg/ft².**NOTE 3:**

Blank units are in µg

ATC ASSOCIATES, INC

104 E 25th Street, 10th Floor

New York, NY 10010

Tel. 212-353-8280

Fax 212-353-8306

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: IL

REPORT PREPARED BY: [Signature]

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: [Signature]

LABORATORY DIRECTOR: [Signature]

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).