

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

030210730

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS NYC SCA		CONTACT: HAMID SAVOJ		SAMPLER (SIGNATURE) <i>Carlos Lopez</i>		DATE 8-6-02		TIME		SAMPLE(S) SEALED ☒ YES / ☐ NO	
PROJECT LOCATION: STUYVESANT H.S.		PROJECT # H477-15217/29881		SAMPLER NAME (PRINT) CARLOS LOPEZ		CORRECT CONTAINER(S) ☒ YES / ☐ NO					
SAMPLE INFORMATION:				MATRIX (CIRCLE ONE): ☒ WIPE ☐ PAINT ☐ SOIL ☐ OTHER							
LABORATORY #	SAMPLE #	LOCATION	AREA (FT ²)	SURFACE MATERIAL WOOD METAL BRICK OTHER				LAB RESULT			
	LW-01	ROOM # 801 Floor by window.	1 FT				FL Tile	12.0			
	LW-02	ROOM # 801 DESK by ENTRANCE	1 FT	X				10.0			
	LW-03	ROOM # 802 Floor by ENTRANCE.	1 FT				tile				
	LW-04	ROOM # 802 TABLE by ENTRANCE	1 FT	X							
	LW-05	ROOM # 802A Floor AT CENTER	1 FT				tile				
	LW-06	ROOM # 802A TABLE by Windows.	1 FT	X							
	LW-07	ROOM # 802B Floor AT CENTER	1 FT				tile				
	LW-08	ROOM # 802B TABLE by window	1 FT	X				11.0			
			TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY 1 / 1				COMMENTS / INSTRUCTIONS				
RELINQUISHED BY (SIGNATURE) <i>Carlos Lopez</i>		DATE 8-6-02 TIME 1752		PRINTED NAME <i>C. Savoj</i>		RECEIVED BY (SIGNATURE) <i>[Signature]</i>		DATE 8/6/02 TIME 556p		PRINTED NAME	
RELINQUISHED BY (SIGNATURE)		DATE TIME		PRINTED NAME		RECEIVED BY LAB (SIGNATURE)		DATE TIME		PRINTED NAME	

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

CITY_21MC100_010236738

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

030210730

516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS NYC SCA		CONTACT: HAMID SAUDJ.		SAMPLER (SIGNATURE) <i>Carlos Jofat</i>		DATE 8-6-02		TIME		SAMPLE(S) SEALED ☒ YES / NO	
PROJECT LOCATION: STUYVESANT H.S.		PROJECT # 1477-15217 / 29881		SAMPLER NAME (PRINT) CARLOS JOFAT		CORRECT CONTAINER(S) ☒ YES / NO					
SAMPLE INFORMATION:				MATRIX (CIRCLE ONE) ☒ WIPE ☐ PAINT ☐ SOIL ☐ OTHER							
LABORATORY #	SAMPLE #	LOCATION	AREA (FT ²)	SURFACE MATERIAL WOOD METAL BRICK OTHER				LAB RESULT			
	LW-09	ROOM # 802C Floor by Entrance	1							13.0	
	LW-10	ROOM # 802C by Book Shelf	1							< 10.0	
	LW-11	ROOM # 803 Floor. AT CENTER.	1								
	LW-12	ROOM # 803 Table center by window.	1								
	LW-13	ROOM # 807 Floor AT CENTER	1								
	LW-14	ROOM # 807. TABLE AT CENTER OF ROOM.	1								
	LW-15	ROOM # 807A Floor AT CENTER	1								
	LW-16	ROOM # 807A - Book Shelf AT LEFT SIDE	1								
TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /				COMMENTS / INSTRUCTIONS							
RELINQUISHED BY (SIGNATURE) <i>Carlos Jofat</i>		DATE 8-6-02 TIME 1752		PRINTED NAME <i>C. Jofat</i>		RECEIVED BY (SIGNATURE) <i>[Signature]</i>		DATE 8/6/02 TIME 556 p		PRINTED NAME	
RELINQUISHED BY (SIGNATURE)		DATE TIME		PRINTED NAME		RECEIVED BY LAB (SIGNATURE)		DATE TIME		PRINTED NAME	

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

CITY_21MC100_010236739

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

030210730

516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS NYC SCA			CONTACT: HAMID SAUOJ		SAMPLER (SIGNATURE) <i>Carlos J. Jofat</i>		DATE 8-6-02		TIME		SAMPLE(S) SEALED ☒ YES ☐ NO	
PROJECT LOCATION: STUYVESANT H.S.			PROJECT # N477-15217/29851		SAMPLER NAME (PRINT) CARLOS O JOFAT				CORRECT CONTAINER(S) ☒ YES ☐ NO			
					MATRIX (CIRCLE ONE) ☒ WIPE ☐ PAINT ☐ SOIL ☐ OTHER _____							
SAMPLE INFORMATION:					AREA (FT ²)		SURFACE MATERIAL				LAB RESULT	
LABORATORY #	SAMPLE #	LOCATION				WOOD	METAL	BRICK	OTHER			
	LW-17	ROOM# 811 Floor by ENTRANCE			1				TILE	10.0		
	LW-18	ROOM# 811 TABLE AT CENTER OF ROOM			1	✓				10.0		
	LW-19	ROOM# 804 Floor AT CENTER.			1				TILE	10.0		
	LW-20	ROOM# 804 DESK AT CENTER			1	✓				13.0		
	LW-21	ROOM# 809 Floor AT CENTER.			1				TILE	10.0		
	LW-22	ROOM# 809. TABLE by ENTRANCE			1	✓				10.0		
	LW-23	ROOM# 823 Floor AT CENTER			1				✓	10.0		
	LW-24	ROOM# 823 ELECTRIC PANEL AT LEFT SIDE TOP			1		✓			10.0		
					TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /				COMMENTS / INSTRUCTIONS			
RELINQUISHED BY (SIGNATURE) <i>Carlos J. Jofat</i>		DATE 8-6-02	PRINTED NAME <i>Carlos Jofat</i>		RECEIVED BY (SIGNATURE) <i>[Signature]</i>		DATE 8/6/02	PRINTED NAME				
RELINQUISHED BY (SIGNATURE)		DATE	PRINTED NAME		RECEIVED BY LAB (SIGNATURE)		DATE	PRINTED NAME				
		TIME					TIME					

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

CITY_21MC100_010236740

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

030210730

516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS NYC SCA		CONTACT: HAMID SAVOJ		SAMPLER (SIGNATURE) <i>Carlos J. Lopez</i>		DATE 8-6-02		TIME		SAMPLE(S) SEALED ☒ YES / ☐ NO				
PROJECT LOCATION: Stuyvesant H.S.		PROJECT # H477-15217/29881		SAMPLER NAME (PRINT) CARLOS JOSE						CORRECT CONTAINER(S) ☒ YES / ☐ NO				
SAMPLE INFORMATION:				MATRIX (CIRCLE ONE): ☒ WIPE ☐ PAINT ☐ SOIL ☐ OTHER										
LABORATORY #			SAMPLE #			LOCATION			AREA (FT ²)		SURFACE MATERIAL WOOD METAL BRICK OTHER		LAB RESULT	
			LW-25			ROOM # 821 Floor AT CENTER			1 FT ²		☐ ☐ ☐ ☒		< 10.0	
			LW-26			ROOM # 821. AT STAND AT CENTER OF ROOM.			1 FT ²		☐ ☒ ☐ ☐		< 10.0	
			FB-01			FIELD BLANK			—		—		—	
			FB-02			↓			—		—		—	
			FB-03			↓			—		—		—	
			LW-27			8 FL CORRIDOR IN FRONT OF STAIRWELL E			1 FT ²		☐ ☐ ☐ ☐		< 10.0	
			LW-28			8 FL CORRIDOR by ROOM # 815			1 FT ²		☐ ☐ ☐ ☐		< 10.0	
				TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /				COMMENTS / INSTRUCTIONS						
RELINQUISHED BY (SIGNATURE) <i>Carlos J. Lopez</i>		DATE 8-6-02 TIME 1752		PRINTED NAME C. JOSE		RECEIVED BY (SIGNATURE) <i>[Signature]</i>		DATE 8/6/02 TIME 5:52 PM		PRINTED NAME				
RELINQUISHED BY (SIGNATURE)		DATE TIME		PRINTED NAME		RECEIVED BY LAB (SIGNATURE)		DATE TIME		PRINTED NAME				

ENCL. MANHATTAN
RECEIVED

02 AUG - 6 PM 5:56

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

CITY_21MC100_010236741

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

030210730

516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT											
CLIENT NAME/ADDRESS NYC SCA			CONTACT: HAMILTON SAVOY		SAMPLER (SIGNATURE) Carlos J. Fat		DATE 8-6-02		TIME		
					SAMPLER NAME (PRINT) CARLOS J. FAT				SAMPLE(S) SEALED YES / NO		
PROJECT LOCATION: Soyuzsant H.S. CHAMBERS ST, NY, NY			PROJECT # H477-15217 / 79881						CORRECT CONTAINER(S) YES / NO		
SAMPLE INFORMATION:					MATRIX (CIRCLE ONE): <u>WIPE</u> PAINT SOIL OTHER						
LABORATORY #			SAMPLE #		LOCATION		AREA (FT ²)		SURFACE MATERIAL		
									WOOD METAL BRICK OTHER		
			LW-29		Room C821 - Floor center		1		✓		
			LW-30		Room C823 - Floor center		1		✓		
			LW-31		Room C828 (Service Elev. lobby) Floor - center		1		✓		
			LW-32		Room C832 - 8th Floor Floor - center		1		✓		
			FB-4		Field Blank						
TURNAROUND REQUIRED:					COMMENTS / INSTRUCTIONS						
NORMAL ☐ STAT ☐ BY / /											
RELINQUISHED BY (SIGNATURE) Carlos J. Fat			DATE 8-6-02 TIME 1752		PRINTED NAME C. J. FAT		RECEIVED BY (SIGNATURE) S. J. Fat			DATE 8/6/02 TIME 550	
RELINQUISHED BY (SIGNATURE)			DATE		PRINTED NAME		RECEIVED BY LAB (SIGNATURE)			DATE	
			TIME							PRINTED NAME	

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

CITY_21MC100_010236742

EMSL Analytical, Inc.

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com



Attn: Taylor Environmental Group, Inc.
 Floral Park Corporate Center
 130 Jericho Tpke.
 Floral Park, NY 11001

Fax: (516) 358-1780

Phone: 516-358-2955

Project: M-477-15217/ 29881/ NYC SCA/ STUYVESANT H.S.

Customer ID: TAYL50

Customer PO:

Received: 08/06/02 5:56 PM

EMSL Order: 030210730

EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>	<i>Notes</i>
LW-01 ROOM #801 FLOOR BY WINDOW	0001		144 in ²	12.0 µg/ft ²	
LW-02 ROOM #801 DESK BY ENTRANCE	0002		144 in ²	<10.0 µg/ft ²	
LW-03 ROOM #802 FLOOR BY ENTRANCE	0003		144 in ²	<10.0 µg/ft ²	
LW-04 ROOM #802 TABLE BY ENTRANCE	0004		144 in ²	<10.0 µg/ft ²	
LW-05 ROOM #802A FLOOR AT CENTER	0005		144 in ²	<10.0 µg/ft ²	
LW-06 ROOM #802A TABLE BY WINDOWS	0006		144 in ²	<10.0 µg/ft ²	
LW-07 ROOM #802B FLOOR AT CENTER	0007		144 in ²	<10.0 µg/ft ²	
LW-08 ROOM #802B TABLE BY WINDOW	0008		144 in ²	11.0 µg/ft ²	
LW-09 ROOM #802C FLOOR BY ENTRANCE	0009		144 in ²	13.0 µg/ft ²	
LW-10 ROOM #802C BY BOOK SHELF	0010		144 in ²	<10.0 µg/ft ²	
LW-11 ROOM #803 FLOOR AT CENTER	0011		144 in ²	<10.0 µg/ft ²	
LW-12 ROOM #803 TABLE CENTER BY WINDOW	0012		144 in ²	<10.0 µg/ft ²	
LW-13 ROOM #807 FLOOR AT CENTER	0013		144 in ²	<10.0 µg/ft ²	
LW-14 ROOM #807 TABLE AT CENTER OF ROOM	0014		144 in ²	<10.0 µg/ft ²	
LW-15 ROOM #807A FLOOR AT CENTER	0015		144 in ²	<10.0 µg/ft ²	
LW-16 ROOM #807A BOOK SHELF AT LEFT SIDE	0016		144 in ²	<10.0 µg/ft ²	
LW-17 ROOM #811 FLOOR BY ENTRANCE	0017		144 in ²	<10.0 µg/ft ²	

Laboratory Manager
 or other approved signatory

Reporting limit is 10 µg/wipe

ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

EMSL Analytical, Inc.

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com


EMSL

Attn: Taylor Environmental Group, Inc.
 Floral Park Corporate Center
 130 Jericho Tpke.
 Floral Park, NY 11001
 Fax: (516) 358-1780 Phone: 516-358-2955
 Project: M-477-15217/ 29881/ NYC SCA/ STUYVESANT H.S.

Customer ID: TAYL50
 Customer PO:
 Received: 08/06/02 5:56 PM
 EMSL Order: 030210730
 EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description	Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
LW-18 ROOM #811 TABLE AT CENTER OF ROOM	0018		144 in ²	<10.0 µg/ft ²	
LW-19 ROOM #804 FLOOR AT CENTER	0019		144 in ²	<10.0 µg/ft ²	
LW-20 ROOM #804 DESK AT CENTER	0020		144 in ²	13.0 µg/ft ²	
LW-21 ROOM #809 FLOOR AT CENTER	0021		144 in ²	10.0 µg/ft ²	
LW-22 ROOM #809 TABLE BY ENTRANCE	0022		144 in ²	<10.0 µg/ft ²	
LW-23 ROOM #823 FLOOR AT CENTER	0023		144 in ²	<10.0 µg/ft ²	
LW-24 ROOM 3#823 ELECTRIC PANEL COMP. AT LEFT SIDE TOP	0024		144 in ²	<10.0 µg/ft ²	
LW-25 ROOM #821 FLOOR AT CENTER	0025		144 in ²	<10.0 µg/ft ²	
LW-26 ROOM #821 AT STAND AT CENTER OF ROOM	0026		144 in ²	<10.0 µg/ft ²	
FB-01 Field blank	0027		n/a	<10.0 µg/wipe	
FB-02 Field blank	0028		n/a	<10.0 µg/wipe	
FB-03 Field blank	0029		n/a	<10.0 µg/wipe	
LW-27 8 FL CORRIDOR IN FRONT OF STAIRWELL E	0030		144 in ²	<10.0 µg/ft ²	
LW-28 8 FL CORRIDOR BY ROOM #815	0031		144 in ²	<10.0 µg/ft ²	
LW-29 ROOM C821-FLOOR CENTER	0032		144 in ²	<10.0 µg/ft ²	
LW-30 ROOM C823-FLOOR CENTER	0033		144 in ²	<10.0 µg/ft ²	
LW-31 ROOM C828 (SERVICE ELEV. LOBBY) FLOOR-CENTER	0034		144 in ²	<10.0 µg/ft ²	
LW-32 ROOM C832 SLOP SINK	0035		144 in ²	<10.0 µg/ft ²	


 Laboratory Manager
 or other approved signatory

Reporting limit is 10 ug/wipe

ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

EMSL Analytical, Inc.

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com



Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001

Fax: (516) 358-1780 Phone: 516-358-2955

Project: M-477-15217/ 29881/ NYC SCA/ STUYVESANT H.S.

Customer ID: TAYL50

Customer PO:

Received: 08/06/02 5:56 PM

EMSL Order: 030210730

EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description	Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
FLOOR-CENTER					
FB-4 Field blank	0036		n/a	<10.0 µg/wipe	

Laboratory Manager
or other approved signatory

Reporting limit is 10 µg/wipe

ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581