





TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

2/251

10/13

516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS NYC SCA		CONTACT: HAMID SAWOJ		SAMPLER (SIGNATURE) 		DATE 8/17/02		TIME		SAMPLE(S) SEALED (YES) / NO	
PROJECT LOCATION: STUYVESANT HS.		PROJECT # M477-15217/29881		SAMPLER NAME (PRINT) Kirk McKenzie		CORRECT CONTAINER(S) (YES) / NO					
MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____											
SAMPLE INFORMATION:			AREA (FT ²)	SURFACE MATERIAL				LAB RESULT			
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER				
	LW-31	Room 373 - Floor North side by RADIATOR	1				X				< 9.0
	LW-32	Room 373 - Table Top North side	1				X				< 9.0
	LW-33	Room 372 - Floor Center of Room	1				X				< 9.0
	LW-34	Room 372 - Desk Top South Desk	1				X				< 9.0
	LW-35	Room 371 - Floor North side by R/nc BOARD	1				X				< 9.0
	LW-36	Room 371 - Table Top Northeast side	1				X				< 9.0
	LW-37	Room 371 A - Floor 3' of ENTRANCE	1				X				< 9.0
	LW-38	Room 371 A - Desk Top 1st Desk	1				X				< 9.0
FAX Results to 212-406-2536 or 516-358-1780				TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY 1 / 1				COMMENTS / INSTRUCTIONS 6 hrs TAT			
RELINQUISHED BY (SIGNATURE) 		DATE 8/17/02 TIME 05:20		PRINTED NAME Kirk McKenzie		RECEIVED BY (SIGNATURE) 		DATE 8/17/02 TIME 05:20		PRINTED NAME R. Drouotina	
RELINQUISHED BY (SIGNATURE)		DATE TIME		PRINTED NAME		RECEIVED BY LAB (SIGNATURE) 		DATE TIME		PRINTED NAME	

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

CITY_21MC100_010236853

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

21291

516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS NYC SCA			CONTACT: HAMID SAHOJ		SAMPLER (SIGNATURE) <i>[Signature]</i>		DATE 8/17/02	TIME	SAMPLE(S) SEALED (YES) / NO	
PROJECT LOCATION: STUYVESANT HS			PROJECT # M477-15217/29881		SAMPLER NAME (PRINT) MARV MC KENZIE		CORRECT CONTAINER(S) (YES) / NO			
MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____										
SAMPLE INFORMATION:					AREA (FT ²)		SURFACE MATERIAL		LAB RESULT	
LABORATORY #	SAMPLE #	LOCATION			WOOD	METAL	BRICK	OTHER		
	LW-39	ROOM 371 B - FLOOR corner 3' of ROOM ENT.			1				X	< 9.0
	LW-40	ROOM 371 B - TOP OF 1st desk			1				X	< 9.0
	LW-41	ROOM 371 C - FLOOR center of ROOM			1				X	13.8
	LW-42	ROOM 371 C - TOP of Red platform			1				X	18.7
	LW-43	ROOM 371 D - FLOOR by entrance			1				X	< 9.0
	LW-44	ROOM 371 D - TOP of Red platform			1			X		< 9.0
	LW-45	ROOM 371 E - FLOOR NW side			1				X	26.8
	LW-46	ROOM 371 E - TOP of Refrigerator - South			1				X	< 9.0
FAX RESULTS TO: 212 406-2536 516 358-1780					TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY 1 / 1			COMMENTS / INSTRUCTIONS 6 HR DAT		
RELINQUISHED BY (SIGNATURE) <i>[Signature]</i>		DATE 8/17/02	PRINTED NAME KIRK McKenzie		RECEIVED BY (SIGNATURE) <i>[Signature]</i>			DATE 8/17/02	PRINTED NAME	
RELINQUISHED BY (SIGNATURE)		DATE	PRINTED NAME		RECEIVED BY LAB (SIGNATURE) R. Drouillard			DATE 8.17.02	PRINTED NAME R. Drouillard	

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

CITY_21MC100_010236854

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICO TPKE., FLORAL PARK, NY 11001



21251

584

516-358-2955

Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS NYC SCA			CONTACT: HAMID SAWOJ		SAMPLER SIGNATURE) 		DATE 8/17/02		TIME		SAMPLE(S) SEALED ☒ YES ☐ NO									
PROJECT LOCATION: STUYVESANT HS			PROJECT # M477-15217/29881		SAMPLER NAME (PRINT) KIRK MC KENZIE				CORRECT CONTAINER(S) ☒ YES ☐ NO											
SAMPLE INFORMATION:					MATRIX (CIRCLE ONE): ☒ WIPE ☐ PAINT ☐ SOIL ☐ OTHER															
LABORATORY #			SAMPLE #			LOCATION			AREA (FT ²)		SURFACE MATERIAL				LAB RESULT					
											WOOD		METAL		BRICK		OTHER			
			LW-47			ROOM 371 F - FLOOR 3' of ENTRANCE			1								X		< 9.0	
			LW-48			ROOM 371 G - FLOOR 3' of ENTRANCE			1								X		< 9.0	
			LW-49			NE CORRIDOR o/s Gym Floor - by north entrance											X		< 9.0	
			LW-50			Room GYM (G380) - FLOOR Center of Gym					X								< 9.0	
			LW-51			Gym (G380) Center Top of Bleachers south end					X								13.2	
			LW-52			G380 B - FLOOR Center of room											X		11.4	
			LW-53			G380 B - Shelf Top Left side							X						< 9.0	
			LW-54			G380 C - FLOOR West side											X		15.5	
FAX RESULTS TO: 212 406-2536 516 358-1780					TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY 1/1					COMMENTS / INSTRUCTIONS 6 HR TAT										
RELINQUISHED BY (SIGNATURE) 			DATE 8/17/02 TIME 05:20		PRINTED NAME Kirk McKenzie			RECEIVED BY (SIGNATURE) 				DATE 8/17/02		PRINTED NAME						
RELINQUISHED BY (SIGNATURE)			DATE TIME		PRINTED NAME			RECEIVED BY LAB (SIGNATURE) R. Drondika				DATE 8/17/02 TIME 05:20		PRINTED NAME R. Drondika						

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT



CITY_21MC100_010236855

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

21251

484
516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS NYC SCA			CONTACT: HAMID SAWOJ		SAMPLER SIGNATURE 		DATE 8/17/02		TIME		SAMPLE(S) SEALED ☒ YES ☐ NO	
PROJECT LOCATION: STUYVESANT HS			PROJECT # M477-15217/29881		SAMPLER NAME (PRINT) KIRK MC KENZIE				CORRECT CONTAINER(S) ☒ YES ☐ NO			
MATRIX (CIRCLE ONE): ☒ WIPE ☐ PAINT ☐ SOIL ☐ OTHER												
SAMPLE INFORMATION:			AREA (FT ²)	SURFACE MATERIAL				LAB RESULT				
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER					
	LW-55	G 380 C - Shelf Center	1		X							< 9.0
	LW-56	G 382 (AUX GYM) - FLOOR By G 382 B	1						X			< 9.0
	LW-57	G 382 - Top B Tumbling PADS								X		23.4
	LW-58	G 382/A - FLOOR by entrance										26.0
	LW-59	G 382 B - FLOOR center of ROOM								X		27.9
	LW-60	G 382 B - Shelf Left side				X						30.8
	LW-61	ROOM 317 - FLOOR 3' of ENTRANCE	1						X			19.2
	LW-62	ROOM 317 - Shelf Right side				X						< 9.0
FAX RESULTS TO: 212 406-2536 516 358-1780					TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY 1/1				COMMENTS / INSTRUCTIONS 6 HR TAT			
RELINQUISHED BY (SIGNATURE) 		DATE 8/17/02 TIME 05:20		PRINTED NAME Kirk McKenzie		RECEIVED BY (SIGNATURE) 		DATE 8/17/02 TIME 10 AM		PRINTED NAME		
RELINQUISHED BY (SIGNATURE)		DATE TIME		PRINTED NAME		RECEIVED BY LAB (SIGNATURE) R. Droudina		DATE 8/17/02 TIME 05:20		PRINTED NAME R. Droudina		

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

21251

516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT										
CLIENT NAME/ADDRESS <div style="font-size: 1.2em; font-family: cursive;">NYC SCA</div>			CONTACT: <div style="font-size: 1.2em; font-family: cursive;">Hamid Davoj</div>		SAMPLER SIGNATURE <div style="font-size: 1.2em; font-family: cursive;">[Signature]</div>		DATE <div style="font-size: 1.2em; font-family: cursive;">8/17/02</div>		TIME	
PROJECT LOCATION: <div style="font-size: 1.2em; font-family: cursive;">Stuyvesant H.S. 345 Chambers St N.Y.</div>			PROJECT # <div style="font-size: 1.2em; font-family: cursive;">M477-15217-29881</div>		SAMPLER NAME (PRINT)		SAMPLE(S) SEALED <div style="font-size: 1.2em; font-family: cursive;">YES</div> / NO		CORRECT CONTAINER(S) <div style="font-size: 1.2em; font-family: cursive;">YES</div> / NO	
SAMPLE INFORMATION:					MATRIX (CIRCLE ONE): <div style="font-size: 1.2em; font-family: cursive;">WIPE</div> PAINT SOIL OTHER					
LABORATORY #	SAMPLE #	LOCATION	AREA (FT ²)	SURFACE MATERIAL				LAB RESULT		
				WOOD	METAL	BRICK	OTHER			
	LW-63	Corr. Door - EAST side by Recess Elevators - Floor	1				X	< 9.0		
	LW-64	Locker # 3-98 o/s Gym	1		X			< 9.0		
	FBL-1	Locker # Field Blank					< 9.0			
	FBL-2	Field Blank					< 9.0			
	FBL-3	Field Blank					< 9.0			
	FBL-4	Field Blank					< 9.0			
TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY <div style="font-size: 1.2em; font-family: cursive;">1 / 1</div>					COMMENTS / INSTRUCTIONS <div style="font-size: 1.2em; font-family: cursive;">8 HR TAT</div>					
RELINQUISHED BY (SIGNATURE) <div style="font-size: 1.2em; font-family: cursive;">[Signature]</div>		DATE <div style="font-size: 1.2em; font-family: cursive;">8/17/02</div>	PRINTED NAME <div style="font-size: 1.2em; font-family: cursive;">Kirk McKenzie</div>		RECEIVED BY (SIGNATURE) <div style="font-size: 1.2em; font-family: cursive;">[Signature]</div>		DATE <div style="font-size: 1.2em; font-family: cursive;">8/17/02</div>	PRINTED NAME		
RELINQUISHED BY (SIGNATURE)		DATE	PRINTED NAME		RECEIVED BY LAB (SIGNATURE) <div style="font-size: 1.2em; font-family: cursive;">[Signature]</div>		DATE	PRINTED NAME		
		TIME					TIME			

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

CITY_21MC100_010236857

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 08-19-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217-29881

SAMPLED BY: Client

SAMPLE DATE: 08-17-02
DATE RECEIVED: 08-17-02
DATE ANALYZED: 08-17-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION (µg/ft ²)	DETECTION LIMIT (µg/ft ²)
LW-31	21251	Rm 373 Floor North Side by Radiator	<9.0	9.0
LW-32	21251	Rm 373 Tabel Top North Side	<9.0	9.0
LW-33	21251	Rm 372 Floor Center of Room	<9.0	9.0
LW-34	21251	Rm 372 Desk Top South Desk	<9.0	9.0
LW-35	21251	Rm 371 Floor North Side by Blackboard	<9.0	9.0
LW-36	21251	Rm 371 Table Top North East Side	<9.0	9.0
LW-37	21251	Rm 371A Floor 3' of Entrance	<9.0	9.0
LW-38	21251	Rm 371A Desk Top 1st Desk	<9.0	9.0
LW-39	21251	Rm 371B Floor of Room Ent.	<9.0	9.0
LW-40	21251	Rm 371B Top of 1st Desk	<9.0	9.0
LW-41	21251	Rm 371C Floor Center of Room	13.8	9.0
LW-42	21251	Rm 371C Top of Bed	18.7	9.0
LW-43	21251	Bedroom 371D Floor by Entrance	<9.0	9.0

ATC ASSOCIATES, INC**104 E 25th Street, 10th Floor****New York, NY 10010****Tel. 212-353-8280****Fax 212-353-8306**

LW-44	21251	Rm 371D Top of Bedroom Platform	<9.0	9.0
LW-45	21251	Rm 371E Floor NW Side	26.8	9.0
LW-46	21251	Rm 371E Top of Refrigerator South	<9.0	9.0
LW-47	21251	Rm 371F Floor 3' of Entrance	<9.0	9.0
LW-48	21251	Rm 371G Floor 3' of Entrance	<9.0	9.0
LW-49	21251	NE Corridor O/S GYM Floor by North Entrance	<9.0	9.0
LW-50	21251	GYM (G380) Floor Center of GYM	<9.0	9.0
LW-51	21251	GYM (G380) Top of Bleachers South End	13.2	9.0
LW-52	21251	G380B Floor Center of Room	11.4	9.0
LW-53	21251	G380 Shelf Top Left Side	<9.0	9.0
LW-54	21251	G380C Floor West Side	15.5	9.0
LW-55	21251	G380C Shelf Center	<9.0	9.0
LW-56	21251	G382 (Aux. GYM) Floor by G382B	<9.0	9.0
LW-57	21251	G382 Top of Tumbling Pads	23.4	9.0
LW-58	21251	G382A Floor by Entrance	26.0	9.0
LW-59	21251	G382B Floor Center of Room	27.9	9.0
LW-60	21251	G382B Shelf Left Side	30.8	9.0
LW-61	21251	Rm 317 Floor 3' of Entrance	19.2	9.0
LW-62	21251	Rm 317 Shelf Right Side	<9.0	9.0
LW-63	21251	Corridor East Side by Elevator Floor	<9.0	9.0
LW-64	21251	Locker #3-98 O/S GYM	<9.0	9.0
FBL-1	21251	Field Blank	<9.0 µg	9.0 µg
FBL-2	21251	Field Blank	<9.0 µg	9.0 µg
FBL-3	21251	Field Blank	<9.0 µg	9.0 µg
FBL-4	21251	Field Blank	<9.0 µg	9.0 µg

NOTE 1:

THE REPORTING LIMIT (RL) IS 18.0 µg

NOTE 2:

HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft², Window sills 250 µg/ft², Window wells 400 µg/ft², Exterior surfaces 800 µg/ft².

NOTE 3:

Blank units are in µg

ATC ASSOCIATES, INC

104 E 25th Street, 10th Floor

New York, NY 10010

Tel. 212-353-8280

Fax 212-353-8306

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY:

ITEM

REPORT PREPARED BY:

[Signature]

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR:

[Signature]

LABORATORY DIRECTOR:

M.L.

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).