NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

**REPORT DATE:** 07-29-02

**CLIENT:** Taylor Environmental Group, Inc.

**PROJECT NAME:** SCA/Stuyvesant HS
345 Chambers Street, NY

**PROJECT NUMBER:** M477-15217/29881

**SAMPLED BY:** Client

**SAMPLE DATE:** 07-28-02
**DATE RECEIVED:** 07-29-02
**DATE ANALYZED:** 07-29-02

**SAMPLE MEDIA:** Dust Wipe Sample
**ANALYSIS REQUIRED:** Method EPA 3050/7420

ANALYSIS RESULTS

| SAMPLE ID | BATCH NO. | SAMPLE DESCRIPTION | LEAD CONCENTRATION ($\mu g/ft^2$) | DETECTION LIMIT ($\mu g/ft^2$) |
|---|---|---|---|---|
| LW-01 | 20724 | Rm 301A East Side Unitvent Rear | <9.0 | 9.0 |
| LW-02 | 20724 | Rm 301A South Side Unitvent Rear | <9.0 | 9.0 |
| LW-03 | 20724 | Rm 303 Souht Side Left Unitvent Rear | <9.0 | 9.0 |
| LW-04 | 20724 | Rm 303 South Side Right Unitvent Rear | <9.0 | 9.0 |
| LW-05 | 20724 | Rm 305 South Side Left Unitvent Rear | <9.0 | 9.0 |
| LW-06 | 20724 | Rm 305 South Side Right Unitvent Rear | <9.0 | 9.0 |
| LW-07 | 20724 | Rm 325 South Side Left Unitvent Rear | <9.0 | 9.0 |
| LW-08 | 20724 | Rm 325 South Side Right Unitvent Rear | <9.0 | 9.0 |
| LW-09 | 20724 | Rm 313 South Side Left Unitvent Rear | <9.0 | 9.0 |
| LW-10 | 20724 | Rm 313 South Side Right Unitvent Rear | <9.0 | 9.0 |
| FBL-1 | 20724 | Field Blank | <9.0 µg | 9.0 µg |
| FBL-2 | 20724 | Field Blank | <9.0 µg | 9.0 µg |

NOTE 1:
**THE REPORTING LIMIT (RL) IS 18.0 µg**
NOTE 2:
*HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.*
NOTE 3:
Blank units are in µg



NYC-WTC_000232470