





TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICO RD., FLORAL PARK, NY 11001

030212133

Ld = 2
-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS NYC SCA		CONTACT: HARRY SAVOY		SAMPLER (SIGNATURE) 		DATE 8/30/02		TIME 5:20 PM		SAMPLE(S) SEALED ☒ YES ☐ NO							
PROJECT LOCATION: STUYVESANT HS. CHAMBERS ST, NY, NY		PROJECT # M477-15217-29881		SAMPLER NAME (PRINT) HARRY SAVOY		CORRECT CONTAINER(S) ☒ YES ☐ NO											
SAMPLE INFORMATION:				MATRIX (CIRCLE ONE): WIPE ☐ PAINT ☒ SOIL ☐ OTHER ☐													
LABORATORY #			SAMPLE #			LOCATION			AREA (FT ²)		SURFACE MATERIAL				LAB RESULT		
											WOOD METAL BRICK OTHER						
			P-01			RM C039 EAST SIDE OF ENTRANCE OF CAGED STORAGE AREA			—								
			P-02			RM 040 10' NW OF ENTRANCE TO ROOM			—								
			P-03			RM C038 15' NORTH OF ENTRANCE TO ROOM			—								
			P-04			RM C035 CENTER OF ROOM			—								
			P-05			RM C031 SE 10' OF ENTRANCE TO ROOM			—								
			P-06			RM 029 15' SOUTH OF ENTRANCE TO ROOM			—								
			P-07			RM C022 CENTER OF ROOM			—								
			P-08			RM C023 12' EAST OF ENTRANCE TO ROOM			—								
FAX TO 1-212-406-2535 1-516-358-1780										TURNAROUND REQUIRED: NORMAL ☐ STAT ☒ BY 1/1				COMMENTS / INSTRUCTIONS 			
RELINQUISHED BY (SIGNATURE) 			DATE 8/30		PRINTED NAME ERIC LORA		RECEIVED BY (SIGNATURE) 			DATE 8/30		PRINTED NAME					
RELINQUISHED BY (SIGNATURE) 			DATE 8/30		PRINTED NAME ERIC LORA		RECEIVED BY LAB (SIGNATURE) 			DATE 8/30		PRINTED NAME					

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

CITY_21MC100_010245596

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO ROAD, FLORAL PARK, NY 11001

FM 02

030212133

358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS NYCSCA		CONTACT: HANID SAVOY		SAMPLER SIGNATURE: <i>[Signature]</i>		DATE 8/30/02		TIME 11:00 PM		SAMPLE(S) SEALED YES / NO	
PROJECT LOCATION: STUYVESANT HS CHAMBERS ST, NY, NY		PROJECT # M447-15218-29881		SAMPLER NAME (PRINT) ROGER PATRANON						CORRECT CONTAINER(S) YES / NO	
SAMPLE INFORMATION:				MATRIX (CIRCLE ONE):		WIPE		PAINT		SOIL OTHER	
LABORATORY #	SAMPLE #	LOCATION	AREA (FT ²)	SURFACE MATERIAL				LAB RESULT			
				WOOD	METAL	BRICK	OTHER				
	P-09	FM C030 SOUTH/EAST CORNER OF ROOM AT EAST ENTRANCE	—				X				
	P-10	BSMT CORRIDOR OUTSIDE FM 029	—				X				
	P-11	BSMT CORRIDOR OUTSIDE FM C031	—				X				
	P-12	BSMT CORRIDOR OUTSIDE FM C031	—				X				
	P-13	BSMT CORRIDOR OUTSIDE FM 033	—				X				
	P-14	BSMT CORRIDOR OUTSIDE FM C035	—				X				
	P-15	FM C036 CENTER OF ROOM	—				X				
	P-16	FM 6180 C AT ENTRANCE TO ROOM	—				X				
				TURNAROUND REQUIRED: NORMAL ☐ STAT ☒ BY 1/1				COMMENTS / INSTRUCTIONS 342 YAT			
RELINQUISHED BY (SIGNATURE) <i>[Signature]</i>		DATE 8/30/02	PRINTED NAME Reina	RECEIVED BY (SIGNATURE) <i>[Signature]</i>				DATE 8/30	PRINTED NAME		
		TIME 5:30						TIME 3:30 PM			
RELINQUISHED BY (SIGNATURE) <i>[Signature]</i>		DATE 8/30	PRINTED NAME G. McKen	RECEIVED BY LAB (SIGNATURE) <i>[Signature]</i>				DATE	PRINTED NAME		
		TIME 5:30						TIME			

02 AUG 30 PM 8:20

RECEIVED

CITY_21MC100_010245597

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT