

AMBIENT GROUP, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542

DUST CHARACTERIZATION LABORATORY DATA REPORT

PROJECT ID: 211361
CLIENT: S.L. GREEN
LOCATION: 17 BATTERY PLACE, NORTH TOWER
TECHNICIAN: WILLIAM ESPOSITO

DATE COLLECTED: 9/17/01
DATE RECEIVED: 9/17/01
DATE ANALYZED: 9/18/01

FIELD ID LABORATORY ID	DESCRIPTION	SAMPLE CONSTITUENTS	PERCENT OF SAMPLE **
211361-09 DB1880	AHW, DOWN STREAM FILTERS	CELLULOSE	10.0%
		FIBER GLASS	10.0%
		CEMENT DUST	40.0%
		CARBON PARTICLES	20.0%
		DECAYED ORGANIC MATTER	20.0%
		TOTAL	100.0%
211361-10 DB1881	11TH FLOOR SOUTH CHAMBER	CELLULOSE	20.0%
		FIBER GLASS	40.0%
		CEMENT DUST	30.0%
		CARBON PARTICLES	10.0%
		TOTAL	100.0%
211361-11 DB1882	FILTER	FIBER GLASS	5.0%
		CEMENT DUST	30.0%
		RUST	50.0%
		CARBON PARTICLES	10.0%
		POLLEN	5.0%
211361-12 DB1883	LOBBY ELEVATOR BANK	TOTAL	100.0%
		CELLULOSE	5.0%
		FIBER GLASS	30.0%
		CEMENT DUST	20.0%
		GRAVEL ROAD DUST	20.0%
		CARBON PARTICLES	10.0%
		DECAYED ORGANIC MATTER	10.0%
		POLLEN	5.0%
		TOTAL	100.0%

Signed for Ambient Group Inc. by,

Tarek Fata
TAREK FATA

ND = None Detected, NA = Not Analyzed, There are two (2) types of dust sample submitted for analysis: Settled = Samples submitted on tape/bulk, Air-borne = Samples submitted in Air-O-Cel Cassettes. All results discussed in this report relate only to the items tested. No reproduction of all or any portion of this report shall occur without written approval of Ambient Group Inc. Unless otherwise directed by the Client, Ambient Group Inc. will retain the samples listed in this report for five (5) days, after which time they may be disposed of in accordance with applicable regulations.

CITY_21MC100_009156586