NYC 9/11 Public Portal Document

Table
Asbestos Microvac (ASTM 5575)
Return Ducts
New York City Law Department
100 Church Street
New York

| * Sample ID :<br>Lab Sample ID :<br>Sample Date :<br>* Sample Type :<br>Floor:<br>Surface Type:<br><br><br>Location: | **Geometric Mean** | MV2005<br>#REF!<br>8/10/2002<br>Microvac<br>20<br>Return Duct<br><br>South corridor, 5' west of exit door B | MV2006<br>#REF!<br>8/10/2002<br>Microvac<br>20<br>Return Duct<br><br>South corridor, next to men's toilet | MV2007<br>#REF!<br>8/10/2002<br>Microvac<br>20<br>Return Duct<br><br>Northwest corner, Room 8-1405 | MV2008<br>#REF!<br>8/10/2002<br>Microvac<br>20<br>Return Duct<br><br>Northwest corridor, 5' east of men's toilet |
|---|---|---|---|---|---|
| **CONSTITUENTS** | | | | | |
| **ASBESTOS (structures/cm$^2$)** | 535 | <1,070 | <1,070 | <1,070 | <1,070 |

* Post Cleaning Target = <10,000 str/cm$^2$ (structures per square centimeter) individual sample and geometric mean of <1,000 str/cm$^2$

CITY_21MC100_012558009

TRC
Customer-Focused Solutions