Table
Asbestos Microvac (ASTM 5575)
Return Ducts
New York City Law Department
100 Church Street
New York

* Sample ID :		MV2005	MV2006	MV2007	MV2008
Lab Sample ID :		#REF!	#REF!	#REF!	#REF!
Sample Date :		8/10/2002	8/10/2002	8/10/2002	8/10/2002
* Sample Type :	**Geometric Mean**	Microvac	Microvac	Microvac	Microvac
Floor:		20	20	20	20
Surface Type:		Return Duct	Return Duct	Return Duct	Return Duct
Location:		South corridor, 5' west of exit door B	South corridor, next to men's toilet	Northwest corner, Room 8-1405	Northwest corridor, 5' east of men's toilet
CONSTITUENTS					
ASBESTOS (structures/cm^2)	535	<1,070	<1,070	<1,070	<1,070

* Post Cleaning Target = <10,000 str/cm^2 (structures per square centimeter) individual sample and geometric mean of <1,000 str/cm^2

CITY_21MC100_012558312

TRC
Customer-Focused Solutions