NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

VATC ASSOCIATES INC.

5639 7110 600566 - 600575

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

PROJECT INFORMATION

1. Client	2. Project Name	3. Project #	4. Project Monitor	4c. Rotameter Number
NYC-BOE	NEW STUYVESANT HS (M477)	19125-0216	4a. Air Sampler: HERANT ANTONYAN	SD-059
	2a. Project Address: 345 CHAMBERS STREET, NY, NY 10007			

5. Date	6. Abatement Location	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type	
10/8/01	Exterior of the Building & Roof	Cassette/Filter Manufacture: ____ Lot #: ____	Cassette/Filter Manufacture: Multi-A1 Inc Lot #: 00266916	a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/cc
08				Field Blank									
09				Field Blank									
01	389901			Outside the building North side by the entrance	05:28	09:00	212	9	9	9	1908		<223
02	389872			Outside the building North side 20' West of entrance	05:32	09:07	215	9	9	9	1935		<223
03	389962			Outside the building east side by the entrance	05:40	09:13	213	9	9	9	1917		<223
04	389875			11th level roof, west side	05:50	09:19	209	9	9	9	1881		<223
05	389901			Outside the building North side, north east corner	10:14	13:45	211	9	9	9	1899		<223
06	389872			Outside the building North side, north west corner	10:17	13:50	213	9	9	9	1917		<223

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I H Antonyan	JD	10/8/01	15.15
II			
III			

26. AIC Project Manager	27. Result To:	28. Comments:
ANDREAS ANDREOU	ANDREAS C. ANDREOU	
	Beeper/Phone #'s (646) 772-1153	

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:	10/8	16:45
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
(TEM - AHERA)

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/00)

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008 CONFIDENTIAL, CITY_21MC100_00346986

NYC-WTC_000244366

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

S639

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

PROJECT INFORMATION

1. Client	2. Project Name / 2a. Project Address	3. Project #	4. Project Monitor / 4a. Air Sampler	4c. Rotameter Number
NYC-BOE	NEW STUYVESANT HS (M477) / 345 CHAMBERS STREET, NY, NY 10007	19125-0246	HERANT ANTONYAN	SD - 059

5. Date	6. Abatement Location	7. PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type
10/8/01	Exterior of the building & roof	Cassette/Filter Manufacture: ____ Lot #: ____	Cassette/Filter Manufacture: ____ Lot #: ____	a. ☐ Background b. ☐ Pre Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/cc
				Field Blank									
				Field Blank									
07	389875			11th level roof, east side	10:25	14:01	216	9	9	9	1944		< 0.023
10				SEALED BLANK									

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I H ANTONYAN			
II		10/8/01	15:15
III			

26. ATC Project Manager	27. Result To:	28. Comments:
ANDREAS ANDREOU	ANDREAS C ANDREOU Beeper/Phone #'s (646) 772-1153	

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATEM	23. Date:	24. Time:
a. Analyzed By:	10/8	16:45
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology:
PCM - NIOSH 7400A
TEM - AHERA

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/00)

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008 CONFIDENTIAL, CITY_21MC100_00346986

NYC-WTC_000244367