ATC ASSOCIATES INC.

BATCH NO. 20429

BULK SAMPLE DATA AND CHAIN OF CUSTODY FORM

PROJECT INFORMATION

1. Client: NYC - BOE	2. Project Nam AHERA REINSPECTION	3. Project # 14584-0865	4. Project Manager: Yiannis Efstathiou
	2a. Project Address: 100 Trinity Place, New York, NY10006		4a. Investigator: Chacko Mathew
5. Date: 5/25/02	6. Building Name: M833	8. Turnaround Time: ☐ STAT ☐ ☐ 72 HRS ☐ OTHER	9. Comments (Field): Analyzed all of them for fiberglass
	7. Sampling Areas:	☐ 6 HRS ☐ 48 HOURS ☐ NORMAL RUSH	10. Time in / Time out:

H.A.#	SAMPLE ID NUMBER	MATERIAL DESCRIPTION	LOCATION	FLOOR NUMBER	RESULTS
01	M833-5/25/02- Fiberglass- 01	Settled Dust	Nineth Floor hallway by elevators	9	ND
02	M833-5/25/02- Fiberglass- 02	Settled Dust	Cafeteria by Entrance	8	ND
03	M833-5/25/02- Fiberglass- 03	Settled Dust	7th Floor hallway by Rm 707	7	ND
04	M833-5/25/02- Fiberglass- 04	Settled Dust	6th Floor Class room #606	6	ND
05	M833-5/25/02- Fiberglass- 05	Settled Dust	5th Floor hlwy by Rm 505	5	ND
06	M833-5/25/02- Fiberglass- 06	Settled Dust	4th Floor Class room #407	4	ND
07	M833-5/25/02- Fiberglass- 07	Settled Dust	3rd Floor hlwy by Rm 303	3	ND
08	M833-5/25/02- Fiberglass- 08	Settled Dust	Main Entrance lobby by Rm 105	1	ND
09	M833-5/25/02- Fiberglass- 09	Settled Dust	Auditorium middle of Right isle	1	ND
	M833-5/18/02- Fiberglass-	Settled Dust			

CHAIN OF CUSTODY

17. Relinquished By:	18. Date:	19. Time	20. Received By:	21. Date:	22. Time:
[signature]	5/25/02		T Elbert	05/25/02	12 noon

23. Method of Submittal:	
FIELD	
WALK IN	
US MAIL	
FED-X	
OTHER	

LAB INFORMATION

24. Name and Signature:	25. Date:	26. Time:
24a. Analyzed By: Yelena Regarchiev	5/25/2	PM
24b. Analyzed By:		
24c. QC By:		

27. Comments (Lab): 9 PLM 26

Filename: P:\USERS\DATA\WP96\WP\FORMS\NY-13.XLS

Form NY-13

CITY_COMMENT_0013391317

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT