NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 10/13/01
ADDRESS: 345 Chambers St., NY, NY 10282

T011013B

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
1	OUTSIDE NORTH ENTRANCE OF SCHOOL - EAST SIDE	00.01	7.53	3	3	1416	0	0	416.67	<0.0045
2	- WEST SIDE	00.03	7.55	3	3	1416	0	0	416.67	<0.0046

TECHNICIAN: A. MARTIROSSIAN

ROTAMETER: KAM101

CHAIN OF CUSTODY	PLEASE ANALYZE ASAP AND FAX RESULTS DDC SUPERVISOR (718) 391-1499 DDC OPERATIONS (212) 941-5356 BOB ADAMS (609) 584-1134	RECEIVED AT LAB BY: MG SAMPLE CONDITION UPON RECEIPT: DATE/TIME: 10/13

RECEIVED
KAM CONSULTANTS
2001 OCT 13 AM 8:51

ANALYST: A Martirossian

DATE RECEVED: 10/13/01

DATE OF ANALYSIS 10/13/01 1200

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

PAGE 01/01 KAM CONSULTANTS 7187293774 10/13/2001 11:57 CITY_21MC100_002778739

NYC-WTC_000266604