NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

BULK SAMPLE ANALYSIS REPORT

CLIENT: NYC-DCAS
BUILDING ADDRESS: 31 Chamber Street
PROJECT#:

Client Sample ID# :	1	2	3	4	5
Lab Sample ID# :	010918D-1008	010918D-1009	010918D-1010	010918D-1011	010918D-1012
Sample Location:	8th Floor East Wing	8th Floor South Wing	Entrance Roof Facing West	Room # 703 7th Floor	7th Floor Elevator Bank East
Homogeneity:	Yes	Yes	Yes	Yes	Yes
Sample Description:	Window Sill Wipe	Circle Window Sill Wipe	Roof Wipe	Shelves Wipe	Floor Wipe
Color:	Blk	Blk	Blk	Blk	Blk
Texture:	Mixed	Mixed	Mixed	Mixed	Mixed
Sample Treatment:	None	None	None	None	None
Asbestos Present: (Type & Percent)	ND	ND	ND	ND	ND
Total Percent Asbestos:	**0%**	**0%**	**0%**	**0%**	**0%**
Other Fibr. Mat. (Type & Percent):	2%CELL	3%CELL	2%CELL 5%SYNTH	5%CELL 5%SYNTH	10%CELL 3%SYNTH <1%FBGL
Non Fibr. Mat. (Percent):	98%	97%	93%	90%	86%
Date Received:	9/18/01				
Date of Analysis:	9/18/01				
Date of Report:	9/18/01				

Analyst: Roody Louis **Lab Manager:** David Chen

* Analysis of samples is performed by Polarized Light Microscopy (PLM) - Point Counting Method (EPA 600/M4-82-020)
* Analytical equipments: Stereobinocular microscope (MEIJI EMT-Serial # 25930), Polarized Light Microscope (MEIJI ML-POL-Serial # 88034)
* PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing
* Samples will be stored for ninety (90) days and then returned to the client upon request
* The results relate only to the items calibrated or tested.
* The certificate of report shall not be reproduced without the written approval of the laboratory.
* The report must not be used by the client to claim endorsement by NVLAP or any agency of the US Government.

NYS-DOH ELAP # 11273 *NIST-NVLAP # 102047* *AIHA #: 100269*

CITY_21MC100_006262352

NYC-WTC_000268167

NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

BULK SAMPLE ANALYSIS REPORT

CLIENT: NYC-DCAS
BUILDING ADDRESS: 31 Chamber Street
PROJECT#:

Client Sample ID# :	6	7	8	9	10
Lab Sample ID# :	010918D-1013	010918D-1014	010918D-1015	010918D-1016	010918D-1017
Sample Location:	7th Floor Room # 734	7th Floor Room # 734A North	5th Floor Ladies Bathroom Mezzanine West	5th Floor North West Accounting Dept. Room # 508	5th Floor Accounting Dept. West
Homogeneity:	Yes	Yes	Yes	Yes	Yes
Sample Description:	Window Sill Wipe	Window Sill Wipe	Window Sill Wipe	Dust of Desk Wipe	Window Sill Wipe
Color:	Blk	Blk	Blk	Blk	Blk
Texture:	Mixed	Mixed	Mixed	Mixed	Mixed
Sample Treatment:	None	None	None	None	None
Asbestos Present: (Type & Percent)	ND	ND	ND	ND	ND
Total Percent Asbestos:	**0%**	**0%**	**0%**	**0%**	**0%**
Other Fibr. Mat. (Type & Percent):	10%CELL	<1%CELL	5%CELL	10%SYNTH	5%SYNTH
Non Fibr. Mat. (Percent):	90%	>99%	95%	90%	95%
Date Received:	9/18/01				
Date of Analysis:	9/18/01				
Date of Report:	9/18/01				

Analyst: Roody Louis **Lab Manager:** David Chen

* Analysis of samples is performed by Polarized Light Microscopy (PLM) - Point Counting Method (EPA 600/M4-82-020)
* Analytical equipments: Stereobinocular microscope (MEIJI EMT-Serial # 25930), Polarized Light Microscope (MEIJI ML-POL-Serial # 88034)
* PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing
* Samples will be stored for ninety (90) days and then returned to the client upon request
* The results relate only to the items calibrated or tested.
* The certificate of report shall not be reproduced without the written approval of the laboratory.
* The report must not be used by the client to claim endorsement by NVLAP or any agency of the US Government.

NYS-DOH ELAP # 11273 *NIST-NVLAP # 102047* *AIHA #: 100269*

CITY_21MC100_006262353

NYC-WTC_000268168

NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

BULK SAMPLE ANALYSIS REPORT

CLIENT: NYC-DCAS
BUILDING ADDRESS: 31 Chamber Street
PROJECT#:

Client Sample ID# :	11	12	13	14	15
Lab Sample ID# :	010918D-1018	010918D-1019	010918D-1020	010918D-1021	010918D-1022
Sample Location:	5th Floor Corner Window S.W. Room # 504	5th Floor Middle Window Sill South Room # 504	5th Floor Elevator Bank "B" East	5th Floor Facing South North Wing	3rd Floor Middle Window Room # 301 Facing South
Homogeneity:	Yes	Yes	Yes	Yes	Yes
Sample Description:	Window Sill Wipe	Window Sill Wipe	Floor Wipe	Dust Off Desk Wipe	Window Sill Wipe
Color:	Blk	Blk	Blk	Blk	Blk
Texture:	Mixed	Mixed	Mixed	Mixed	Mixed
Sample Treatment:	None	None	None	None	None
Asbestos Present: (Type & Percent)	ND	ND	ND	ND	ND
Total Percent Asbestos:	**0%**	**0%**	**0%**	**0%**	**0%**
Other Fibr. Mat. (Type & Percent):	3%SYNTH	2%CELL	5%CELL 8%SYNTH	5%SYNTH	3%SYNTH 8%CELL
Non Fibr. Mat. (Percent):	97%	98%	87%	95%	89%
Date Received:	9/18/01				
Date of Analysis:	9/18/01				
Date of Report:	9/18/01				

Analyst: Roody Louis **Lab Manager:** David Chen

* Analysis of samples is performed by Polarized Light Microscopy (PLM) - Point Counting Method (EPA 600/M4-82-020)
* Analytical equipments: Stereobinocular microscope (MEIJI EMT-Serial # 25930), Polarized Light Microscope (MEIJI ML-POL-Serial # 88034)
* PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing
* Samples will be stored for ninety (90) days and then returned to the client upon request
* The results relate only to the items calibrated or tested.
* The certificate of report shall not be reproduced without the written approval of the laboratory.
* The report must not be used by the client to claim endorsement by NVLAP or any agency of the US Government.

NYS-DOH ELAP # 11273 *NIST-NVLAP # 102047* *AIHA #: 100269*

CITY_21MC100_006262354

NYC-WTC_000268169

NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

BULK SAMPLE ANALYSIS REPORT

CLIENT: NYC-DCAS
BUILDING ADDRESS: 31 Chamber Street
PROJECT#:

Client Sample ID# :	16	17	18	19
Lab Sample ID# :	010918D-1023	010918D-1024	010918D-1025	010918D-1026
Sample Location:	3rd Floor Dust Room # 301 South	3rd Floor Room # 301 East	Lobby South	Lobby South
Homogeneity:	Yes	Yes	Yes	Yes
Sample Description:	Dust Tip of Air Condition Units Wipe	Window Sill Wipe	Dust of Statue from Entrance by Chamber Street	Main Entrance from Chamber Floor Wipe
Color:	Blk	Blk	Blk	Blk
Texture:	Mixed	Mixed	Mixed	Mixed
Sample Treatment:	None	None	None	None
Asbestos Present: (Type & Percent)	ND	ND	ND	ND
Total Percent Asbestos:	**0%**	**0%**	**0%**	**0%**
Other Fibr. Mat. (Type & Percent):	8%CELL	10%CELL	5%CELL 5%SYNTH	3%CELL
Non Fibr. Mat. (Percent):	92%	90%	90%	97%
Date Received:	9/18/01			
Date of Analysis:	9/18/01			
Date of Report:	9/18/01			

Analyst: Roody Louis **Lab Manager:** David Chen

* Analysis of samples is performed by Polarized Light Microscopy (PLM) - Point Counting Method (EPA 600/M4-82-020)
* Analytical equipments: Stereobinocular microscope (MEIJI EMT-Serial # 25930), Polarized Light Microscope (MEIJI ML-POL-Serial # 88034)
* PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing
* Samples will be stored for ninety (90) days and then returned to the client upon request
* The results relate only to the items calibrated or tested.
* The certificate of report shall not be reproduced without the written approval of the laboratory.
* The report must not be used by the client to claim endorsement by NVLAP or any agency of the US Government.

NYS-DOH ELAP # 11273 *NIST-NVLAP # 102047* *AIHA #: 100269*

CITY_21MC100_006262355

NYC-WTC_000268170