NYC 9/11 Public Portal Document

The LiRo Group
LiRo-Kassner, Inc.
Engineers, Architects, and Construction Managers
15-09 132nd Street, 2nd Floor, College Point, N.Y. 11356 Telephone (718) 886-7998 Fax (718) 886-6047

March 14, 2002

Mr. John Pawlowski, Ph.D.
City of New York Department of Sanitation
44 Beaver Street
New York, New York 10004

RE: Dust Testing at 44 Beaver Street, 8th floor
LiRo Contract Number S136/350 PIN82702RR000004

Dear Mr. Pawlowski:

In response to a request from your office, LiRo-Kassner, Inc. conducted dust sampling and testing on the roof of the building located at 44 Beaver Street in Manhattan. The sampling was performed on Tuesday, March 4, 2002 by a New York State Department of Labor licensed air sampling technician using a battery operated pump and filtered cassettes compatible with analysis by Transmission Electron Microscopy. The sampling and the analysis for asbestos fibers were conducted in accordance with those procedures described in ASTM 5755.

The results of the analysis of the four samples indicate no asbestos in the tested areas including the roof drain, water drain channel, tank room roof, and elevator room roof. Enclosed are copies of the laboratory report and associated chain-of-custody form for these samples.

Please feel free to contact our office if you have any questions regarding this matter.

Sincerely,

LiRo-Kassner, Inc.

Christopher Zanoni
Project Manager

J:\dos\dustsamplesbeaverst

Manhattan
Telephone (212) 563-0280
Fax No. (212) 563-1841

Syosset
Telephone (516) 938-5476
Fax No. (516) 938-5491

Buffalo
Telephone (716) 759-0887
Fax No. (716) 759-0886

NYC-WTC_000282018