NYC 9/11 Public Portal Document

8015

P.O. _____

220 East 45th Street
New York, NY 10017
(212) 922-0077
Fax (212) 922-0630

WARREN & PANZER ENGINEERS, P.C.

AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

CLIENT: NYC DEP
PROJECT: 181 BROWY
LOCATION: ROOF CLEAN-UP

W&P FILE #: 1679 01 02
TURN AROUND: 24 HR
TECHNICIAN: R. TERWINDEL

Analysis Method: PCM - 7400
(circle one) TEM - AHERA
TEM - EPA LEVEL II

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE START	FLOWRATE STOP	TIME ON	TIME OFF	TOTAL TIME	VOLUME (liters)	CONCENTR. (fib./cc.)
01	SWA SOUTH WALL R SIDE	3		8.0	8.0	1505	1805	180	1440	
02	SWA SOUTH WALL (L) SIDE	3		8.0	8.0	1507	1807	"	"	
03	UPPER ROOF MECH RM (ANNEX)	3		8.0	8.0	1609	1809	"	"	
04	6th FLR STAIRWELL ENTRANCE	3		8.0	8.0	1616	1816	180	1440	
05	FB	1					NA			
06	FB	1					NA			

SAMPLED BY: R. TERWINDEL DATE: 06.08.02
SIGNATURE:
RELEASED BY: DATE:
SIGNATURE:
RECEIVED BY: M. Cobar DATE: 06.08.02
SIGNATURE:

SAMPLE TYPE CODES	
1 – Blank	5 – Final Clearance (Inside)
2 – Pre-Abatement	6 – Final Clearance (outside)
3 – During Abatement	7 – Personal
4 – During Glove Bag Removal	8 – Background

SEE REVERSE SIDE

CITY_21MC100_002942295

NYC-WTC_000282149