NYC 9/11 Public Portal Document

DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF AIR, NOISE & HAZARDOUS MATERIALS
ASBESTOS/LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368

JOEL A. MIELE, SR., P.E.
COMMISSIONER

ASBESTOS CONTROL PROGRAM
BULK ANALYSIS CHAIN OF CUSTODY

Incident No.: TRU0273MN03 Date Sampled: 03/27/03

Premise: 114 LIBERTY STREET Time: 12:50 am/pm

Boro: MANHATTAN

Inspector: R. RAMMOHAN (Print) [signature] (Sign)

TURNAROUND TIME: 24HRS [✓] 48HRS [ ] 1 WK [ ] 2 WKS [ ] 4 WKS [ ]

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 030327/A078 001	FIBROUS MATERIAL	PIZZARIA, ON FLOOR	373
2. 030327/A078 002	FIBROUS MATERIAL	PIZZARIA, ON FLOOR	374
3. 030327/A078 003	FIBROUS MATERIAL	PIZZARIA, ON FLOOR	375
4. 030327/A078 004	FIBROUS MATERIAL	PIZZARIA, ON TABLE	376
5. 030327/A078 005	CEMENTITIOUS PLASTER	PIZZARIA, ON DROP CEILING	377
6.			
7.			
8.			
9.			
10.			

ANALYSES REQUESTED: Asbestos PLM [✓] Asbestos TEM [ ] Lead [ ]

DATE	TIME	ACCEPTED BY	COMMENTS
3/27/03	2:45pm	PRINT Glenda Bruton SIGN [signature]	Safe custody lab
		P S	
		P S	
		P S	
		P S	

DEP ACP REV 5/96