NYC 9/11 Public Portal Document

156

DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF ENVIRONMENTAL COMPLIANCE
AIR MONITORING AUDIT SHEET
for
ROOF/FACADE CLEAN-UP

NAME of AUDITOR: A. SOLOKI **DATE:** 7-30-02

1. Location /Address(as listed on ACP 7): 10 Maiden Lane

2. Air Monitor Onsite: Yes ✓ **No** ___ **3. Name of Monitor :** Festy OSEMWEGIE

4. Certificate No. AH-01-01030 **5. Time of Audit:** 12~~00~~ 1230 am/(pm)

6. Chain of Custody Sheet Completed: Yes ✓ **No** ___
If No, Action Taken(describe): _____

7. Address on Chain of Custody correct(as listed on ACP 7): Yes ✓ **No** ___
If No, Action Taken(describe): _____

8. Analytical Method Circled(TEM-AHERA) : Yes 5 **No** ___
If No, ActionTaken(describe): _____

9. Number of samples listed on Chain of Custody(do not include blank) : 5 F.R. 3 at 11 ~~00~~ AM

10. Activity at Work Area (Check): a. No Activity ( ) b. Setting up Equipment ( ) c. Calibrating Pump ( )
d. Sampling in Process (✓) e. Breaking down Equipment ( ) F. Sampling Completed ( ) g. Doing Paper work( )
h. Other (Describe): _____

11. No of Pumps Running: 5
Problems Observed (describe): _____

Zone Coordinators:
Zone #1: Al Plumptre Zone #2: Denise Anzoulatos Zone #3: Carlstein Lutchmedial

NYC-WTC_000284580