NYC-WTC_000293441

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

ATC ASSOCIATES INC.

5649 12/15 60678-60692

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

PROJECT INFORMATION

1. Client:	2. Project Name / 2a. Project Address	3. Project #	4. Project Monitor: / 4a. Air Sampler:	4c. Rotameter Number:
NYC-BOE	NEW STUYVESANT HS (M477) / 345 CHAMBERS STREET, NY, NY 10007	19125-0216	HERANT ANTONYAN	SD-039

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:
10/9/01	Exterior & Inter. of the building & roof	Cassette/Filter Manufacture: ____ Lot #: ____	Cassette/Filter Manufacture: Multi-M Inc. Lot #: 00266916	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15 Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17 Fiber Conc. ~~f/cc~~ F/MM2
08				Field Blank									
09				Field Blank									
01	389901			Outside the building north side by the entrance	05:36	09:06	210	9	9	9	1890		<22.3
02	389872			Outside the building north side 20' west of entrance	05:38	09:09	211	9	9	9	1899		<22.3
03	389962			Outside the building east side by the entrance	05:43	09:15	212	9	9	9	1908		<22.3
04	389875			11th level roof, west side	05:54	09:24	210	9	9	9	1890		<22.3
05	389872			Outside the building north side, north east corner	10:04	13:34	210	9	9	9	1890		<22.3
06	389901			Outside the building north side, north west corner	10:07	13:38	211	9	9	9	1899		<22.3

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I H Antonyan			
II	RRuy	10.09	19:30
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: RRuy	10.09	21:20
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: ANDREAS ANDREOU

27. Result To: ANDREAS C. ANDREOU
Beeper/Phone #'s (646)772-1153

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/00)

CITY_21MC100_003082079

NYC-WTC_000293442

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.

5649

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other 5 DAYS

PROJECT INFORMATION

1. Client:	2. Project Name / 2a. Project Address	3. Project #	4. Project Monitor: / 4a. Air Sampler:	4c. Rotameter Number:
NYC-BOE	NEW STUYVESANT HS (M477) / 345 CHAMBERS STREET, NY, NY 10007	19125-0216	HERANT ANTONYAN	SD-059

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:
10/9/01	Exterior & Inter. of the building & roof	Cassette/Filter Manufacture: ____ Lot #: ____	Cassette/Filter Manufacture: Multi Mix Lot #: 00266916	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc ~~f/cc~~ f/mm2
10				Field Blank SEALED									
				Field Blank BLANK									
07	389875			11 level roof east side	10:16	13:49	213	9	9	9	1917		<22.3
11	389874			8th floor middle of hallway	15:02	18:32	210	9	9	9	1890		<22.3
12	389875			7th floor, middle of hallway	15:06	18:37	211	9	9	9	1899		<22.3
13	389962			5th floor, middle of hallway	15:09	18:42	213	9	9	9	1917		<22.3
14	389701			3rd floor, middle of hallway	15:12	18:47	215	9	9	9	1935		<22.3
15	389901			1st floor, middle of hallway	15:15	18:49	214	9	9	9	1926		<22.3

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I H. Antonyan	RRey	10/9	19:30
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: RRey	10.09	21:20
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: ANDREAS ANDREOU

27. Result To: ANDREAS C. ANDREOU
Beeper/Phone #'s (646) 772-1153

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY 1 (1/00)

CITY_21MC100_003082080