NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

ATC ASSOCIATES INC

7526 1821 86624-86644

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

PROJECT INFORMATION

1 Client	2 Project Name	3 Project #	4 Project Monitor	4c Rotameter Number
NYC - BOE	HS FOR LEADERSHIP & PUBLIC SERVICE (M894)	14584-0864	4a Air Sampler ALEX KHOLODENKO	HP 53
	2a Project Address 90 TRINITY PLACE, NY NY 10006			

5 Date	6 Abatement Location	7 ☐ PCM (0 8 micron MCE)	8 ☒ TEM (0 45 micron MCE)	9 Type
4/24/12	AS PER PROTOCOL	Cassette/Filter Manufacture ~~Lot #~~	Cassette/Filter Manufacture MMI Lot # 02100916	a ☐ Background b ☐ Pre Abate c ☐ Abatement d ☐ Post Abate e ☐ OSHA f ☐ Environmental g ☒ Ambient h ☐ Other

DAILY AIR SAMPLE RECORD

10 Sample I D Number	11 Pump Number	12 Sample Location 12a IWA	12b OWA	12c Sample Coordinates	13 Time (24 hrs clock) 13a Start	13b End	13c Total	14 Flow Rate (L/min) 14a Start	14b End	14c Avg	15 Total Air Vol (liters)	16 # Fibers/ Fields Minus Blank	17 Fiber Conc F/CC
C1, C2				Field Blank open & sealed									
C3				Field Blank sealed									
-C4				Outside of the school within 10' from entrance	0750	11:38	228	8.0	8.0	8.0	1824		
-C5				North/west side of vestibule - 1st Floor	0754	11:42	228	8.0	8.0	8.0	1824		
-C6				On roof, adj. to HVAC intake.	0757	11:44	227	8.0	8.0	8.0	1816		
-C1				14th Floor - Students cafeteria - South/west	0800	11:50	230	8.0	8.0	8.0	1840		
-C8				2nd Floor - auditorium West Side	0804	11:52	228	8.0	8.0	8.0	1824		
-C9				Basement - 10' from entrance from Gym	0809	11:55	226	8.0	8.0	8.0	1808		

CHAIN OF CUSTODY

	18 Relinquished By	19 Received By	20 Date	21 Time
I	[illegible]	[illegible]	4/24/12	21 [illegible]
II				
III				

LAB INFORMATION (ATC ELAP # 10879 ATC NVLAP # 1187)

22 Lab Name ATC-DEM	23 Date	24 Time
a Analyzed By RKy	4 26 12	4 00
b QC By		
c Lab Batch # 7526		

25 Microscope Make/Serial #
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

26 ATC Project Manager	27 Results To	28 Comments
MARK TERJESEN	YANNIS EFSTATHIOU EXT# 211 ~~Beeper/Phone # s~~ 646 772 1155	

Analysis Methodology
PCM – NIOSH 7400A
TEM – AHERA

CITY_21MC100_003086241

NYC 9/11 Public Portal Document

ATC ASSOC TEB INC

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

PROJECT INFORMATION

1 Client	2 Project Name	3 Project #	4 Project Monitor	4c Rotameter Number
NYC - BOE	HS FOR LEADERSHIP & PUBLIC SERVICE (M894)	14584-0864		HP 53
	2a Project Address 90 TRINITY PLACE, NY NY 10006		4a Air Sampler ALEX KHOLODENKO	

5 Date	6 Abatement Location	7 ☐ PCM (0 8 micron MCE)	8 ☒ TEM (0 45 micron MCE)	9 Type
4/4/11	AS PER PROTOCOL	Cassette/Filter Manufacture ~~Lot #~~	Cassette/Filter Manufacture MMI Lot # 02100516	a ☐ Background b ☐ Pre Abate c ☐ Abatement d ☐ Post Abate e ☐ OSHA f ☐ Environmental g ☒ Ambient h ☐ Other

DAILY AIR SAMPLE RECORD

10 Sample ID Number	11 Pump Number	12 Sample Location 12a IWA	12b OWA	12c Sample Coordinates	13 Time (24 hrs clock) 13a Start	13b End	13c Total	14 Flow Rate (L/min) 14a Start	14b End	14c Avg	15 Total Air Vol (liters)	16 # Fibers/ Fields Minus Blank	17 Fiber Conc F/CC
				Field Blank									
				Field Blank									
-10				Outside of Building Adj to main entrance	1138	15 28	228	8 0	8 0	8 0	1824		
-11				North/west Side of the vestibule 1st floor	1142	15.28	226	8 0	8 0	8 0	1808		
-12				On main Roof, Adj to HVAC intake	1145	15.33	228	8.0	8 0	8 0	1824		
-13				13th Floor - Hallway by library	1537	19.25	228	8 0	8 0	8.0	18		
-14				10th Floor - Room 1015 Center	15.41	19.30	229	8 0	8 0	8 0	1832		
-15				9th Floor - Hallway by elevators Bank	15.45	19.33	228	8 0	8.0	8.0	1824		

CHAIN OF CUSTODY

18 Relinquished By	19 Received By	20 Date	21 Time
I		2/24/2	21 3c
II			
III			

LAB INFORMATION (ATC ELAP # 10879 ATC NVLAP # 1187)

22 Lab Name ATC - JF/M	23 Date	24 Time
a Analyzed By	4 25 04	4 00
b QC By		
c Lab Batch # 75?c		

25 Microscope Make/Serial #
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

26 ATC Project Manager	27 Results To	28 Comments
MARK TERJESEN	YANNIS EFSTATHIOU EXT# 211 Beeper/Phone # s 646 772 1155	

Analysis Methodology
PCM – NIOSH 7400A
TEM – AHERA

CITY_21MC100_003086242

NYC-WTC_000296492

ATC ASSOC TES NC

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 3 of 3

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

PROJECT INFORMATION

1 Client	2 Project Name	3 Project #	4 Project Monitor	4c Rotameter Number
NYC-BOE	H S FOR LEADERSHIP & PUBLIC SERVICE (M894)	14584-0864	4a Air Sampler ALEX KHOLODENKO	HP 53
	2a Project Address 90 TRINITY PLACE, NY NY 10006			

5 Date	6 Abatement Location	7 ☐ PCM (0.8 micron MCE)	8 ☒ TEM (0.45 micron MCE)	9 Type
4/24/02	AS PER PROTOCOL	~~Cassette/Filter Manufacture~~ ~~Lot #~~	Cassette/Filter Manufacture MMI Lot # 02100916	a ☐ Background b ☐ Pre Abate c ☐ Abatement d ☐ Post Abate e ☐ OSHA f ☐ Environmental g ☒ Ambient h ☐ Other

DAILY AIR SAMPLE RECORD

10 Sample I D Number	11 Pump Number	12 Sample Location 12a IWA	12b OWA	12c Sample Coordinates	13 Time (24 hrs clock) 13a Start	13b End	13c Total	14 Flow Rate (L/min) 14a Start	14b End	14c Avg	15 Total Air Vol (liters)	16 # Fibers/ Fields Minus Blank	17 Fiber Conc F/CC
				Field Blank									
				Field Blank									
-16				8th Floor - Room # 805 Center	15.49	19:36	227	8.0	8.0	8.0	1816		
-17				7th Floor - Hallway By elevators	1553	19.40	227	8.0	8.0	8.0	1816		
-18				6th Floor - Room 609 Center	1557	19:45	228	8.0	8.0	8.0	1824		
-19				5th Floor - hallway Adj to elevators	16.01	19.50	229	8.0	8.0	8.0	1832		
-20				4th Floor - Room 403 Center	16.04	19:53	229	8.0	8.0	8.0	1832		
21				3rd Floor - Hallway By elevators	16.08	19:55	227	8.0	8.0	8.0	1816		

CHAIN OF CUSTODY

18 Relinquished By	19 Received By	20 Date	21 Time
I [signature]	[signature]	4/24/02	9:30
II			
III			

LAB INFORMATION (ATC ELAP # 10879 ATC NVLAP # 1187)

22 Lab Name ATC-TEM	23 Date	24 Time
a Analyzed By [signature]	4/25/02	4:00
b QC By		
c Lab Batch # 7520		

25 Microscope Make/Serial #
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

26 ATC Project Manager: MARK TERJESEN

27 Results To: YANNIS EFSTATHIOU EXT# 211
~~Beeper/Phone~~ # s 646 772 1155

28 Comments

Analysis Methodology
PCM – NIOSH 7400A

CITY_21MC100_003086243