NYC 9/11 Public Portal Document

VATC ASSOCIATES INC

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME: ☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard ☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

PROJECT INFORMATION

1. Client:	2. Project Name:	3. Project #:	4. Project Monitor:	4c. Rotameter Number:
NYC BOE	H.S. FOR LEADERSHIP & PUBLIC SERVICE (MS 934)	14584-0664	4a. Air Sampler: A. LEHOLCOMB/VOS	HP-53
	2a. Project Address: 90 TRINITY PLACE, NY NY			

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture / Lot #	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture / Lot #	9. Type
3/28/02	AS PER PROTOCOL		MNT 98-117-617	a ☐ Background b ☐ Pre-Abate c ☐ Abatement d ☐ Post-Abate e ☐ OSHA f ☐ Environmental g ☒ Ambient h ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min): 14a. Start	14b. End	14c. Avg	15. Total Air Vol (liters)	16. # Fibers/ Fields Minus Blank	17. Fiber Conc. F/CC
-01, -02				Field Blank open 30 sec/closed									
-03				Field Blank sealed									
-04				Outside of Building by main entrance	07:47	11:35	228	8.0	8.0	8.0	1824		
-05				Inside of vestibule South side	07:49	11:37	228	8.0	8.0	8.0	1824		
-06				On Roof, adj. to HVAC intake.	07:54	11:41	227	8.0	8.0	8.0	1816		
-07				14th Floor Student cafeteria	07:57	11:45	228	8.0	8.0	8.0	1824		
-08				13th Floor - Hall by elevators bank	08:01	11:48	227	8.0	8.0	8.0	1816		
-09				10th Floor - Room 1006 South/West.	08:04	11:51	227	8.0	8.0	8.0	1816		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By	20. Date	21. Time
I.		3/28/02	17:10
II.			
III.			

LAB INFORMATION (ATC ELAP # 10079, ATC NVLAP # 1187)

22. Lab Name: ATC TEST	23. Date	24. Time
a. Analyzed By:	3/28	21:10
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #
☐ Nikon Labophot 2 #89113
☐ Nikon Labophot 2 #89117
☐ Nikon Labophot 2 #89079

Analysis Methodology
PCM: NIOSH 7400A
TEM: AHERA

26. ATC Project Manager:	27. Results To:	28. Comments:
YANNIS EFSTATHIOU	YANNIS EFSTATHIOU EXT 210 Beeper/Phone #'s call 646-772-1155	

CITY_21MC100_003087569

NYC-WTC_000297435

NYC 9/11 Public Portal Document

VATC ASSOCIATES INC

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

PROJECT INFORMATION

1. Client:	2. Project Name:	3. Project #:	4. Project Monitor	4c. Rotameter Number
NYC BCE	H.S. LEADERSHIP & PUBLIC SERVICE (14594)	14594.C664	4a. Air Sampler: A. LHC LC. DENAC	HD-2
2a. Project Address: 90 TRINITY PLACE, NY NY				

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture / Lot #	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture: MMT / Lot #	9. Type
3/28/02	AS PER PROTOCOL			a ☐ Background; b ☐ Pre-Abate; c ☐ Abatement; d ☐ Post Abate; e ☐ OSHA; f ☐ Environmental; g ☒ Ambient; h ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min): 14a. Start	14b. End	14c. Avg	15. Total Air Vol (liters)	16. # Fibers/ Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
-10				9th Floor - Hallway By Room 915	0807	11:55	228	8.0	8.0	8.0	1824		
-11				8th Floor - Room 805 West Side	0810	11:57	227	8.0	8.0	8.0	1816		
-12				7th Floor - Hallway adj to PRINCIPAL office	0814	12:01	227	8.0	8.0	8.0	1816		
-13				6th Floor - Room 609 North Side	0816	12:03	227	8.0	8.0	8.0	1816		
-14				5th Floor - Hall adj to janitors closet	0819	12:07	228	8.0	8.0	8.0	1824		
-15				4th Floor - Room 403 Center	0822	12:10	228	8.0	8.0	8.0	1824		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By	20. Date	21. Time
I. [illegible]	[illegible]	3/28/02	17:10
II.			
III.			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC TECH	23. Date	24. Time
a. Analyzed By: [illegible]	3/28	21:15
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #
☐ Nikon Labophot 2 189113
☐ Nikon Labophot 2 189017
☐ Nikon Labophot 2 189079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager:	27. Results To: YANNIS EFSTATHIOU EXT 236 Beeper/Phone #'s call 646.772.1155	28. Comments:
YANNIS EFSTATHIOU		

CITY_21MC100_003087570

NYC-WTC_000297436

NYC 9/11 Public Portal Document

Page 3 of 3

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

PROJECT INFORMATION

1. Client:	2. Project Name: H.S. APPLIED DESIGN & PUBLIC SCHOOL (#1594)	3. Project #:	4. Project Monitor:	4c. Datameter Number
NYC BOE	2a. Project Address: 90 TRINITY PLACE, NY NY	14584-0664	4a. Air Sampler ALEXANDRIA	HP [illegible]

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacturer / Lot #	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacturer MMT / Lot #	9. Type a ☐ Background b ☐ Pre Abate c ☐ Abatement d ☐ Post-Abate e ☐ OSHA f ☐ Environmental g ☒ Ambient h ☐ Other
3/28/02	AS PER PROTOCOL			

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a IN/A	12b OUT/A	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14c. Avg	15. Total Air Vol (liters)	16. # Fibers/ Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
-16				3rd Floor - corridor adj to elevators	1145	15:32	227	8.0	8.0	8.0	1816		
-17				2nd Floor - auditorium west side	1148	15:35	227	8.0	8.0	8.0	1816		
-18				Basement - gym, adj to entrance to boy's locker	1150	15:39	229	8.0	8.0	8.0	1832		
-19				Outside of Building By main entrance	1135	15:42	227	8.0	8.0	8.0	1816		
-20				1st Floor hallway By South wall	1137	15:44	227	8.0	8.0	8.0	1816		
-21				On roof - Adj to HVAC intake	1141	15:47	226	8.0	8.0	8.0	1808		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By	20. Date	21. Time
I. [signature]	[signature]	3/28/02	17:40
II.			
III.			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: [illegible]	23. Date	24. Time
a. Analyzed By: [signature]	3/28	21:05
b. OC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #
☐ Nikon Labophot 2 #89114
☐ Nikon Labophot 2 #89017
☐ Nikon Labophot 2 #89079

Analysis Method/Iology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager:	27. Results To: YANNIS EFSTATHIOU EXT 211 Beeper/Phone #'s call 646.772.1155	28. Comments:
YANNIS EFSTATHIOU		

CITY_21MC100_003087571

NYC-WTC_000297437