NYC-WTC_000298024

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION 6749 18/21 (M894) 74899-74919

1 Client	2 Project Name / 2a Project Address	3 Project #	4 Project Monitor / 4a Air Sampler	4c Rotameter Number
NYC-BOE	H.S. for Leadership & Public Services / 90 Trinity Place, NY, NY	14584-0864	— / A. KHOLDAFAK	1 1 5 3

5 Date	6 Abatement Location	7 PCM (0.8 micron MCE)	8 TEM (0.45 micron MCE)	9 Type
2/19/02	AS PER PROTOCOL	Cassette/Filter Manufacture: ~~—~~ Lot #: ~~—~~	Cassette/Filter Manufacture: MMI Lot #: 26396	a ☐ Background b ☐ Pre-Abate c ☐ Abatement d ☐ Post-Abate e ☐ OSHA f ☐ Environmental g ☒ Ambient h ☐ Other

DAILY AIR SAMPLE RECORD

10 Sample I.D. Number	11 Pump Number	12 Sample Location: 12a IWA	12b OWA	12c Sample Coordinates	13 Time (24 hrs clock): 13a Start	13b End	13c Total	14 Flow Rate (L/min): 14a Start	14b End	14b Avg	15 Total Air Vol (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc. f/cc
-01;02				Field Blank open 30 sec									
-03				Field Blank Sealed									
-04				Out of Building By main entrance	07:47	11:35	228	8.0	8.0	8.0	1824		
-05				IN Vestibule - 1ST Floor North/west side	07:50	11:38	228	8.0	8.0	8.0	1824		
-06				On Roof, adj to HVAC INTAKE.	07:54	11:41	227	8.0	8.0	8.0	1816		
-07				14th Floor - Students cafeteria - South	07:56	11:44	228	8.0	8.0	8.0	1824		
-08				13th Floor Hallway	07:59	11:47	228	8.0	8.0	8.0	1824		
-09				10th Floor - Room # 1005	08:03	11:50	227	8.0	8.0	8.0	1816		

CHAIN OF CUSTODY

18 Relinquished By	19 Received By	20 Date	21 Time
I		2/19/02	~~1752~~ 1752
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22 Lab Name	23 Date	24 Time
a Analyzed By		
b QC By		
c Lab Batch #		

25 Microscope Make/Serial #
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26 ATC Project Manager: A. ANDREOU

27 Result To: Andreas C. Andreou
Beeper/Phone #'s: (646) 772-1155

28 Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

CITY_21MC100_003088546

NYC-WTC_000298025

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1 Client	2 Project Name	3 Project #	4 Project Monitor	4c Rotameter Number
NYC-BOE	HS for Leadership & Public Services (M894)		—	11753
	2a Project Address 90 Trinity Place, NY, NY 14584-0864		4a Air Sampler J. KHOLOPENKO	

5 Date	6 Abatement Location	7 ☐ PCM (0.8 micron MCE)	8 ☒ TEM (0.45 micron MCE)	9 Type
2/19/02	AS PER PROTOKOL	Cassette/Filter Manufacture ~~—~~ Lot # —	Cassette/Filter Manufacture MMI Lot # 263916	a ☐ Background b ☐ Pre-Abate c ☐ Abatement d ☐ Post Abate e ☐ OSHA f ☐ Environmental g ☒ Ambient h ☐ Other

DAILY AIR SAMPLE RECORD

10 Sample I.D. Number	11 Pump Number	12 Sample Location: 12a IWA	12b OWA	12c Sample Coordinates	13 Time (24 hrs clock): 13a Start	13b End	13c Total	14 Flow Rate (L/min): 14a Start	14b End	14b Avg	15 Total Air Vol (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc. F/CC
				Field Blank									
				Field Blank									
-10				9th Floor, Hall by elevators	08:07	11:55	228	8.0	8.0	8.0	1824		
-11				8th Floor - Rm # 815	08:11	11:58	227	8.0	8.0	8.0	1816		
-12				7th Floor - Hall By Rm # 706	08:15	12:02	227	8.0	8.0	8.0	1816		
-13				6th Floor - Rm # 602	08:17	12:05	228	8.0	8.0	8.0	1824		
-14				5th Fl - Hall By elevators	08:21	12:09	228	8.0	8.0	8.0	1824		
-15				4th Floor - Rm # 403	08:26	12:13	227	8.0	8.0	8.0	1816		

CHAIN OF CUSTODY

18 Relinquished By	19 Received By	20 Date	21 Time
I		2/19/02	1752
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22 Lab Name	23 Date	24 Time
a Analyzed By	2/20	9:35
b QC By		
c Lab Batch # 6749		

25 Microscope Make/Serial #
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM 4 HERA

26 ATC Project Manager	27 Result To	28 Comments
A. ANDREOU	Andreas C. Andreou Beeper/Phone #'s (646) 772-1153	

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

ATC Form 1 (1/00)

CITY_21MC100_0030885547

NYC-WTC_000298026

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME: ☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard ☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

PROJECT INFORMATION

1 Client	2 Project Name	3 Project #	4 Project Monitor	4c Rotameter Number
NYC-BOE	HS for Leadership & Public Services (M894)	14584-0864	4a Air Sampler A. KHOLODENKO	11 A 5 3
	2a Project Address 90 Trinity Place, NY, NY			

5 Date	6 Abatement Location	7 ☐ PCM (0.8 micron MCE)	8 ☒ TEM (0.45 micron MCE)	9 Type
	AS PER PROTOCOL	Cassette/Filter Manufacture ____ Lot # ____	Cassette/Filter Manufacture MMI Lot # 26396	a ☐ Background b ☐ Pre-Abate c ☐ Abatement d ☐ Post-Abate e ☐ OSHA f ☐ Environmental g ☒ Ambient h ☐ Other

DAILY AIR SAMPLE RECORD

10 Sample I.D. Number	11 Pump Number	12 Sample Location 12a IWA	12b OWA	12c Sample Coordinates	13 Time (24 hrs clock) 13a Start	13b End	13c Total	14 Flow Rate (L/min) 14a Start	14b End	14b Avg	15 Total Air Vol (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc. F/CC
				Field Blank									
				Field Blank									
-16				3rd Floor - hallway by Rm #305	08:30	12:17	227	8.0	8.0	8.0	1816		
-17				2nd Floor - auditorium center	08:34	12:23	229	8.0	8.0	8.0	1832		
-18				Bsmt, Center of gymnasium.	08:37	12:26	229	8.0	8.0	8.0	1832		
-19				Outside of Bldng, adj' to main entrance	11:56	15:44	228	8.0	8.0	8.0	1824		
-20				Vestibule at 1st fl, N/S side.	11:59	15:	227	8.0	8.0	8.0	1816		
-21				On main roof - adj' to INTAKE of HVAC	12:03	15:50	227	8.0	8.0	8.0	1816		

CHAIN OF CUSTODY

18 Relinquished By	19 Received By	20 Date	21 Time
I		2/19/02	1752
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22 Lab Name	23 Date	24 Time
a Analyzed By	2/20	9:30
b QC By		
c Lab Batch #	76	

25 Microscope Make/Serial #
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM AHERA

26 ATC Project Manager	27 Result To	28 Comments
A. ANDREOU	Andreas C. Andreou	
	Beeper/Phone #'s (646) 772-1153	

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

CITY_21MC100_003088548