ATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION 7562 21/24 87143-87166

1. Client:	2. Project Name:	3. Project #:	4. Project Monitor:	4c. Rotameter Number:
NYC - BOE	New Stuyvesant HS (M477)	19125-0246	4a. Air Sampler: HERANT ANTONYAN	HP-88
	2a. Project Address: 345 Chambers St. NY, NY 10007			

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type
4/28/02	Exterior, Interior of the bldg. & the Roof	Cassette/Filter Manufacture ____ Lot # ____	Cassette/Filter Manufacture Multy Metric Lot # 02101916	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other ____

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14c. Avg	15. Total Air Vol (liters)	16. # Fibers/ Fields Minus Blank	17. Fiber Conc. F/CC
22				Field Blank									
23				Field Blank									
1				5th floor Cafeteria	5:09	9:10	241	8	8	8	1928		
2				3rd floor Aux Gym	5:12	9:13	241	8	8	8	1928		
3				Inside the Pool area	5:15	9:17	242	8	8	8	1936		
4				Inside the Auditorium	5:18	9:20	242	8	8	8	1936		
5				Outside of the building North side	5:21	9:23	242	8	8	8	1936		
6				Outside the building East side	5:24	9:27	243	8	8	8	1944		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By	20. Date	21. Time
I. H [signature]	[signature]	4/28/02	4
II.			
III.			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC TEM	23. Date	24. Time
a. Analyzed By: [signature]	4/28	23:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

26. ATC Project Manager:	27. Results To:	28. Comments:
Yiannis Efstathiou	Yiannis Efstathiou Beeper/Phone #'s (646) 772-1155	

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

NYC-WTC_000298346

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION 7562

1. Client:	2. Project Name: / 2a. Project Address:	3. Project #:	4. Project Monitor: / 4a. Air Sampler:	4c. Rotameter Number:
NYC - BOE	New Stuyvesant HS (M477) / 345 Chambers St. NY, NY 10007	19125-0246	HERANT ANTONYAN	HP-88

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture / Lot #	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture / Lot #	9. Type
4/28/02	Exterior, Interior of the Bldg. & the Roof			a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g ☒ Ambient h ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14c. Avg	15. Total Air Vol (liters)	16. # Fibers/ Fields Minus Blank	17. Fiber Conc F/CC
24				Field Blank Sealed blank Field Blank									
7				Outside the building South side	5:27	9:30	243	8	8	8	1944		
8				1st floor lobby area	5:30	9:33	243	8	8	8	1944		
9				2nd floor lobby area	5:31	9:34	243	8	8	8	1944		
10				Outside the building 11th floor Roof.	5:35	9:40	245	8	8	8	1960		
11				Outside the building North side	9:23	13:23	240	8	8	8	1920		
12				Outside the building East side	9:27	13:27	240	8	8	8	1920		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By	20. Date	21. Time
I. H. Antonyan	M	4/28/02	9
II.			
III.			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: NYC EEC	23. Date	24. Time
a. Analyzed By:	4/29	23:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager:	27. Results To: / Beeper/Phone #'s	28. Comments:
Yiannis Efstathiou	Yiannis Efstathiou (646) 772-1155	

CITY_21MC100_003089913

NYC-WTC_000298347

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

7562

1. Client:	2. Project Name: / 2a. Project Address:	3. Project #:	4. Project Monitor: / 4a. Air Sampler:	4c. Rotameter Number:
NYC - BOE	New Stuyvesant HS (M477) / 345 Chambers St. NY, NY 10007	19125-0246	HERANT ANTONYAN	HP-88

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture / Lot #	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture / Lot #	9. Type
4/28/02	Exterior, Interior of the b/dg. & the Roof			a ☐ Background b ☐ Pre-Abale c ☐ Abatement d ☐ Post-Abale e ☐ OSHA f ☐ Environmental g ☒ Ambient h ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14c. Avg	15. Total Air Vol (liters)	16. # Fibers/ Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
13				Outside the building South side	9:30	13:30	240	8	8	8	1920		
14				1st floor lobby area	9:33	13:34	241	8	8	8	1928		
15				2nd floor lobby area	9:34	13:36	242	8	8	8	1936		
16				Outside the building 11th floor Roof	9:40	13:41	241	8	8	8	1928		
17				2nd floor Hallway	9:45	13:46	241	8	8	8	1928		
18				3rd floor Hallway	9:48	13:48	240	8	8	8	1920		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By	20. Date	21. Time
I. H.		4/28/02	
II.			
III.			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date	24. Time
a. Analyzed By:		
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager:	27. Results To: / Beeper/Phone #'s	28. Comments:
Yiannis Efstathiou	Yiannis Efstathiou (646) 772-1155	

CITY_21MC100_003089914

NYC-WTC_00029834B

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

ATC ASSOCIATES INC

7562

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1. Client:	2. Project Name: / 2a. Project Address:	3. Project #:	4. Project Monitor: / 4a. Air Sampler:	4c. Rotameter Number:
NYC - BOE	New Stuyvesant HS (M477)	9125-0246	HERANT ANTONYAN	HP-88

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture / Lot #	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture / Lot #	9. Type
4/28/02	Exterior, Interior of the Bldg. & the Roof			a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14c. Avg	15. Total Air Vol. (liters)	16. # Fibers/ FieldS Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
19				3rd floor, Rm. 301 E.	9:53	13:54	241	8	8	8	1928		
20				4th floor, Rm. 440 N.	9:56	13:57	241	8	8	8	1928		
21				5th floor, Rm. 513 S.	10:00	14:02	242	8	8	8	1936		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By	20. Date	21. Time
I. H. Antonyan	[illegible]	4/28/02	4
II.			
III.			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date	24. Time
a. Analyzed By:	5/1/02	2100
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager:	27. Results To: / Beeper/Phone #'s	28. Comments:
Yiannis Efstathiou	Yiannis Efstathiou (646) 772-1155	

NYC 9/11 Public Portal Document
CITY_21MC100_00308915