NYC-WTC_000298699

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

7985 21/24 93045-93068

1. Client:	2. Project Name:	3. Project #:	4. Project Monitor:	4c. Rotameter Number:
NYC - BOE	New Stuyvesant HS (M477)	19125-0246	4a. Air Sampler: HERANT ANTONYAN	HP ~~128~~ 128
	2a. Project Address: 345 Chambers St. NY, NY 10007			

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type
6/6/02	Exterior, Interior of the bldg. & the Roof	Cassette/Filter Manufacture ____ Lot # ____	Cassette/Filter Manufacture Mutty Metric Lot # 01205916	a. ☐ Background b. ☐ Pre-Abale c. ☐ Abalement d. ☐ Post-Abale e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other ____

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a IWA	12b OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b End	14c. Avg	15. Total Air Vol (liters)	16. # Fibers/ Fields Minus Blank	17. Fiber Conc F/CC
22				Field Blank									
23				Field Blank									
1				5th floor Cafeteria	7:11	11:12	241	8	8	8	1928		
2				3rd floor Aux Gym	7:14	11:15	241	8	8	8	1928		
3				Inside the Pool area	7:17	11:18	241	8	8	8	1928		
4				Inside the Auditorium	7:20	11:21	241	8	8	8	1928		
5				Outside of the building North side	7:23	11:24	241	8	8	8	1928		
6				Outside the building East side	7:26	11:28	242	8	8	8	1936		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By	20. Date	21. Time
I. H Antony	[illegible]	6/6/02	19
II.			
III.			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date	24. Time
a. Analyzed By:	6/6	21:30
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

26. ATC Project Manager:	27. Results To: Yiannis Efstathiou	28. Comments:
Yiannis Efstathiou	Beeper/Phone #'s (646) 772-1155	

Analysis Methodology
PCM – NIOSH 7400A
TEM – AHERA

White – File Yellow – Client/Report Pink – Lab Goldenrod – Field

CITY_21MC100_003091491

ATC ASSOCIATES INC

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

7985

PROJECT INFORMATION

1. Client:	2. Project Name:	3. Project #:	4. Project Monitor:	4c. Rotameter Number:
NYC - BOE	New Stuyvesant HS (M477)	19125-0246	4a. Air Sampler: HERANT ANTONYAN	HP-~~188~~ 128
	2a. Project Address: 345 Chambers St. NY, NY 10007			

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type
6/6/02	Exterior, Interior of the bldg. & the Roof	Cassette/Filter Manufacture ____ Lot # ____	Cassette/Filter Manufacture ____ Lot # ____	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other ____

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14c. Avg	15. Total Air Vol. (liters)	16. # Fibers/ Fields Minus Blank	17. Fiber Conc. F/CC
24				Field Blank Sealed blank									
				Field Blank									
7				Outside the building South side	7:29	11:31	242	8	8	8	1936		
8				1st floor lobby area	7:32	11:34	242	8	8	8	1936		
9				2nd floor lobby area	7:33	11:35	242	8	8	8	1936		
10				Outside the building 11th floor Roof.	7:40	11:40	240	8	8	8	1920		
11				Outside the building North side	11:24	15:24	240	8	8	8	1920		
12				Outside the building East side	11:28	15:28	240	8	8	8	1920		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By	20. Date	21. Time
I. H. [signature]	[signature]	6/6/02	19!
II.			
III.			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: TEA	23. Date	24. Time
a. Analyzed By: [signature]	6/6	21:30
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

26. ATC Project Manager: Yiannis Efstathiou

27. Results To: Yiannis Efstathiou
Beeper/Phone #'s (646) 772-1155

28. Comments:

Analysis Methodology
PCM – NIOSH 7400A
TEM – AHERA

White – File Yellow – Client/Report Pink – Lab Goldenrod – Field

NYC-WTC_000298701

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

3985

1. Client:	2. Project Name:	3. Project #:	4. Project Monitor:	4c. Rotameter Number:
NYC - BOE	New Stuyvesant HS (M477)	19125-0246	4a. Air Sampler: HERANT ANTONYAN	HP 188 128
	2a. Project Address: 345 Chambers St. NY, NY 10007			

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type
6/6/02	Exterior, Interior of the b/dg. & the Roof	Cassette/Filter Manufacture ____ Lot # ____	Cassette/Filter Manufacture ____ Lot # ____	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other ____

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14c Avg	15. Total Air Vol (liters)	16. # Fibers/ Fields Minus Blank	17. Fiber Conc F/CC
				Field Blank									
				Field Blank									
13				Outside the building South side	11:31	15:31	240	8	8	8	1920		
14				1st floor lobby area	11:34	15:34	240	8	8	8	1920		
15				2nd floor lobby area	11:35	15:35	240	8	8	8	1920		
16				Outside the building 11th floor Roof	11:40	15:41	241	8	8	8	1928		
17				6th floor, Rm. 629 S.	14:25	18:25	240	8	8	8	1920		
18				7th floor, Rm. 710 N.	14:34	18:34	240	8	8	8	1920		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By	20. Date	21. Time
I. H. Antonyan	[illegible]	6/6/02	9:
II.			
III.			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date	24. Time
a. Analyzed By:	6/6	6:30
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM – NIOSH 7400A
TEM – AHERA

26. ATC Project Manager:	27. Results To:	28. Comments:
Yiannis Efstathiou	Yiannis Efstathiou Beeper/Phone #'s (646) 772-1155	

White – File Yellow – Client/Report Pink – Lab Goldenrod – Field

CITY_21MC100_003091493

NYC-WTC_000298702

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

ATC ASSOCIATES INC.

7985

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1. Client:	2. Project Name: / 2a. Project Address:	3. Project #:	4. Project Monitor: / 4a. Air Sampler:	4c. Rotameter Number:
NYC - BOE	New Stuyvesant HS (M477)	9125-0246	HERANT ANTONYAN	HP-~~88~~ 128

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture / Lot #	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture / Lot #	9. Type
6/6/02	Exterior, Interior of the Bldg. & the Roof			a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14c. Avg	15. Total Air Vol. (liters)	16. # Fibers/ Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
19				8th floor, Rm. 801 E.	14:30	18:30	240	8	8	8	1920		
20				5th floor Hallway	14:13	18:14	241	8	8	8	1928		
21				4th floor Hallway	14:10	18:10	240	8	8	8	1920		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By	20. Date	21. Time
I. H.		6/6/02	19'
II.			
III.			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date	24. Time
a. Analyzed By:	6/6	21:30
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

26. ATC Project Manager:	27. Results To: / Beeper/Phone #'s	28. Comments:
Yiannis Efstathiou	Yiannis Efstathiou (646) 772-1155	

Analysis Methodology
PCM – NIOSH 7400A
TEM – ~~AHERA~~

White – File Yellow – Client/Report Pink – Lab Goldenrod – Field

CITY_21MC100_0030914 94

NYC 9/11 Public Portal Document