NYC 9/11 Public Portal Document

CENTRAL ARTERY (I-93)
ENVIRONMENTAL OPERATIONS
AIR QUALITY INSPECTION SHEET

Inspection Date: 07/01/02 Inspector: JF DOLAN Weather: HOT; HUMID MID 80'S

Time of Inspection	Contract Number	Work Area Inspected	Dirt/Mud tracked onto Public Roadways	Windblown Dust/Dirt from the Work Area	Diesel Emissions from the Work Area	Observations/Recommendations
1110H	C2152	TIDE AND F. KENNEDY	N	N	N	WATER TRUCK OBSERVED IN USE ON TIDE STREET AND FID KENNEDY AVENUE.
1145H	C08A1	BREMEN AND MARION	N	N	N	WATER TRUCK OBSERVED IN USE IN CONTRACTOR'S LAYDOWN AREA ADJACENT TO BREMEN STREET.
1315H	C15A2	CAUSEWAY AND N. WASHINGTON	N	N	N	STREET SWEEPER OBSERVED IN USE ON CAUSEWAY AND NORTH WASHINGTON STREETS.
1325H		NASHUA AND MINOT	N	N	N	NO DIRT TRACKING; NO ON-SITE AIRBORNE DUST; OR NO DIESIL EMISSIONS OBSERVED.
1405H	C17A3 C17A9	ATLANTIC AND NORTHERN	N	N	N	NO DIRT TRACKING; NO ON-SITE AIRBORNE DUST; OR NO DIESIL EMISSIONS OBSERVED.
1425H		A AND ACCESS ROAD	N	N	N	WATER TRUCK OBSERVED IN USE ON A STREET AND GARAGE ACCESS ROAD.
1440H		ALBANY AND E. BERKELEY	N	N	N	NO DIRT DIRT TRACKING; NO ON-SITE AIRBORNE DUST; OR NO DIESIL EMISSIONS OBSERVED