NYC-WTC_000310552

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

7206 17/20 81662-81681

1. Client	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number
NYC-BOE	H.S. & Economics and Finance (17833)	14584-865	—	HP-128
	2a. Project Address: 100 Trinity Pl. NY, NY	3a. Task # 01	4a. Air Sampler: M. BALOTA	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:		
03.25.02	ENTIRE	Cassette/Filter Manufacture:	Cassette/Filter Manufacture: Mult-Metrics	a. ☐ Background	c. ☐ Abatement	f. ☐ Environmental
		Lot #:	Lot # 00264916	b. ☐ Pre-Abate	d. ☐ Post-Abate	g. ☒ Ambient
					e. ☐ OSHA	h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol (liters)	16 # Fibers/Fields Minus Blank	17. Fiber Conc. F/cc
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
01				Field Blank									
02				Field Blank									
03			V	Outside the building - Roof South east corner	07.28	11.18	230	8.0	8.0	8.0	1840.		
04		V		8th floor - Cafeteria North west corner	07.31	11.20	229	8.0	8.0	8.0	1832.		
05			V	Staircase B (open staircase) At 7th floor landing	07.35	11.22	227	8.0	8.0	8.0	1816		
06		V		1st floor - Auditorium Left side of the entrance	07.40	11.25	225	8.0	8.0	8.0	1800.		
07		V		1st floor - Lobby Adj. to Room # 1024	07.42	11.28	226	8.0	8.0	8.0	1808.		
08			V	Outside the building Right side of Main Entrance	07.44	11.29	225	8.0	8.0	8.0	1800.		

CHAIN OF CUSTODY

18. Relinquished By	19. Received By:	20. Date:	21. Time:
I M. Balota	M.I	3.25.02	8PM
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: RRM	3/26/02	2:30
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Mark Terpeluk

27. Result To: Yiannis Efstathiou
Beeper/Phone #: (646) 772-1155

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

CITY_21MC100_003044760

NYC-WTC_000310553

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

7206

1. Client:	2. Project Name / 2a. Project Address	3. Project # / 3a. Task #	4. Project Monitor: / 4a. Air Sampler:	4c. Rotameter Number:
NYC - BOE	U.S. of Economics and Finance (NIOSH) / 100 Trinity Pl, NY, NY	14384-865 / 01	— / M. BALOTA	HP-12 B

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:
03.25.02	ENTIRE	Cassette/Filter Manufacture: ____ Lot #: ____	Cassette/Filter Manufacture: Multi-Metrics Lot #: 00264916	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
09			V	Outside the building - Roof South east corner	11.18	15.08	230	8.0	8.0	8.0	1840		
10			V	Staircase B (open staircase) At 7th floor landing	11.22	15.10	228	8.0	8.0	8.0	1824		
11		V		1st floor - Lobby Adj. to Room# 202A	11.28	15.15	227	8.0	8.0	8.0	1816		
12			V	Outside the building Right side of Main Entrance	11.29	15.16	227	8.0	8.0	8.0	1816		
13		V		9th floor - Elevator Bank Adj. to Room# 902	15.20	19.10	230	8.0	8.0	8.0	1840		
14		V		8th floor - Room# 804 Inside the room	15.22	19.12	230	8.0	8.0	8.0	1840		

CHAIN OF CUSTODY

	18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I	M. Balota	M J	3.25.02	8PM
II				
III				

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
ATC-TEM		
a. Analyzed By: RDuy	3/26	2:30
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager:	27. Result To: / Beeper/Phone #:	28. Comments:
Mark Tergesen	Yiannis Efstathiou (646) 772 - 1115	

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_0030447 61

NYC-WTC_000310554

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

#ACC

1. Client	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number
NYC-BOE	H.S. of Economics and Finance (M833)	14524-865	—	HP-128
	2a. Project Address 100 Trinity Pl., NY, NY	3a. Task # 01	4a. Air Sampler: M. BALOTA	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:
03.25.02	ENTIRE	Cassette/Filter Manufacture ____ Lot # ____	Cassette/Filter Manufacture Mu/Ai-Metrics Lot # 00264916	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
15		✓		7th floor - Elevator Bank Across Elevator # 4	15.25	19.14	229	8.0	8.0	8.0	1832		
16		✓		6th floor - Room # 605 Inside the room	15.27	19.16	229	8.0	8.0	8.0	1832		
17		✓		5th floor - corridor Adj. to Room # 504	15.30	19.18	228	8.0	8.0	8.0	1824		
18		✓		4th floor - Room # 407 Inside the room	15.35	19.21	226	8.0	8.0	8.0	1808		
19		✓		3rd floor - corridor Adj. to Room # 306	15.38	19.23	225	8.0	8.0	8.0	1800		
20				Hand blank									

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I M. Balota	M.I	3.25.2	8PM
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: RRy	4/26	2:30
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 339079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager	27. Result To:	28. Comments:
Mark Tenjesen	Yiannis Efstathiou	
	Beeper/Phone #: (646) 772-1155	

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

CITY_21MC100_0030447 62