NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

ATC ASSOCIATES INC.

Page 1 of 1

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☑ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other RUSH

PROJECT INFORMATION 6354 12/15 70085-70099

1. Client:	2. Project Name	3. Project #	4. Project Monitor	4c. Rotameter Number:
NYC - BOE	PS 89 M	14584-0519	DANIEL FINKLEY	HP 69
	2a. Project Address: 201 WARREN STREET, NY.	3a. Task #	4a. Air Sampler:	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture / Lot #	8. ☑ TEM (0.45 micron MCE) Cassette/Filter Manufacture / Lot #	9. Type:
WED 1.16.02	ROOF 3RD + 5TH FLOORS GROUND LOCATIONS		MULTI METRICS 00263916	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☑ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD AT BREATHING ZONE

10. Sample I.D. Number	11. Pump Number	12. Sample Location	12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) AM / PM 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
013					Field Blank open									
					Field Blank									
01	CAST 384721				ROOF: NORTH ON STAND = AT CENTER LOCATION	07'45 AM	12'16 PM	266	8.0	8.0	8.0	2128		
02	CAST 389780				5TH FLOOR HALLWAY SOUTH SIDE ON STAND	0750	12'07	257	8.0	8.0	8.0	2056		
03	CAST 384807				3RD FLOOR HALLWAY SOUTHSIDE ON STAND	0756	12'10	254	8.0	8.0	8.0	2032		
04	CAST 389704				1ST FLOOR HALLWAY Middle ON STAND opposite of LUNCH RM	08'00	12'21	261	8.0	8.0	8.0	2088		
05	3 8?88/				Play GROUND SOUTH SIDE ON STAND = PLAY AREA	08'03	12'23	260	8.0	8.0	8.0	2080		
06	389837				Play GROUND NORTH SIDE ON STAND - 9' from BASKETBALL HOOP.	08'08 AM	12'25 PM	257	8.0	8.0	8.0	2056		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I Daniel Finkley	RRay	1/17/02	5:00
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: RRay	1/17/02	8:45
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager:	27. Result To:	28. Comments:
A. ANDREOU	ANDREAS ANDREOU Beeper/Phone #'s 646 772 1153.	

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/

CITY_21MC100_003047082

NYC-WTC_000312901

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 11 of 11

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☑ 4 hrs ☑ 24 hrs ☐ 72 hrs ☐ Other RUSH

PROJECT INFORMATION

6354

1. Client:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number:
NYC - BOE	PS 89M	14584 - 0819	DAN FINKLEY	HPC9
	2a. Project Address: 901 WARREN STREET NYC	3a. Task #	4a. Air Sampler:	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture / Lot #	8. ☑ TEM (0.45 micron MCE) Cassette/Filter Manufacture: MULTI METRICS Lot #: 00263916	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post Abate e. ☑ OSHA f. ☑ Environmental g. ☐ Ambient h. ☒ Other
WED 1 16 02	ROOF 3RD + 5TH FLOOR GROUND LOCATIONS			

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: AT BREATHING ZONE — 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
014				Field Blank ~~SEALED~~ OPEN.									
015				Field Blank SEALED.									
07	# 389724			ROOF NORTH ON STAND	12:17 PM	16:07	2:30	8.0	8.0	8.0	1840		
08	# 389780			5TH FLOOR HALLWAY SOUTH SIDE ON STAND	12:08	16:10	242	8.0	8.0	8.0	1936.		
09	# 389807			3RD FLOOR HALLWAY SOUTH SIDE ON STAND	12:10	16:12	242	8.0	8.0	8.0	1936.		
010	# 389704			1ST FLOOR HALLWAY LOCATION middle	9/12:21	16:21	240	8.0	8.0	8.0	1920.		
011	# 389881			PlayGround SOUTH ON STAND	9/12:24	16:24	240	8.0	8.0	8.0	1920.		
012	# 389834			Play Ground NORTH ON STAND	9/12:26 PM	16:26	240	8.0	8.0	8.0	1920.		

CHAIN OF CUSTODY

	18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I	Daniel Finkley			
II		RRuy	9/17/02	5:00
III				

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC - TEM	23. Date:	24. Time:
a. Analyzed By: RRuy	9/17/02	8:45
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager:	27. Result To:	28. Comments:
A ANDREOU	ANDREAS ANDREOU	
	Beeper/Phone #'s 646 772 1153	

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_003047083

NYC-WTC_000312902