ATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

RUSH

15/18

Page _____ of _____

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard RUSH
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☑ Other

PROJECT INFORMATION 6550

1. Client: NYC · BOE	2. Project Name: Ps 89M 72057-72074	3. Project #: 14584-0819	4. Project Monitor:	4c. Rotameter Number: HP 125
	2a. Project Address: 801 WARREN STREET	3a. Task #:	4a. Air Sampler: Daniel Finkley	
5. Date: SAT 2.2.02	6. Abatement Location: ROOF PLAYGROUND; 1st Fl. HALLWAY	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture: Lot #:	8. ☑ TEM (0.45 micron MCE) MULTI METRICS Cassette/Filter Manufacture LOT # 916 Lot # #00263916	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☑ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location AT BREATHING ZONE: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
16				Field Blank Closed Field Blank									
01		In side	\	CAFE NORTHEAST QUAD.	8:20	12:10	230	8.0	8.0	8.0	1840		
02		↓	\	Hallway 1st Floor central.	8:15	12:15	230	8.0	8.0	8.0	1840		
03		\	out side	Play Ground NORTH	8:29	12:20	231	8.0	8.0	8.0	1848		
04		\	↓	Play Ground SOUTH	8:31	12:21	230	8.0	8.0	8.0	1840		
05		In side	\	AUDITORIUM 2ND floor. REAR.	8:10	12:00	230	8.0	8.0	8.0	1840		
06		\	out side	ROOF CENTRAL.	8:36	12:26	230	8.0	8.0	8.0	1840		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I [signature]	[signature]	02/02/02	1840
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: RRY	2/3/02	8:15
b. QC By:		
c. Lab Batch #: 6550		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Andreas Andreou

27. Result To: Andreas Andreou
Beeper/Phone #'s 646·772·1153

28. Comments: Note: 3RD FLOOR NOT Sampled Due to FLOOR STRIPPING & CLEANING ACTIVITYS.

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

NYC-WTC_000312973

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

RUSH

Page _____ of _____

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard RUSH
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other

PROJECT INFORMATION

1. Client:	2. Project Name / 2a. Project Address	3. Project # / 3a. Task #	4. Project Monitor / 4a. Air Sampler:	4c. Rotameter Number:
NYC · BOE	PS 89M / 201 WARREN STREET	14584-089	Daniel Finkley	HP 125

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture / Lot #	8. ☑ TEM (0.45 micron MCE) Cassette/Filter Manufacture / Lot #	9. Type:
4.2.08	ROOF PLAYGROUND; 1ST FL. HALLWAY		MULTI METRIC LOT # 916 #00263916	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: AT BREATHING ZONE — 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
17				Field Blank: Closed									
				Field Blank									
07		Inside		4TH FLOOR SOUTH END HALLWAY	8:00 AM	11:50 AM	230	8.0	8.0	8.0	1840		
08				CLASS RM 204 EAST VENTILATOR UNIT	8:05	11:55	230	8.0	8.0	8.0	1840		
09				CLASS RM 402 SOUTH VENTILATOR UNIT	8:43	12:33	230	8.0	8.0	8.0	1840		
010		Inside		CLASS RM 528 NORTH VENTILATOR UNIT.	8:46	12:36 AM	230	8.0	8.0	8.0	1840		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I [signature]	[signature]	4/6/08	1810
II			
III			

26. ATC Project Manager:	27. Result To:	Beeper/Phone #'s
Andreas Andreou	Andreas Andreou	646·772·1153

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: RLly	4/5/08	8:15
b. QC By:		
c. Lab Batch #: 6530		

28. Comments:

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_003047302

NYC-WTC_000312974

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

RUSH

Page ____ of ____

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard RUSH
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

ROJECT INFORMATION

1. Client:	2. Project Name	3. Project #	4. Project Monitor	4c. Rotameter Number:
NYC · BOE	PS 89M	14584 - 089	Daniel Finkley	HP 125
	2a. Project Address: 201 WARREN STREET	3a. Task #	4a. Air Sampler:	

Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☑ TEM (0.45 micron MCE)	9. Type:	
SAT 2.2.02	ROOF PLAYGROUND; 1ST FL. HALLWAY	Cassette/Filter Manufacture: Lot #:	Cassette/Filter Manufacture: MULTI METRIX Lot # 00263916 Lot # 916	a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA
					f. ☐ Environmental g. ☑ Ambient h. ☐ Other

AILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: AT BREATHING ZONE 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
18				Field Blank Open.									
				Field Blank									
011		inside		1ST floor Hallway CENTRAL.	12:15	16:05	230	8.0	8.0	8.0	1840		
012			outside	Playground NORTH	12:20	16:10	230	8.0	8.0	8.0	1840		
013			↓	Playground SOUTH	12:22	16:12	230	8.0	8.0	8.0	1840		
014		inside		SOUTH END HALLWAY 2ND FLOOR	12:05	15:55	230	8.0	8.0	8.0	1840		
015			outside	ROOF CENTRAL.	12:26	16:16	230	8.0	8.0	8.0	1840		

HAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I [signature]	[signature]	2/2/02	1840
II			

16. ATC Project Manager: Andreas Andreou

27. Result To: Andreas Andreou

Beeper/Phone #'s 646·772·1153

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: RDH	2/5/02	8:15
b. QC By:		
c. Lab Batch #: 6550		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

28. Comments: Note: 1ST Hallway painting ACTIVITY'S MAY CAUSE OVERLOADED SAMPLE IN 1ST FLOOR HALLWAY LOCATION

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_00304730