NYC 9/11 Public Portal Document

AYC ASSOCIATES INC.

DUST WIPE SAMPLING - CHAIN OF CUSTODY

9786

TOTAL # OF SAMPLES: 17

104 EAST 25TH STREET, 10TH FLOOR
NEW YORK, NEW YORK 10010
PHONE: 212-353-8280 FAX: 212-353-8306

Client Name: New York City Board of Education

Project Number: 19125-0246

Date: 4/27/02

Project Address: M477 /345 Chambers street, New York ,NY 10007

Project Manager: Y. Efstathiou

Turnaround Time: Rush

Investigator: Chacko Mathew

Building Type: School

Analysis Required: Lead in dust

Sample ID#	Room, Component, Location	Surface Condition	Dimension of sample area (in. x in.)	Detection Limit	Result (µg/ft²)
M477-4/27/02 – 11	MER HVAC-2 SUPPLY LOUVER	✓ Visible Dust; Visible Debris; No Visible Dust or Debris	15 x 5 1/2	15.7	174.7
M477-4/27/02 – 12	MER HVAC-2 SUPPLY LINER	✓ Visible Dust; Visible Debris; No Visible Dust or Debris	9 x 7	19.2	38.2
M477-4/27/02 – 13	MER HVAC 2 RETURNS LOUVER	✓ Visible Dust; Visible Debris; No Visible Dust or Debris	26 8/4 x 5 1/2	8.8	204.7
M477-4/27/02 – 14	MER HVAC 1 SUPPLY LOUVER	✓ Visible Dust; Visible Debris; No Visible Dust or Debris	20.0 x 5.5	11.8	31.3
M477-4/27/02 – 15	MER HVAC 1 SUPPLY LINER	✓ Visible Dust; Visible Debris; No Visible Dust or Debris	9.5 x 5.5	24.8	101.4

COMMENTS: Please call the project manager with results @ 1(646) 772-1155 (ADDITIONAL COMMENTS ON BACK)

RELINQUISHED BY (SIGNATURE BELOW):	DATE/TIME	RECIEVED BY (SIGNATURE BELOW):	DATE/TIME	LABORATORY:	
	4/27/02	4/27 4pm			
PRINT NAME:		PRINT NAME:		NLLAP#	ELAP#

CITY_21MC100_00305144G

NYC-WTC_000321508

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.

DUST WIPE SAMPLING - CHAIN OF CUSTODY

104 EAST 25TH STREET, 10TH FLOOR
NEW YORK, NEW YORK 10010
PHONE: 212-353-8280 FAX: 212-353-8306

9786

TOTAL # OF SAMPLES: 17

Client Name: New York City Board of Education

Project Number: 19125-0246

Date: 4/27/02

Project Address: M477 /345 Chambers street, New York ,NY 10007

Project Manager: Y. Efstathiou

Turnaround Time: Rush

Investigator: Chacko Mathew

Building Type: School

Analysis Required: Lead in dust

Sample ID#	Room, Component, Location	Surface Condition	Dimension of sample area (in. x in.)	Detection Limit	Result (µg/ft²)
M477 - 4/27/02 - 16	MER HVAC 1 RETURN LOUVER	✓ Visible Dust; Visible Debris; No Visible Dust or Debris	19¼" x 5.0"	13.5	253.0
M477 - 4/27/02 - 17	MER HVAC 1 RETURN LINER	✓ Visible Dust; Visible Debris; No Visible Dust or Debris	5.5" x 5.0"	47.1	139.9
M477 - 4/27/02 - 18	MER HVAC 13 RETURN Left liner	✓ Visible Dust; Visible Debris; No Visible Dust or Debris	12 x 11½	9.4	28.7
M477 - 4/27/02 - 19	MER HVAC 8 Return left liner	✓ Visible Dust; Visible Debris; No Visible Dust or Debris	12" x 12"	9.0	26.2
M477 - 4/27/02 - 20	MER HVAC 8 Supply Wall-1 liner	✓ Visible Dust; Visible Debris; No Visible Dust or Debris	12 x 5	21.6	36.7

COMMENTS: Please call the project manager with results @ 1(646) 772-1155 (ADDITIONAL COMMENTS ON BACK)

RELINQUISHED BY (SIGNATURE BELOW):	DATE/TIME	RECIEVED BY (SIGNATURE BELOW):	DATE/TIME	LABORATORY:	
[signature]	4/27/02	ACh 4/27 4 pm			
PRINT NAME:		PRINT NAME:		NLLAP#	ELAP#

CITY_21MC100_003051447

NYC-WTC_000321509

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.
104 EAST 25TH STREET, 10TH FLOOR
NEW YORK, NEW YORK 10010
PHONE: 212-353-8280 FAX: 212-353-8306

DUST WIPE SAMPLING - CHAIN OF CUSTODY

9780 PAGE 2 OF 2

TOTAL # OF SAMPLES: 17

Client Name: New York City Board of Education | Project Number: 19125-0246 | Date: 4/27/02

Project Address: M477 /345 Chambers street, New York ,NY 10007 | Project Manager: Y. Efstathiou | Turnaround Time: Rush

Investigator: Chacko Mathew | Building Type: School | Analysis Required: Lead in dust

Sample ID#	Room, Component, Location	Surface Condition	Dimension of sample area (in. x in.)	Detection Limit	Result (µg/ft²)
M477-4/27/02 – 21	MER HVAC #9 Return Wall-1 liner	✓ Visible Dust; Visible Debris; No Visible Dust or Debris	12 x 12	9.0	27.3
M477-4/27/02 – 22	MER HVAC #9 Supply Wall-1 liner	✓ Visible Dust; Visible Debris; No Visible Dust or Debris	12 x 12	9.0	< 9.0
M477-4/27/02 – 23	MER HVAC #7 Return ~~Supply~~ Wall-1 liner	✓ Visible Dust; Visible Debris; No Visible Dust or Debris	12 x 6	18.0	48.8
M477-4/27/02 – 24	MER HVAC #7 Supply Wall-1 liner	✓ Visible Dust; Visible Debris; No Visible Dust or Debris	12 x 12	9.0	17.0
M477-4/27/02 – 25	Floor HVAC 14 Supply line	✓ Visible Dust; Visible Debris; No Visible Dust or Debris	12 x 12	9.0	200.5

COMMENTS: Please call the project manager with results @ 1(646) 772-1155 *(ADDITIONAL COMMENTS ON BACK)*

RELINQUISHED BY (SIGNATURE BELOW):	DATE/TIME	RECIEVED BY (SIGNATURE BELOW):	DATE/TIME	LABORATORY:	
[signature]	4/27/02	[signature] 4/27 4pm			
PRINT NAME:		PRINT NAME:		NLLAP#	ELAP#

CITY_21MC100_003051448

NYC-WTC_000321510

NYC 9/11 Public Portal Document

AJC ASSOCIATES INC.

DUST WIPE SAMPLING - CHAIN OF CUSTODY

9786

104 EAST 25TH STREET, 10TH FLOOR
NEW YORK, NEW YORK 10010
PHONE: 212-353-8280 FAX: 212-353-8306

PAGE 1 OF 1

TOTAL # OF SAMPLES: 1

Client Name: New York City Board of Education

Project Number: 19125-0246

Date: 4/27/02

Project Address: M477 /345 Chambers street, New York ,NY 10007

Project Manager: Y. Efstathiou

Turnaround Time: Rush

Investigator: Chacko Mathew

Building Type: School

Analysis Required: Lead in dust

Sample ID#	Room, Component, Location	Surface Condition	Dimension of sample area (in. x in.)	Detection Limit	Result (µg/ft²)
M477 - 4/27/02 - 26	Blank	___ Visible Dust ___ Visible Debris ___ No Visible Dust or Debris	—		< 9.0
M477 - 4/27/02 - 27	Blank	___ Visible Dust ___ Visible Debris ___ No Visible Dust or Debris	—		< 9.0
M477 - 4/27/02 - 28	Blank	___ Visible Dust ___ Visible Debris ___ No Visible Dust or Debris	—		< 9.0
M477 - 4/27/02 - 29	Blank	___ Visible Dust ___ Visible Debris ___ No Visible Dust or Debris	—		< 9.0
		___ Visible Dust ___ Visible Debris ___ No Visible Dust or Debris			

COMMENTS: Please call the project manager with results @ 1(646) 772-1155 *(ADDITIONAL COMMENTS ON BACK)*

RELINQUISHED BY (SIGNATURE BELOW):	DATE/TIME	RECIEVED BY (SIGNATURE BELOW):	DATE/TIME	LABORATORY:	
	4/27/02	4/27 4 pm			
PRINT NAME:		PRINT NAME:		NLLAP#	ELAP#

CITY_21MC100_003051449

NYC-WTC_000321511

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.
104 EAST 25TH STREET, 10TH FLOOR
NEW YORK, NEW YORK 10010
PHONE: 212-353-8280 FAX: 212-353-8306

DUST WIPE SAMPLING - CHAIN OF CUSTODY

TOTAL # OF SAMPLES: 17

Client Name: New York City Board of Education

Project Number: 19125-0246

Date: 4/27/02

Project Address: M477/345 Chambers Street ,New York, NY 10007

Project Manager: Y. Efstathiou

Turnaround Time: Rush

Investigator: Chacko Mathew

Building Type: School

Analysis Required: Lead in dust

Sample ID#	Room, Component, Location	Surface Condition	Dimension of sample area (in. x in.)	Detection Limit	Result (µg/ft²)
M477-4/27/02 -28	Blank	___ Visible Dust ___ Visible Debris ___ No Visible Dust or Debris		9.0µg	<9.0µg
-29	Blank	___ Visible Dust ___ Visible Debris ___ No Visible Dust or Debris		9.0µg	<9.0µg
		___ Visible Dust ___ Visible Debris ___ No Visible Dust or Debris			
		___ Visible Dust ___ Visible Debris ___ No Visible Dust or Debris			
		___ Visible Dust ___ Visible Debris ___ No Visible Dust or Debris			

COMMENTS: Please call the project manager with results @ 1(646) 772-1155 *(ADDITIONAL COMMENTS ON BACK)*

RELINQUISHED BY (SIGNATURE BELOW):	DATE/TIME	RECIEVED BY (SIGNATURE BELOW):	DATE/TIME	LABORATORY:	
	4/27/02				
PRINT NAME:		PRINT NAME:		NLLAP#	ELAP#

CITY_21MC100_003051450

NYC-WTC_000321512