NYC 9/11 Public Portal Document

228 East 45th Street
New York, NY 10017
(212) 922-0077
Fax (212) 922-0630

5928

WARREN & PANZER ENGINEERS, P. C.

AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

24 hr+/a 12 hr+/a 6 hr+/a 3 hr+/a (Immediate +/a)

P.O. _____

5/09

CLIENT: NYC DDC

PROJECT: American Express Bldg. (30th Fl.)

LOCATION: Vesey St. NY NY

64597-64605

W&P FILE #: 1017.44.01

LABORATORY: ATC. ENV. Cons.

ANALYSIS METHOD: PCM / TEM 7400 / TEM AHERA / (TEM EPA LEVEL II) — circle one

TECHNICIAN: Vladimir Khinich

CONTACT: _____

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE START	FLOWRATE STOP	TIME ON	TIME OFF	TOTAL TIME	VOLUME (liters)	CONCENTR (f/cc.)
-40	Cubby of Down Barbara	8	—	5.0	5.0	7:10	1310	360	1800	
-41	Cubby # 169-170	8		5.0	5.0	7:12	1312	360	1800	
~~-42~~	~~Cubby # 120-305~~	8		5.0	5.0	7:15	UNPLUGGED	(VOID (FIELD)		
-43	FIELD BLANK	1	—	—	—	0705	—	—	—	
-44	FIELD BLANK	1	—	—	—	0706	—	—	—	
-45	CAPPED BLANK	1	—	—	—	—	—	—	—	
-46	DAWN BARBARE CUBBY	8		5.0	5.0	1330	1930	360	1800	
-47	CUBBY # 169-170	8		5.0	5.0	1332	1932	360	1800	
-48	CUBBY # 120-305	8		5.0	5.0	1334	1934	360	1800	

COMMENTS: Fax to: ① Bob Adams 609-584-11-34
② Bruce Rothrock 201-287-0059
③ DDC office 718-391-1281
④ W&P 212-922-0630

SAMPLE BY: Vladimir Khinich DATE: 11-19-01

SIGNATURE: _____

RELEASED BY: Lawrence Baer DATE: 11/19/01

SIGNATURE: _____

RECEIVED BY: _____ DATE: 11/19/01

SIGNATURE: _____ 2130

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION

CITY_21MC100_003132842

NYC-WTC_000322452