NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-22-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
350 Chambers Street
7th Floor

PROJECT NUMBER: M477-15217-29881

SAMPLED BY: Client

SAMPLE DATE 07-21-02
DATE RECEIVED: 07-21-02
DATE ANALYZED: 07-21-02

SAMPLE MEDIA: Air Samples
ANALYSIS REQUIRED: Method NIOSH 7082

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/m^3$)	DETECTION LIMIT ($\mu g/m^3$)
01	20521	Inside Room #701A by Entrance	<3.1	3.1
02	20521	Inside Room #701 by Entrance	<3.1	3.1
03	20521	Inside Room #705 by Entrance	<3.1	3.1
04	20521	Inside Room #707 by Entrance	<3.6	3.6
05	20521	Inside Room #709 by Entrance	<3.1	3.1
06	20521	Inside Room #715 by Entrance	<3.1	3.1
07	20521	Inside Room #717 by Entrance	<3.1	3.1
08	20521	Inside Room #727 by Entrance	<3.6	3.6
09	20521	Inside Room #729 by Entrance	<3.1	3.1
10	20521	Inside Room #704 by Entrance	<4.2	4.2
11	20521	Inside Room #702 by Entrance	<5.4	5.4
12	20521	Inside Room #726 by Entrance	<5.4	5.4
13	20521	Inside Room #736 by Entrance	<5.4	5.4
14	20521	Inside Room #738 by Entrance	<5.4	5.4
15	20521	Inside Room #701A by Entrance	<3.4	3.4
16	20521	Inside Room #701 by Entrance	<3.4	3.4
17	20521	Inside Room #705 by Entrance	<3.4	3.4

NYC-WTC_000323045

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

18	20521	Inside Room #707 by Entrance	<3.4	3.4
19	20521	Inside Room #709 by Entrance	3.9	3.9
20	20521	Inside Room #715 by Entrance	<3.4	3.4
21	20521	Inside Room #717 by Entrance	<3.4	3.4
22	20521	Inside Room #727 by Entrance	<3.4	3.4
23	20521	Inside Room #729 by Entrance	<3.4	3.4
24	20521	Inside Room #704 by Entrance	<3.4	3.4
25	20521	Inside Room #702 by Entrance	<3.9	3.9
26	20521	Inside Room #726 by Entrance	<3.4	3.4
27	20521	Inside Room #736 by Entrance	<3.4	3.4
28	20521	Inside Room #738 by Entrance	<3.4	3.4
29	20521	Inside Room #740 by Entrance	<3.4	3.4
30	20521	Field Blank	<1.5 µg	1.5 µg
31	20521	Field Blank	<1.5 µg	1.5 µg
32	20521	Field Blank	<1.5 µg	1.5 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 3.0 µg
NOTE 2:
At the present time there are no regulatory levels or requirements for indoor airborne lead in area samples. However, OSHA has established an action level of 30 $\mu g/m^3$ and a permissible exposure level (PEL) of 50 $\mu g/m^3$ for personal samples.
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000323046