NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.

7790

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

RUSH

16/19

90326-90344

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other Rush

PROJECT INFORMATION

1. Client:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number:
NYC - BOE	PS 89 M	14584 - 0819		HP 125
	2a. Project Address: 201, WARREN STREET	3a. Task #	4a. Air Sampler: G. VARUGHESE	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:		
05/18/02	ALL Floors Playground, Roof	Cassette/Filter Manufacture: ____ Lot # ____	Cassette/Filter Manufacture MULTIMETRICS Lot # 02100916	a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA	f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: AIR BREATHING ZONE — 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) — 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) — 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
017				Field Blank CLOSED Field Blank									
01		Inside	/	CAFETERIA - Rm 115 NORTH EAST	7 50 A	11 50 A	240	8.0	8.0	8.0	1920		
02		Inside	/	FIRST FLOOR HALLWAY OUTSIDE CAFETERIA	7 55 A	11 55 A	240	8.0	8.0	8.0	1920		
03		/	Outside	PLAYGROUND NORTH NEXT TO DOOR	8 00 A	12 00 P	240	8.0	8.0	8.0	1920		
04		/	Outside	PLAYGROUND SOUTH NEXT TO DOOR	8 05 A	12 05 P	240	8.0	8.0	8.0	1920		
05		Inside	/	SECOND FLOOR AUDITORIUM REAR MIDDLE	8 10 A	12 10 P	240	8.0	8.0	8.0	1920		
06		Inside	/	THIRD FLOOR GYMNESIUM SOUTH EAST	8 15 A	12 15 P	240	8.0	8.0	8.0	1920		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I Vaughan	H. Gray	5/18/02	20:30
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: RRuf	5.19.02	1:50
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Yiannis Efstathiou

27. Result To: Yiannis Efstathiou
Beeper/Phone #'s 646 - 772 - 1155

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_011275326

NYC-WTC_000324751

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC

7790

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

RUSH

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other Rush

PROJECT INFORMATION

1. Client:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number:
NYC - BoE	PS 89 M	14584 - 0819		HP 125
	2a. Project Address: 201, WARREN STREET	3a. Task #	4a. Air Sampler: G. VARUGHESE	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:	
05/18/02	ALL Floors Playground, Roof	Cassette/Filter Manufacture:	Cassette/Filter Manufacture: MULTIMETRICS	a. ☐ Background	c. ☐ Abatement
		Lot #:	Lot #: 02100916	b. ☐ Pre-Abate	d. ☐ Post-Abate
				e. ☐ OSHA	f. ☐ Environmental
					g. ☒ Ambient
					h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: AIR BREATHING ZONE — 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) — 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) — 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
018				Field Blank: FIELD BLANK									
				Field Blank									
07		/	Outside	ROOF ON NORTHSIDE MIDDLE OF ROOF	8 25 A	12 25 P	240	8.0	8.0	8.0	1920		
08		Inside	/	FIRST FLOOR HALLWAY OUTSIDE OF CAFETERIA	12 30 P	4 30 P	240	8.0	8.0	8.0	1920		
09		/	Outside	PLAYGROUND NORTH NEXT TO DOOR	12 35 P	4 35 P	240	8.0	8.0	8.0	1920		
010		/	Outside	PLAYGROUND SOUTH NEXT TO DOOR	12 40 P	4 40 P	240	8.0	8.0	8.0	1920		
011		/	Outside	ROOF ON NORTHSIDE MIDDLE OF ROOF	12 50 P	4 50 P	240	8.0	8.0	8.0	1920		
012		Inside	/	SECOND FLOOR HALLWAY SOUTH END	2 35 P	6 35 P	240	8.0	8.0	8.0	1920		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I [illegible]	K. Gray	5/18/02	20:30
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: RDM	5.19.02	1:50
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Yiannis Efstathiou

27. Result To: Yiannis Efstathiou
Beeper/Phone #'s 646-772-1155

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_011275327

NYC-WTC_000324752

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC. 7790

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

RUSH

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other Rush

PROJECT INFORMATION

1. Client:	2. Project Name	3. Project: #	4. Project Monitor:	4c. Rotameter Number:
NYC - BOE	PS 89 M	14584 - 0819		HP 125
	2a. Project Address: 201, WARREN STREET	3a. Task #	4a. Air Sampler: G. VARUGHESE	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:		
05/18/02	ALL Floors Playground, Roof	Cassette/Filter Manufacture: ____ Lot #: ____	Cassette/Filter Manufacture: MULTIMETRICS Lot #: 002100916	a. ☐ Background	c. ☐ Abatement	f. ☐ Environmental
				b. ☐ Pre-Abate	d. ☐ Post-Abate	g. ☒ Ambient
					e. ☐ OSHA	h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: AIR BREATHING ZONE — 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) — 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) — 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17 Fiber Conc. F/CC
019				Field Blank OPENED									
				Field Blank									
013		Inside	/	CLASSROOM 301 SOUTH VENT	2:40 P	6:40 P	240	8.0	8.0	8.0	1920		
014		Inside	/	FOURTH FLOOR HALLWAY SOUTH END	2:45 P	6:45 P	240	8.0	8.0	8.0	1920		
015		Inside	/	CLASSROOM 428 NORTH VENT	2:50 P	6:50 P	240	8.0	8.0	8.0	1920		
016		Inside	/	CLASSROOM 202 EAST VENT	2:55 P	6:55 P	240	8.0	8.0	8.0	1920		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I [signature]	H. [signature]	5/18/02	20:30
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC - TEM	23. Date:	24. Time:
a. Analyzed By: RRy	5.19.02	1:50
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Yiannis Efstathiou

27. Result To: Yiannis Efstathiou
Beeper/Phone #'s 646 - 772 - 1155

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_011275328

NYC-WTC_000324753