ATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

RUSH

Page 1 of 3

TURNAROUND TIME: ☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard ☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION 6899 P 16/19 76832- 14584

1. Client:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number:
NYC BOE	P.S. 89M 76850	-0819		HP 125
	2a. Project Address: 201 WARREN ST	3a. Task #	4a. Air Sampler: G. VARUGHESEY	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☑ TEM (0.45 micron MCE)	9. Type:
3/02/02	All FLOORS, PLAYGROUND + ROOF.	Cassette/Filter Manufacture: ~~Lot #~~	Cassette/Filter Manufacture: MULTIMETRICS Lot # 00263916	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates AT BREATHING ZONE ON STANDS.	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
017				Field Blank CLOSED									
				Field Blank									
01		INSIDE		CAFETERIA Rm 115 NORTH EAST SIDE	7:10 AM	11:00 AM	230 min	8.0	8.0	8.0	1840		
02				FIRST FLOOR HALLWAY OUTSIDE OF CAFETERIA	7:13 AM	11:05 AM	232 min	8.0	8.0	8.0	1856		
03			OUTSIDE	PLAYGROUND NORTH COLUMN NEXT TO DOORWAY	7:15 AM	11:10 AM	235	8.0	8.0	8.0	1880		
04				PLAYGROUND SOUTH SOUTH COLUMN NEXT TO DOOR	7:18 AM	11:13 AM	235	8.0	8.0	8.0	1880		
05		INSIDE		SECOND FLOOR AUDITORIUM RM 217. REARSIDE MIDDLE	7:22 AM	11:17 AM	235	8.0	8.0	8.0	1880		
06				THIRD FLOOR GYM SOUTH EAST SIDE	7:25 AM	11:20 AM	235	8.0	8.0	8.0	1880		

CHAIN OF CUSTODY

18. Relinquished By	19. Received By:	20. Date:	21. Time:
I [signature]	[signature]	3/2/02	8:00 PM
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: RRly	3/3/02	9:00
b. QC By:		
c. Lab Batch #: 6899		

25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079

Analysis Methodology: PCM - NIOSH 7400A; TEM - AHERA

26. ATC Project Manager: Andreas Andreou

27. Result To: A Andreou

Beeper/Phone #'s: 646-772-1153

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

HY-1 (1/01)

CITY_21MC100_003269272

ATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

RUSH

Page 2 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client	2. Project Name	3. Project #	4. Project Monitor	4c. Rotameter Number
NYC BOE	P.S. 89M	14584 - 0819		HP 125
	2a. Project Address: 201 WARREN ST	3a. Task #	4a. Air Sampler: G. VAROGHES, GY	

5. Date	6. Abatement Location	7. ☐ PCM (0.8 micron MCE)	8. ☑ TEM (0.45 micron MCE)	9. Type
3/02/02	AIR FLOORS, PLAYGROUND + ROOF.	Cassette/Filter Manufacture: ~~Lot #~~	Cassette/Filter Manufacture: MULTI METRICS; Lot # 00263916	a. ☐ Background; b. ☐ Pre-Abate; c. ☐ Abatement; d. ☐ Post-Abate; e. ☐ OSHA; f. ☐ Environmental; g. ☐ Ambient; h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates: AT BREATHING ZONE ON STANDS.	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
018				Field Blank CLOSED Field Blank									
07			outside	Roof - Central	7:30 AM	11:30 AM	240	8.0	8.0	8.0	1920		
08		INSIDE		FIRST FLOOR HALLWAY OUTSIDE OF CAFETERIA	11:45	3:35	230	8.0	8.0	8.0	1840		
09			OUTSIDE	PLAYGROUND NORTH NEXT TO COLUMN BY DOOR	11:48	3:38	230	8.0	8.0	8.0	1840		
010			OUTSIDE	PLAYGROUND SOUTH NEXT TO COLUMN BY DOOR	11:50	3:40	230	8.0	8.0	8.0	1840		
011			↓	ROOF - CENRAL	11:55	3:45	230	8.0	8.0	8.0	1840		
012		INSIDE		CLASSROOM 528 NORTH VENT	3:10 PM	7:00 PM	230	8.0	8.0	8.0	1840		

CHAIN OF CUSTODY

18. Relinquished By	19. Received By	20. Date	21. Time
I [signature]	[signature]	3/2/02	8:00 PM
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date	24. Time
a. Analyzed By: [signature]	3/3/02	9:00
b. QC By:		
c. Lab Batch #: 6899		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Andreas Andreou

27. Result To: A Andreou
Beeper/Phone #'s 646-772-1153

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

HY-1 (1/01)

CITY_21MC100_003269273

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

RUSH

TURNAROUND TIME: ☐ 2 hrs ☐ 4 hrs ☐ 6 hrs ☐ 24 hrs ☐ 48 hrs ☐ 72 hrs ☐ Standard ☐ Other

14584

PROJECT INFORMATION

1. Client:	2. Project Name:	3. Project #:	4. Project Monitor:	4c. Rotameter Number:
NYC BOE	P.S. 89M	0819		HP 125
	2a. Project Address: 601 WARREN ST	3a. Task #	4a. Air Sampler: G. VAROUGHESE	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture / Lot #	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture / Lot #	9. Type:	
3/02/02	ALL FLOORS, PLAYGROUND + ROOF.		MULTIMETRICS 00263916	a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: AT BREATHING ZONE ON STANDS. 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
019				Field Blank OPENED									
				Field Blank									
013		Inside	/	CLASSROOM 402 SOUTH VENT	3:15 pm	7:05 pm	230	8.0	8.0	8.0	1840		
014		↓	/	CLASSROOM 308 EAST VENT	3:17 pm	7:07 pm	230	8.0	8.0	8.0	1840		
015		Inside	/	SECOND FLOOR HALLWAY SOUTH END	3:19 pm	7:10 pm	230	8.0	8.0	8.0	1840	1	
016		↓	/	FOURTH FLOOR HALLWAY SOUTH END	3:16 pm	7:06 pm	230	8.0	8.0	8.0	1840		
/													

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
A		3/2/02	8:00 PM
B			
C			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: RDy	3/3/02	9:00
b. QC By:		
c. Lab Batch #: 6899		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Andreas Andreou

27. Result To: A Andreou
Beeper/Phone #'s: 646 772 1153

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

HY-1 (1/01)

CITY_21MC100_00326927 4

NYC-WTC_000325239