ATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

RUSH

Page I of III

16/19 72560-72578 14584

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☑ Other RUSH

PROJECT INFORMATION 6584

1. Client:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number:
NYC. BOE	PS 89M	-0819		HP 125
	2a. Project Address: 201 WARREN ST	3a. Task #	4a. Air Sampler: DANIEL FINKLEY	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☑ TEM (0.45 micron MCE)	9. Type:
WED. 2/6/02	All FLOORS. PLAYGROUND / ROOF.	~~Cassette/Filter Manufacture~~ ~~Lot #~~	Cassette/Filter Manufacture MULTIMETRICS Lot # 00263916	a. ☐ Background b. ☐ Pre Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☑ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
17				Field Blank CLOSED.									
				Field Blank									
01		In Side	\	CAFE SOUTHEAST NEAR PANTRY	8:10 AM	12:00 PM	230	8.0	8.0	8.0	1840		
02		↓	\	1ST floor Hallway OUTSIDE CAFE	8:12	12:02	230	8.0	8.0	8.0	1840		
03		\	OUT Side	Play Ground NORTH NEAR COLUMN NEXT TO BENCH	8:20	12:10	230	8.0	8.0	8.0	1840		
04		\	↓	Play Ground SOUTH NEAR COLUMN NEXT TO BENCH	8:36	12:26	230	8.0	8.0	8.0	1840		
05		\	↓	ROOF CENTAL AREA OF ROOF ON STAND.	8:33	12:23	230	8.0	8.0	8.0	1840		
06		In SIDE	\	2ND FLOOR	8:05 AM	11:55 AM	230	8.0	8.0	8.0	1840		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I [signature]	[signature]	02/06/02	2030
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: [signature]	3/7/02	8:20
b. QC By:		
c. Lab Batch #: 6584		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Andreas Andreou

27. Result To: A Andreou
Beeper/Phone #'s 646-772 1153

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_003269417

NYC-WTC_000325342

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

RUSH

14584

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard RUSH
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client	2. Project Name	3. Project #	4. Project Monitor	4c. Rotameter Number
NYC. BOE	PS 89M	-0819		
	2a. Project Address: 201 WARREN ST	3a. Task #	4a. Air Sampler: DANIEL FINKLEY	IIP-165

5. Date	6. Abatement Location	7. PCM (0.8 micron MCE)	8. TEM (0.45 micron MCE)	9. Type
WED 2/6/02	ALL FLOORS. PLAYGROUND / ROOF.	Cassette/Filter Manufacture: Lot #:	Cassette/Filter Manufacture: MULTIMETRICS Lot #:	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☑ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
18				Field Blank CLOSED.									
				Field Blank									
07		IN SIDE		3RD FLOOR	800 AM	1150 AM	230	8.0	8.0	8.0	1840		
08		↓		1ST floor Hallway OUTSIDE OF CAFE	1202	1552	230	8.0	8.0	8.0	1840		
09			OUT	Playground NORTH	1210	1600	230	8.0	8.0	8.0	1840		
010			SIDE	Playground SOUTH	1226	1616	230	8.0	8.0	8.0	1840		
011			E	ROOF.	1223	1613	230	8.0	8.0	8.0	1840		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I			
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC - TEM	23. Date:	24. Time:
a. Analyzed By:	2/7/02	8:20
b. QC By:		
c. Lab Batch #: 6889		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Andreas Andreou

27. Result To: A Andreou
Beeper/Phone #'s 646-772 1153

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY 1 (1/01)

CITY_21MC100_003269418

ATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

RUSH

14584

Page III of III

TURNAROUND TIME: ☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard ☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other RUSH

PROJECT INFORMATION

1. Client:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number:
NYC. BOE	PS 89M	-0819		HP 125
	2a. Project Address: 201 WARREN ST	3a. Task #	4a. Air Sampler: DANIEL FINKLEY	

5. Date: WED 2/6/02

6. Abatement Location: All FLOORS PLAYGROUND/ROOF.

7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture ____ Lot # ____

8. ☑ TEM (0.45 micron MCE) Cassette/Filter Manufacture MULTIMETRICS Lot # ____

9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☑ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

12. Sample Location: AT BREATHING ZONE

10. Sample I.D. Number	11. Pump Number	12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
19				Field Blank OPEN.									
				Field Blank									
012		Inside	N/A	Class RM 226 (2ND FL) NORTH VENT. CENTER OF VENT UNIT.	1520	1910	230	8.0	8.0	8.0	1840		
013				Class RM 302 (3RD FL) SOUTH VENT. CENTER OF VENT UNIT.	1510	1900	230	8.0	8.0	8.0	1840		
014				Class RM 410 EAST VENT CENTER OF VENT.	301	1851	230	8.0	8.0	8.0	1840		
015				2ND Floor Hallway SOUTH END	1515	1905	230	8.0	8.0	8.0	1840		
016				4TH Floor. HALLWAY SOUTH END	1523	1913	230	8.0	8.0	8.0	1840		
			N/A										

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I [signature]	[signature]	02/06/02	2030
II			
III			

26. ATC Project Manager: Andreas Andreou

27. Result To: A Andreou

Beeper/Phone #'s 646-772 1153

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: [signature]	3/5/02	8:20
b. QC By:		
c. Lab Batch #: 6584		

28. Comments:

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)