ATC ASSOCIATES INC.

7215

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

RUSH

Page I of III

TURNAROUND TIME: ☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard ☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

16/19 81851 14584-

PROJECT INFORMATION

1. Client: NYC·BOE	2. Project Name: PS 89M 81869	3. Project #: 0819.	4. Project Monitor: Daniel Finkley
	2a. Project Address: 201 WARREN ST.	3a. Task #	4a. Air Sampler:
4c. Rotameter Number: HP125			

5. Date: TUES 3/26/02

6. Abatement Location: ALL FLOORS. PLAYGROUND/ROOF

7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture Lot #

8. ☑ TEM (0.45 micron MCE) Cassette/Filter Manufacture MULTI-METRICS Lot # 00266916

9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☑ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

12. Sample Location: AT BREATHING ZONE

10. Sample I.D. Number	11. Pump Number	12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
017				Field Blank CLOSED									
				Field Blank									
01		IN Side	\	cafeteria	7:57 AM	11:47 AM	230	8.0	8.0	8.0	1840		
02		↓	\	1st floor Hallway outside of cafeteria	8:05	11:55 AM	230	8.0	8.0	8.0	1840		
03		\	OUT Side	Playground NORTH END. COLUMN NEXT	8:15	12:05 PM	230	8.0	8.0	8.0	1840		
04		\	↓	playground SOUTH END.	8:17	12:07 P.M.	230	8.0	8.0	8.0	1840		
05		IN Side	\	2ND floor AUDITORIUM. 217.	7:48	11:39 AM	230	8.0	8.0	8.0	1840		
06		↓	\	3RD floor GYMNASIUM 315.	7:51 AM	11:41 AM	230	8.0	8.0	8.0	1840		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I D Finkley	[signature]	3/26	20:00
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC TECH	23. Date:	24. Time:
a. Analyzed By: [signature]	3/26	22:05
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079

26. ATC Project Manager: Yiannis Efstahiou

27. Result To: Y. EFstahiou Beeper/Phone #'s 646.772.1155

28. Comments:

Analysis Methodology: PCM - NIOSH 7400A; TEM - AHERA

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_011275926

ATC ASSOCIATES INC.

7215

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

RUSH

Page # of 711

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number:
NYC·BOE	PS 89M	14584-0819.	Daniel Finkley	HP125
	2a. Project Address: 201 WARREN ST.	3a. Task #	4a. Air Sampler:	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☑ TEM (0.45 micron MCE)	9. Type:
TUES 3/26/02	ALL FLOORS. PLAYGROUND/ROOF.	Cassette/Filter Manufacture: ~~Lot #~~	Cassette/Filter Manufacture: MULTI-METRICS Lot #	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☑ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

12. Sample Location: AT BREATHING ZONE

10. Sample I.D. Number	11. Pump Number	12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
018				Field Blank CLOSED.									
				Field Blank									
07			OUT SIDE	ROOF - CENTRAL	8:25 AM	12:15 P.M.	230	8.0	8.0	8.0	1840		
08		IN Side		1st floor Hallway OUTside of cafeteria	11:55 AM	3:45	230	8.0	8.0	8.0	1840		
09			OUT Side	Play Ground NORTH END	12:05 PM	3:55 PM	230	8.0	8.0	8.0	1840		
010				Play Ground ~~NORTH~~ SOUTH END	12:07 P.M.	3:57	230	8.0	8.0	8.0	1840		
011				ROOF - CENTRAL.	12:16 PM	4:06 PM	230	8.0	8.0	8.0	1840		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I [signature]	[signature]	3/26	20:00
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By: [signature]	3/26	22:05
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Yiannis Efstahiou

27. Result To: Y. Efstahiou
Beeper/Phone #'s 646.772 1155.

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_011275927

NYC 9/11 Public Portal Document

VATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

RUSH

Page III of III

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client:	2. Project Name:	3. Project #:	4. Project Monitor:	4c. Rotameter Number:
NYC BOE	PS89M	0819	Daniel Finkley	HP125
	2a. Project Address: 201 WARREN ST.	3a. Task #:	4a. Air Sampler:	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture / Lot #	8. ☑ TEM (0.45 micron MCE) Cassette/Filter Manufacture: MULTI-METRICS / Lot #	9. Type:
3/26/02 TUES.	ALL FLOORS. PLAYGROUND/ROOF			a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☑ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: AT BREATHING ZONE — 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank OPEN.	P.M.	P.M.							
01				Field Blank									
11		IN SIDE		CLASS ROOM # 428 NORTH VENT.	255 PM	645 PM	230	8.0	8.0	8.0	1840		
13		|		CLASS ROOM # 304 EAST VENT.	300 PM	650	230	8.0	8.0	8.0	1840		
14		|		CLASS ROOM 502 SOUTH VENT.	305 PM	655	230	8.0	8.0	8.0	1840.		
15		|		2ND FLOOR HALLWAY SOUTH END	244	634	230	8.0	8.0	8.0	1840		
16		V		4TH FLOOR HALLWAY SOUTHEND	249	639	230	8.0	8.0	8.0	1840		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I		3/26	2015
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:	3/26	22:10
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager:	27. Result To:	28. Comments:
Yiannis Efstathiou	Y. Efstathiou Beeper/Phone #'s 646.772.1155.	

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field NY-1 (1/01)

CITY_21MC100_011275928

NYC-WTC_000325804