NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

ATC ASSOCIATES INC. 7131 — RUSH — 16/19 80516-80534 14584-

Page 1 of _____

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client:	2. Project Name: PS 89M	3. Project #: 0819	4. Project Monitor:	4c. Rotameter Number:
NYC-BOE	2a. Project Address: 201 WARREN ST	3a. Task #	4a. Air Sampler: Daniel Finkley	HP125

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☑ TEM (0.45 micron MCE)	9. Type:
TUES 3/18/02	ALL FLOORS PLAYGROUND / ROOF	Cassette/Filter Manufacture: _____ Lot #: _____	MULTI-METRIC Cassette/Filter Manufacture: _____ Lot # 002660916	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

BREATHING ZONE — A.M.

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
017				Field Blank CLOSED Field Blank									
01		IN SIDE		CAFETERIA	8:00 AM	11:50 AM	230	8.0	8.0	8.0	1840		
02		↓		1ST FLOOR HALLWAY OUTSIDE CAFETERIA	8:02	11:52 AM	230	8.0	8.0	8.0	1840		
03			OUT SIDE	PLAYGROUND - NORTH	8:05	12:15 PM	230	8.0	8.0	8.0	1840		
04			↓	PLAYGROUND - SOUTH	8:07	12:17 PM	230	8.0	8.0	8.0	1840		
05		IN SIDE		2ND FLOOR AUDITORIUM 217	8:10 AM	12:00	230	8.0	8.0	8.0	1840		
06		↓		3RD FLOOR GYMNASIUM	8:15 AM	12:05 PM	230	8.0	8.0	8.0	1840		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I Finkley	AMJ	3.19.02	1820
II			
III			

26. ATC Project Manager: Yiannis Efstathiou

27. Result To: _____ Beeper/Phone #'s 646 772-1155

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC	23. Date:	24. Time:
a. Analyzed By:	3/19	21:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field NY-1 (1/01)

CITY_21MC100_011276061

NYC-WTC_000325896

NYC-WTC_000325897

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

7131 P 14584-

RUSH

Page II of

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client:	2. Project Name / 2a. Project Address	3. Project # / 3a. Task #	4. Project Monitor / 4a. Air Sampler:	4c. Rotameter Number:
NYC-BOE	PS 89M / 201 WARREN ST	0819	Daniel Finkley	HP165

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☑ TEM (0.45 micron MCE)	9. Type:
TUES. 3/19/02	ALL FLOORS PLAYGROUND / ROOF	Cassette/Filter Manufacture: Lot #:	Cassette/Filter Manufacture: MULTI-METRIC Lot #:	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

BREATHING ZONE 8 P.M.

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
018				Field Blank CLOSED.									
				Field Blank									
07			OUT SIDE	ROOF - CENTRAL	820 AM	1210	230	8.0	8.0	8.0	1840		
08		IN SIDE		1ST floor HALLWAY OUTSIDE OF CAFETERIA	1152 AM	342	230	8.0	8.0	8.0	1840		
09			OUT SIDE	PLAYGROUND - NORTH END	1215	405	230	8.0	8.0	8.0	1840		
010			↓	PLAYGROUND - SOUTH END.	1217	407	230	8.0	8.0	8.0	1840		
011			↓	ROOF - CENTRAL.	1210	400 PM	230	8.0	8.0	8.0	1840.		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I [signature]	MI	3.19.02	7PM
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:	3/19	21:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Yiannis Efstathiou

27. Result To:
Beeper/Phone #'s 646 772-1155

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field NY-1 (1/01)

CITY_21MC100_011276062

NYC-WTC_000325898

NYC 9/11 Public Portal Document

VATC ASSOCIATES INC.

7131

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

RUSH

14584-

Page III of III

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client	2. Project Name	3. Project #	4. Project Monitor	4c. Rotameter Number
NYC-BOE	PS 89M	0819	Daniel Finkley	HP125
	2a. Project Address: 201 WARREN ST	3a. Task #	4a. Air Sampler:	

5. Date	6. Abatement Location	7. ☐ PCM (0.8 micron MCE)	8. ☑ TEM (0.45 micron MCE)	9. Type
TUES 3/19/02	ALL FLOORS PLAYGROUND / ROOF	Cassette/Filter Manufacture: Lot #:	MULTI-METRIC Cassette/Filter Manufacture: Lot #:	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

BREATHING ZONE

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
019				Field Blank OPEN.									
				Field Blank									
012		IN SIDE		CLASS ROOM 302 SOUTH VENT.	305	625	200	9.0	9.0	9.0	1800		
013				CLASS ROOM ~~302~~ 304 EAST VENT.	310	630	200	9.0	9.0	9.0	1800		
014				CLASS ROOM 526 NORTH VENT	315	635	200	9.0	9.0	9.0	1800		
015				2ND FLOOR HALLWAY SOUTHEND	845	606	201	9.0	9.0	9.0	1809		
016		V		4TH FLOOR HALLWAY SOUTHEND.	240	600	200	9.0	9.0	9.0	1800		

CHAIN OF CUSTODY

	18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I		MI	3.19.02	7PM
II				
III				

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:	3/19	21:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Yiannis Efstathiou

27. Result To:
Beeper/Phone #'s 646 772-1155

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field NY-1 (1/01)

CITY_21MC100_011276063