NYC 9/11 Public Portal Document

EPA Monitoring Site: 455 North End Ave.

Asbestos in Bulk Dust

If a substance contains 1% or more asbestos, it is considered to be an "asbestos-containing material." EPA is using the 1% definition in evaluating dust samples from in and around ground zero and other areas potentially impacted by the World Trade Center collapse. The majority of areas in which EPA has found levels of asbestos in dust above 1% are in the vicinity of the World Trade Center work zone.

The presence of asbestos in dust is not necessarily a significant health hazard. The dust must become airborne and be inhaled for it to cause health problems. Measurements of asbestos in the air are more accurate indicators of the potential for exposure. If dust or debris from the World Trade Center site has entered homes, schools or businesses, it should be cleaned thoroughly and properly following the recommendations of the New York City Department of Health.

Monitor Location: 455 North End Ave.

Date	Analyte	Measurement*
19-SEP-01	ASBESTOS - CHRYSOTILE	1.8%

*The information contained in this database should be considered provisional and may be subject to adjustment upon final analysis.

CITY_21MC100_003066976

NYC-WTC_000332121