NYC-WTC_000335877

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC

7374

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

18/H M894 84319-84339

PROJECT INFORMATION

1. Client	2. Project Name	3. Project #	4. Project Monitor	4c. Rotameter Number
NYC-BOE	H.S. for Leadership and Public Service	14504-864	M. BALOTA	HP-128
	2a. Project Address 607 Hinsity Pl., NY, NY	3a. Task # 01	4a. Air Sampler: -11-	

5. Date	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:		
04.10.02	ENTIRE	Cassette/Filter Manufacture:	Cassette/Filter Manufacture: Multi-Metrics	a. ☐ Background	c. ☐ Abatement	f. ☐ Environmental
		Lot #:	Lot # 01206516	b. ☐ Pre-Abate	d. ☐ Post-Abate	g. ☒ Ambient
					e. ☐ OSHA	h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample ID Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
01				Field Blank									
02				Field Blank									
03				Outside the building - Roof North west corner	07.28	11.18	230	8.0	8.0	8.0	1840.		
04				14th flown - Cafeteria South east corner	07.30	11.15	225	8.0	8.0	8.0	1832.		
05				2nd floor - Auditorium South east corner	07.47	11.34	227	8.0	8.0	8.0	1816.		
06				Basement - Gym Adj. to Room B13	07.50	11.36	226	8.0	8.0	8.0	1808.		
07				1st floor - Lobby North west corner	07.32	11.23	231	8.0	8.0	8.0	1848		
08				Outside the building Adj. to Main Entrance	07.33	11.24	231	8.0	8.0	8.0	1848		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I M. Balota	[illegible]	04/10/02	21:05
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC Lab	23. Date:	24. Time:
a. Analyzed By:	4/11	2:35
b. QC By:		
c. Lab Batch #: 7374		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
~~TEM - AHERA~~

26. ATC Project Manager	27. Result To:	28. Comments:
M. Tenjeras	Yannis Efstathiou	
	Beeper/Phone #'s (646) 772-1155	

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_003060127

NYC-WTC_000335878

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.

7374

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

M894

PROJECT INFORMATION

1. Client:	2. Project Name: H.S. for Leadership and Public Service	3. Project #: 1454-864	4. Project Monitor: M BALOTA	4c. Rotameter Number:
NYC-BOE	2a. Project Address: 80 Trinity Pl, NY, NY	3a. Task # 01	4a. Air Sampler: —11—	HP-128

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture / Lot #	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture: Multi-Metrics Lot # 020G916	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other
04.10.02.	ENTIRE			

DAILY AIR SAMPLE RECORD

10 Sample ID Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
09				Outside the building-Roof South east corner	11.18	15.04	226	8.0	8.0	8.0	1808		
10				1st floor - Lobby North West corner	11.23	15.08	225	8.0	8.0	8.0	1800.		
11				Outside the building Adj. to Main Entrance	11.24	15.09	225	8.0	8.0	8.0	1800.		
12				13th floor - hallway Next to Elevator # 3	15.24	19.14	230	8.0	8.0	8.0	1840		
13				10th floor - Room # 1005 Inside the room	15.28	19.17	229	8.0	8.0	8.0	1832		
14				9th floor - hallway Across Room # 905	15.31	19.19	228	8.0	8.0	8.0	1824		

CHAIN OF CUSTODY

	18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I	M. Balota	[illegible]	04/10/02	2105
II				
III				

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: [illegible]	23. Date:	24. Time:
a. Analyzed By:	4/11	2135
b. QC By:		
c. Lab Batch #: 7374		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
~~TEM - AHERA~~

26. ATC Project Manager:	27. Result To: Yannis Efstathiou Beeper/Phone #: (646) 772-1155	28. Comments:
M. Tenjeeen		

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_003060128

NYC-WTC_000335879

VATC ASSOCIATES INC.

7374

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

M894

PROJECT INFORMATION

1. Client:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number:
NYC - BOE	H.S. for Leadership and Public Service	14584-864	M BALOTA	HB-128
	2a. Project Address: 90 Trinity Pl, NY, NY	3a. Task # 01	4a. Air Sampler: -11-	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture / Lot #	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture: MULTI-Metrics Lot # 01206916	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other
04.10.02	ENTIRE			

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
21				Field Blank Mailed Blank									
				Field Blank									
15				8th floor - Room # 809 Inside the room	15.35	19.22	227	8.0	8.0	8.0	1816		
16				7th floor - hallway Adj. to Room # 713	15.37	19.25	228	8.0	8.0	8.0	1824		
17				6th floor - Room # 610 Inside the room	15.41	19.28	227	8.0	8.0	8.0	1816		
18				5th floor - hallway In front of Rm # 515	15.44	19.30	226	8.0	8.0	8.0	1808		
19				4th floor - Room # 404 Inside the room	15.47	19.32	225	8.0	8.0	8.0	1800		
20				3rd floor - hallway By Elevator # 4	15.50	19.35	225	8.0	8.0	8.0	1800.		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I M. Balota	[illegible]	04/10/02	2105
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC Lab	23. Date:	24. Time:
a. Analyzed By: [illegible]	4/11	2:35
b. QC By:		
c. Lab Batch #: 7374		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager:	27. Result To:	28. Comments:
M. Ferguson	Yanis Efstathiou Beeper/Phone #'s (646) 772-1133	

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_003060129

NYC 9/11 Public Portal Document