ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 03-14-02

CLIENT: NYC BOE

PROJECT ADDRESS: Stuyvesant HS (M477)/345 Chambers St.
NY, NY 10007

PROJECT NO: 19125-0246
SAMPLED BY: H. Antonyan

SAMPLE DATE: 03-13-02
DATE RECEIVED: 03-13-02
DATE ANALYZED: 03-13-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
01	9723	5th Floor Cafeteria Floor	<9.0	9.0
02	9723	5th Floor Cafeteria Window Sill	6.1	4.5
03	9723	3rd Floor Aux. GYM Floor	<9.0	9.0
04	9723	3rd Floor Aux. GYM Window Sill	<18.0	18.0
05	9723	1st Floor Pool Area Floor	<9.0	9.0
06	9723	1st Floor Pool Area Window Sill	<4.7	4.7
07	9723	Auditorium Floor	<9.0	9.0
08	9723	1st Floor Lobby Area Floor	<9.0	9.0
09	9723	2nd Floor Lobby Area Floor	<9.0	9.0
10	9723	5ht Floor Hallway Middle Floor	<9.0	9.0
11	9723	4th Floor Hallway Middle Floor	<9.0	9.0
12	9723	Rm 301E Floor	<9.0	9.0
13	9723	Rm 301E Window Sill	<6.5	6.5
14	9723	Rm 250N Floor	<9.0	9.0

NYC 9/11 Public Portal Document

NYC-WTC_000336809

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

15	9723	Rm 250N Window Sill	<3.2	3.2
16	9723	Rm 125S Floor	<9.0	9.0
17	9723	Rm 125S Window Sill	<10.8	10.8
18	9723	Blank	< 9.0 µg	9.0 µg
19	9723	Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg

NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft^2, Window sills 250 µg/ft^2, Window wells 400 µg/ft^2, Exterior surfaces 800 µg/ft^2.

NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC Environmental Inc. (ATC) is accredited by the New York State Department of Health Environmental Laboratory Approval Program (NYS DOH ELAP) to perform analysis of lead in paint and dust wipes (ELAP #10879).

NYC 9/11 Public Portal Document

NYC-WTC_000336810

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.
DUST WIPE SAMPLING - CHAIN OF CUSTODY
104 EAST 25TH STREET, 10TH FLOOR
NEW YORK, NEW YORK 10010
PHONE: 212-353-8280 FAX: 212-353-8306

9723

TOTAL # OF SAMPLES 19

Client Name: New York City Board of Education
Project Number: 19125-0246
Date: 3/13/02
Project Address: Stuyvesant HS (M477)/345 Chambers str,NY,NY 10007
Project Manager: Y. Efstathiou
Turnaround Time: Rush
Investigator: Herant Anlonyan
Building Type: School
Analysis Required: Lead in dust

Sample ID#	Room, Component, Location	Surface Condition	Dimension of sample area (in. x in.)	Detection Limit	Result (µg/ft²)
M 477 - 3-13-02 1	5th floor Cafeteria Floor	✓ No Visible Dust or Debris	12 x 12	9.0	< 9.0
2	5th floor Cafeteria Window Sill	✓ No Visible Dust or Debris	48 x 6	45	6.1
3	3rd floor Aux. Gym Floor	✓ No Visible Dust or Debris	12 x 12	9.0	< 9.0
4	3rd floor Aux Gym Window Sill	✓ No Visible Dust or Debris	36 x 2	18.0	< 18.0
5	1st floor Pool area Floor	✓ No Visible Dust or Debris	12 x 12	9.0	< 9.0

COMMENTS: Please call the project manager with results @ 1(646) 772-1155 (ADDITIONAL COMMENTS ON BACK)

RELINQUISHED BY (SIGNATURE BELOW):	DATE/TIME	RECIEVED BY (SIGNATURE BELOW):	DATE/TIME	LABORATORY:	
H. Anlonyan	3-13-02	ATC 03/13 8pm			
PRINT NAME:		PRINT NAME:		NLLAP#	ELAP#

CITY_21MC100_003072967

NYC-WTC_000336811

NYC 9/11 Public Portal Document

9723

ATC ASSOCIATES INC.
DUST WIPE SAMPLING - CHAIN OF CUSTODY

101 EAST 25TH STREET, 10TH FLOOR
NEW YORK, NEW YORK 10010
PHONE: 212-353-8280 FAX: 212-353-8306

TOTAL # OF SAMPLES: 19

Client Name: New York City Board of Education | Project Number: 19125-0246 | Date: 3-13-02

Project Address: Stuyvesant HS (M477)/345 Chambers str,NY,NY 10007 | Project Manager: Y. Efstathiou | Turnaround Time: Rush

Investigator: Herant Antonyan | Building Type: School | Analysis Required: Lead in dust

Sample ID#	Room, Component, Location	Surface Condition	Dimension of sample area (in. x in.)	Detection Limit	Result (µg/ft²)
M477 - 3-13-02 6	1st floor Pool area Window Sill	___ Visible Dust ___ Visible Debris ✓ No Visible Dust or Debris	46 x 6	4.7	< 4.7
7	Auditorium Floor	___ Visible Dust ___ Visible Debris ✓ No Visible Dust or Debris	12 x 12	9.0	< 9.0
8	1st floor Lobby area Floor	___ Visible Dust ___ Visible Debris ✓ No Visible Dust or Debris	12 x 12	9.0	< 9.0
9	2nd floor Lobby area Floor	___ Visible Dust ___ Visible Debris ✓ No Visible Dust or Debris	12 x 12	9.0	< 9.0
10	5th floor Hallway, middle Floor	___ Visible Dust ___ Visible Debris ✓ No Visible Dust or Debris	12 x 12	9.0	< 9.0

COMMENTS: Please call the project manager with results @ 1(646) 772-1155 (ADDITIONAL COMMENTS ON BACK)

RELINQUISHED BY (SIGNATURE BELOW):	DATE/TIME	RECIEVED BY (SIGNATURE BELOW):	DATE/TIME	LABORATORY:	
H. Antonyan	3-13-02	Alex 03/13 Span			
PRINT NAME:		PRINT NAME:		NLLAP#	ELAP#

CITY_21MC100_003072968

NYC-WTC_000336812

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.
DUST WIPE SAMPLING - CHAIN OF CUSTODY
104 EAST 25TH STREET, 10TH FLOOR
NEW YORK, NEW YORK 10010
PHONE: 212-353-8280 FAX: 212-353-8306

9723

TOTAL # OF SAMPLES 19

Client Name: New York City Board of Education | Project Number: 19125-0246 | Date: 3-13-02

Project Address: Stuyvesant HS (M477)/345 Chambers str,NY,NY 10007 | Project Manager: Y. Efstathiou | Turnaround Time: Rush

Investigator: Herant Antonyan | Building Type: School | Analysis Required: Lead in dust

Sample ID#	Room, Component, Location	Surface Condition	Dimension of sample area (in. x in.)	Detection Limit	Result (µg/ft²)
M477-3-13-02 11	4th floor Hallway, middle Floor	___ Visible Dust ___ Visible Debris ✓ No Visible Dust or Debris	12x12	9.0	< 9.0
12	Rm. 301 E. Floor	___ Visible Dust ___ Visible Debris ✓ No Visible Dust or Debris	12x12	9.0	< 9.0
13	Rm. 301 E. Window Sill	___ Visible Dust ___ Visible Debris ✓ No Visible Dust or Debris	40x5	6.5	< 6.5
14	Rm. 250 N. Floor	___ Visible Dust ___ Visible Debris ✓ No Visible Dust or Debris	12x12	9.0	< 9.0
15	Rm. 250 N. Window Sill	___ Visible Dust ___ Visible Debris ✓ No Visible Dust or Debris	10x40	3.2	< 3.2

COMMENTS: Please call the project manager with results @ 1(646) 772-1155 (ADDITIONAL COMMENTS ON BACK)

RELINQUISHED BY (SIGNATURE BELOW):	DATE/TIME	RECIEVED BY (SIGNATURE BELOW):	DATE/TIME	LABORATORY:	
H. Antonyan	3-13-02	AA 03/13 8pm			
PRINT NAME:		PRINT NAME:		NLLAP#	ELAP#

CITY_21MC100_0003072969

NYC-WTC_000336813

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.
104 EAST 25TH STREET, 10TH FLOOR
NEW YORK, NEW YORK 10010
PHONE: 212-353-8280 FAX: 212-353-8306

DUST WIPE SAMPLING - CHAIN OF CUSTODY

9723

TOTAL # OF SAMPLES: 19

Client Name: New York City Board of Education

Project Number: 19125-0246

Date: 3-13-02

Project Address: Stuyvesant HS (M477)/345 Chambers str,NY,NY 10007

Project Manager: Y. Efstathiou

Turnaround Time: Rush

Investigator: Herant Antonyan

Building Type: School

Analysis Required: Lead in dust

Sample ID#	Room, Component, Location	Surface Condition	Dimension of sample area (in. x in.)	Detection Limit	Result (µg/ft²)
M477 - 3-13-02 16	Rm. 125 S. Floor	___ Visible Dust ___ Visible Debris ✓ No Visible Dust or Debris	12×12	9.0	< 9.0
17	Rm. 125 S. Window Sill	___ Visible Dust ___ Visible Debris ✓ No Visible Dust or Debris	40×3	10.8	< 10.8
18	Blank	___ Visible Dust ___ Visible Debris ___ No Visible Dust or Debris		9.0µg	< 9.0µg
19	Blank	___ Visible Dust ___ Visible Debris ___ No Visible Dust or Debris		9.0µg	< 9.0 µg
		___ Visible Dust ___ Visible Debris ___ No Visible Dust or Debris			

COMMENTS: Please call the project manager with results @ 1(646) 772-1155 (ADDITIONAL COMMENTS ON BACK)

RELINQUISHED BY (SIGNATURE BELOW):	DATE/TIME	RECIEVED BY (SIGNATURE BELOW):	DATE/TIME	LABORATORY:	
H. Antonyan	3-13-02	03/13 Koch Sign			
PRINT NAME:		PRINT NAME:		NLLAP#	ELAP#

CITY_21MC100_0003072970

NYC-WTC_000336814