NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1987
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 10/12/01
ADDRESS: 345 Chambers St., NY, NY 10282

10/13/01

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
1	PIER #25 NORTHEAST OF STUYVESANT H.S.	1600	0900	3	3	1440	0	0	<16.67	<0.0045
2	PIER #25 NORTH WEST OF STUYVESANT H.S.	1601	0901	3	3	1440	0	0	<16.67	<0.0045

TECHNICIAN: DIMITRIOS M. SALIS
ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX TO D.D.C OFFICE	RECEIVED AT LAB BY: ML SAMPLE CONDITION UPON RECEIPT: DATE/TIME: 10/13

ANALYST: [signature]
DATE RECEVED: 10/13/01
DATE OF ANALYSIS 10/13/01

1200

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

RECEIVED KAM CONSULTANTS 2001 OCT 13 AM 8:51

P.02
DDC
OCT-14-2001 08:25
10/13/2001 12:26 7187293774 KAM CONSULTANTS PAGE 02/02
CITY_21MC100_003062285
NYC-WTC_000337303