NYC-WTC_000340334

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME: ☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard ☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

5505 53/58 60079-60136

PROJECT INFORMATION

1. Client	2. Project Name / 2a. Project Address	3. Project #	4. Project Monitor / 4a. Air Sampler	4c. Rotameter Number
NYC - BOE	HS FOR ECONOMICS & FINANCE (M833) / 105 Trinity Place, NY, NY 10006	14584-0790	Yiannis Efstathiou / Horant Antonyan	HP-120

5. Date	6. Abatement Location	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type
0/3/01	ENTIRE	Cassette/Filter Manufacture: ____ Lot #: ____	Cassette/Filter Manufacture: NUC Lot #: 98117617	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10 Sample ID Number	11 Pump Number	12 Sample Location: 12a IWA	12b OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (l/min): 14a. Start	14b. End	14b. Avg	15 Total Air Vol. (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc. F/CC
54				Field Blank									
55				Field Blank									
01				Library - 1002	14:42	17:43	181	10	10	10	1810		
02				10th Floor hallway by office #1001	14:43	17:44	181	10	10	10	1810		
03				Office # 1006 ~~10th Fl~~	14:44	17:45	181	10	10	10	1810		
04				10th Floor staircase #10	14:46	17:47	181	10	10	10	1810		
05				10th Floor Men's toilet	14:47	17:48	181	10	10	10	1810		
06				9th Floor hallway by Room #903	14:50	17:51	181	10	10	10	1810		

CHAIN OF CUSTODY

18. Relinquished By	19. Received By	20. Date:	21. Time:
I. Yiannis Efstathiou		10/4	10:30
II.			
III.			

22a. AIC Project Manager: ANDREAS C. ANDREOU

27. Result To: ANDREAS C. ANDREOU

Beeper/Phone #'s: (646) 772-1153

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: TCA	23. Date:	24. Time:
a. Analyzed By:	10/5	1:30
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology:
PCM - NIOSH 7400A
TEM - AHERA

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/00)

CITY_21MC100_00927964 6

NYC-WTC_000340335

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

PROJECT INFORMATION

5 6 6

1. Client	2. Project Name / 2a. Project Address	3. Project #	4. Project Monitor / 4a. Air Sampler	4c. Rotameter Number
NYC - BOE	HS FOR ECONOMICS & FINANCE (M833) / 100 Trinity Place, NY, NY 10006	14584-0790	Yiannis Efstathiou / Herant Antonyan	HP-120

5. Date	6. ~~Abatement~~ Location	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:
0/3/01	ENTIRE	Cassette/Filter Manufacture: ____ Lot #: ____	Cassette/Filter Manufacture: ____ Lot #: ____	a. ☐ Background b. ☐ Pre Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Other g. ☒ Ambient

DAILY AIR SAMPLE RECORD

10. Sample ID Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
56				Field Blank									
57				Field Blank									
58				Sealed Room # 903									
07					14:51	17:52	181	10	10	10	1810		
08				Office #913	14:53	17:55	182	10	10	10	1820		
09				Staircase #A - 9th Floor	14:54	17:56	182	10	10	10	1820		
10				Room # 933	14:55	17:57	182	10	10	10	1820		
11				Cafeteria - 8th Floor (East side	14:57	17:58	182	10	10	10	1820		
12				Cafeteria - 8th Floor - (North-west side)	14:58	17:59	181	10	10	10	1810		

CHAIN OF CUSTODY

18. Relinquished By	19. Received By	20. Date:	21. Time:
I Yiannis Efstathiou		10/4	19:30
II			
III			

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:	10/5	1:30
b. QC By:		
c. Lab Batch #:		

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: ANDREAS C. ANDREOU

27. Result To: ANDREAS C. ANDREOU
Beeper/Phone #'s: (646) 772-1153

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY 1 (1/00)

CITY_21MC100_00927964?

NYC-WTC_000340336

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME: ☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard ☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

5006

PROJECT INFORMATION

1. Client	2. Project Name / 2a. Project Address	3. Project #	4. Project Monitor / 4a. Air Sampler	4c. Rotameter Number
NYC - BOE	H.S. FOR ECONOMICS & FINANCE (M833) / 100 Trinity Place, NY, NY 10006	14584-0790	Yiannis Efstathiou / Hrant Antonyan	HP-120

5. Date	6. Abatement Location	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture / Lot #	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture / Lot #	9. Type:
10/3/01	ENTIRE			a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample ID Number	11. Pump Number	12. Sample Location: 12a IWA	12b OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
13				8th Floor - Kitchen	14:59	18:00	181	10	10	10	1810		
14				Room #801	15:01	18:02	181	10	10	10	1810		
15				Staircase #B - 8th Floor	15:02	18:03	181	10	10	10	1810		
16				Classroom #706	15:04	18:05	181	10	10	10	1810		
17				7th Floor hallway by Boy's toilet	15:05	18:07	182	10	10	10	1820		
18				Staircase #B - 7th Floor	15:06	18:08	182	10	10	10	1820		

CHAIN OF CUSTODY

18. Relinquished By	19. Received By	20. Date:	21. Time:
I. Yiannis Efstathiou		10/6	15:30
II.			
III.			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:	10/5	11:30
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
(TEM - AHERA)

26. ATC Project Manager	27. Result To / Beeper/Phone #'s	28. Comments:
ANDREAS C. ANDREOU	ANDREAS C. ANDREOU (646) 772-1153	

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/00)

CITY_21MC100_00927964B

NYC-WTC_000340337

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

PROJECT INFORMATION 5 6 0 6

1. Client	2. Project Name / 2a. Project Address	3. Project #	4. Project Monitor / 4a. Air Sampler	4c. Pictameter Number
NYC - BOE	H.S. FOR ECONOMICS & FINANCE (M833) / 105 Trinity Place, NY, NY 10006	14584-0790	Ioannis Epstathiou / Hercant Antonyan	HP-120

5. Date	6. Abatement Location	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type
0/3/01	ENTIRE	Cassette/Filter Manufacture: ____ Lot #: ____	Cassette/Filter Manufacture: ____ Lot #: ____	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample ID Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
19				G.R #703	15:07	18:09	182	10	10	10	1820		
20				7th Floor hallway by G.R #702	15:08	18:10	182	10	10	10	1820		
21				Staircase #A - 6th Floor	15:10	18:12	182	10	10	10	1820		
22				C.R # 607	15:11	18:13	182	10	10	10	1820		
23				6th Floor Hallway by Girls toilet	15:12	18:14	182	10	10	10	1820		
24				C.R # 604	15:13	18:15	182	10	10	10	1820		

CHAIN OF CUSTODY

18. Relinquished By	19. Received By	20. Date	21. Time
I Jeannis Epstathiou		10/3	18:30
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date	24. Time
a. Analyzed By:	10/5	1:30
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
(TEM - AHERA)

26. ATC Project Manager: ANDREAS C. ANDREOU

27. Result to: ANDREAS C. ANDREOU
Beeper/Phone #'s: (646) 772-1153

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY 1 (1/00)

CITY_21MC100_00927964 9

NYC-WTC_000340338

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

ATC ASSOCIATES INC

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

PROJECT INFORMATION 5 of 6

1. Client	2. Project Name / 2a. Project Address	3. Project #	4. Project Monitor / 4a. Air Sampler	4c. Rotameter Number
NYC - BOE	HS FOR ECONOMICS & FINANCE (M833) / 100 Trinity Place, NY, NY 10006	14584-0790	Yiannis Efstathiou / Hrant Antonyan	HP-120

5. Date	6. ~~Abatement~~ Location	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type
01/3/01	ENTIRE	Cassette/Filter Manufacture: ____ Lot #: ____	Cassette/Filter Manufacture: ____ Lot #: ____	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample ID Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
25				C.R #605	15:14	18:16	182	10	10	10	1820		
26				C.R #509	15:17	18:18	181	10	10	10	1810		
27				C.R #510	15:18	18:19	181	10	10	10	1810		
28				C.R #507	15:19	18:20	181	10	10	10	1810		
29				5th Floor hallway by Room #503	15:20	18:21	181	10	10	10	1810		
30				Staircase #B - 5th Floor	15:21	18:22	181	10	10	10	1810		

CHAIN OF CUSTODY

18. Relinquished By	19. Received By	20. Date:	21. Time:
I Yiannis Efstathiou		1/3/01	18:30
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC	23. Date:	24. Time:
a. Analyzed By:	1/3/01	1:30
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: ANDREAS C. ANDREOU

27. Result to: ANDREAS C. ANDREOU
Beeper/Phone #'s: (646) 772-1153

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/00)

CITY_21MC100_009279650

NYC-WTC_000340339

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME: ☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard ☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

PROJECT INFORMATION

1. Client	2. Project Name / 2a. Project Address	3. Project #	4. Project Monitor / 4a. Air Sampler	4c. Rotameter Number
NYC - BOE	H.S. FOR ECONOMICS & FINANCE (M833) / 105 Trinity Place, NY, NY 10006	14584-0790	Juanius Efstathiou / Herant Antonyan	HP-120

5. Date	6. ~~Abatement~~ Location	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type
0/3/01	ENTIRE	Cassette/Filter Manufacture: ____ Lot #: ____	Cassette/Filter Manufacture: ____ Lot #: ____	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10 Sample ID Number	11 Pump Number	12 Sample Location: 12a IWA	12b OWA	12c Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15 Total Air Vol. (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc. F/CC
				Field Blank									
				Field Blank									
31				Staircase #A - 4th Floor	15:23	18:25	182	10	10	10	1820		
32				C.R #408	15:24	18:26	182	10	10	10	1820		
33				4th Floor hallway by Office #404	15:25	18:27	182	10	10	10	1820		
34				C.R #406	15:26	18:28	182	10	10	10	1820		
35				Office #404	15:27	18:29	182	10	10	10	1820		
36				C.R #309	15:30	18:31	181	10	10	10	1810		

CHAIN OF CUSTODY

18. Relinquished By	19. Received By	20. Date:	21. Time:
I. Juanius Efstathiou		10/5	19:30
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date	24. Time
a. Analyzed By:	10/5	1:30
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology:
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: ANDREAS C. ANDREOU

27. Result To: ANDREAS C. ANDREOU
Beeper/Phone #'s: (646) 772-1153

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/00)

CITY_21MC100_009279651

NYC-WTC_000340340

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

ATC ASSOCIATES INC

Page 1 of 1

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

PROJECT INFORMATION 5606

1. Client	2. Project Name / 2a. Project Address	3. Project #	4. Project Monitor / 4a. Air Sampler	4c. Rotameter Number
NYC - BOE	HS FOR ECONOMICS & FINANCE (M833) / 100 Trinity Place, NY, NY 10006	14584-0790	Yiannis Epstathiou / Herant Ashkenyan	HP-120

5. Date	6. Abatement Location	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:
10/3/01	ENTIRE	Cassette/Filter Manufacture: Lot #:	Cassette/Filter Manufacture: Lot #	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
37				C.R #~~300~~ 306	15:31	18:32	181	10	10	10	1810		
38				C.R #304	15:32	18:33	182	10	10	10	1810		
39				Office #303	15:33	18:34	181	10	10	10	1810		
40				Staircase #B - 3rd Floor	15:34	18:35	181	10	10	10	1810		
41				2nd Floor - Staircase #A	15:36	18:38	182	10	10	10	1820		
42				C.R #207	15:37	18:39	182	10	10	10	1820		

CHAIN OF CUSTODY

18. Relinquished By	19. Received By	20. Date:	21. Time:
I. Yiannis Epstathiou	[signature]	10/4	18:30
II.			
III.			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:	10/5	1130
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
(TEM - AHERA)

26. ATC Project Manager: ANDREAS C. ANDREOU

27. Result to: ANDREAS C. ANDREOU
Beeper/Phone #'s: (646) 772-1153

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY 1 (1/00)

CITY_21MC100_009279652

NYC-WTC_000340341

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME: ☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard ☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

PROJECT INFORMATION 6006

1. Client	2. Project Name / 2a. Project Address	3. Project #	4. Project Monitor / 4a. Air Sampler	4c. Rotameter Number
NYC - BOE	H.S. FOR ECONOMICS & FINANCE (M833) / 100 Trinity Place, NY, NY 10006	14584-0790	Yiannis Efstathiou / Hrant Antonyan	HP-120

5. Date	6. ~~Abatement~~ Location	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type
0/3/01	ENTIRE	Cassette/Filter Manufacture: ____ Lot #: ____	Cassette/Filter Manufacture: ____ Lot #: ____	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample ID Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
43				2nd Floor Gallery by Room #203	15:38	18:40	182	10	10	10	1820		
44				C.R #204	15:39	18:41	182	10	10	10	1820		
45				C.R #205	15:40	18:42	182	10	10	10	1820		
46				1st Floor Lobby by Room #102A	15:42	18:43	181	10	10	10	1810		
47				Room #105	15:43	18:44	181	10	10	10	1810		
48				Auditorium - East side	15:44	18:45	181	10	10	10	1810		

CHAIN OF CUSTODY

18. Relinquished By	19. Received By	20. Date:	21. Time:
I Yiannis Efstathiou		10/4	19:30
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:	10/5	1:30
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology:
PCM - NIOSH 7400A
(TEM - AHERA)

26. ATC Project Manager	27. Result To / Beeper/Phone #'s	28. Comments:
ANDREAS C. ANDREOU	ANDREAS C. ANDREOU (646) 772-1153	

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/00)

CITY_21MC100_009279653

NYC-WTC_000340342

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME: ☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard ☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

PROJECT INFORMATION 5006

1. Client	2. Project Name / 2a. Project Address	3. Project #	4. Project Monitor / 4a. Air Sampler	4c. Rotameter Number
NYC - BOE	HS FOR ECONOMICS & FINANCE (M833) / 100 Trinity Place, NY, NY 10006	14584-0790	Yiannis Efstathiou / Herant Antonyan	HP-120

5. Date	6. Abatement Location	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture / Lot #	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture / Lot #	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other
0/3/01	ENTIRE			

DAILY AIR SAMPLE RECORD

10. Sample ID Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
49				Auditorium - east side	15:45	18:46	181	10	10	10	1810		
50				Room #104	15:46	18:47	181	10	10	10	1810		
51				Gym in the basement (South side)	15:49	18:50	181	10	10	10	1810		
52				Gym in the basement (North-east side)	15:50	18:51	181	10	10	10	1810		
53				Staircase #B - Basement	15:51	18:52	181	10	10	10	1810		

CHAIN OF CUSTODY

18. Relinquished By	19. Received By	20. Date:	21. Time:
I Yiannis Efstathiou		10/4	19:30
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: EMSL	23. Date	24. Time:
a. Analyzed By:	10/5	1:30
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager	27. Result To: / Beeper/Phone #'s	28. Comments:
ANDREAS C. ANDREOU	ANDREAS C. ANDREOU (646) 772-1153	

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/00)

CITY_21MC100_009279654