NYC 9/11 Public Portal Document

New York State Department of Labor
Public Employee Safety and Health Bureau

Vehicle Contamination Sampling

SAMPLE # 1/15/02-#11-17

Vehicle Location or ID: Engine 4 - Ladder 15 42 South St. - Ladder 15

Vehicle Type: Ladder 15 Seagrave

Asbestos

Sample Location of wipe:	Before vents turned on	After vents turned on
	___ Dashboard	___ Dashboard
	___ Front seat	___ Front seat
	___ Floor	___ Floor
	___ Back seat	___ Back seat
	X Other: from Console #11	X Other: defroster unit near ceiling & Windshield - #13

X rear cab wall-#

Metals

Sample Location of wipe:		
	___ Dashboard	___ Dashboard
	___ Front seat	___ Front seat
	___ Floor	___ Floor
	___ Back seat	X Back seat - #17 ✓
	X Other: Top of radio unit on dash #12	X Other: near ceiling behind driver seat #14

Other: Mercury

Sample Location of wipe:		
	___ Dashboard	X Dashboard - #15 ✓
	___ Front seat	___ Front seat
	___ Floor	___ Floor
	___ Back seat	___ Back seat
	___ Other:	___ Other:

At site - not decontaminated initially

Sample Date: 1/15/02

Sampled By: M. Thorsland / C. Jay

CITY_21MC100_012359730

NYC-WTC_000356325