NYC 9/11 Public Portal Document

New York State Department of Labor
Public Employee Safety and Health Bureau

Vehicle Contamination Sampling

SAMPLE # 1-17-02-#16-21

Vehicle Location or ID: Engine 16-Ladder 7 234 E. 29th St,

Vehicle Type: Ladder 7 Truck

Asbestos

Sample Location of wipe:	Before vents turned on	After vents turned on
	___Dashboard	___Dashboard
	___Front seat	___Front seat
	___Floor	___Floor
	___Back seat	___Back seat
16-top of radio on dash	X Other:	X Other: blower unit near windshield-19

(21) X-airbag unit on side of truck

Metals

Sample Location of wipe:		
	___Dashboard	___Dashboard
	___Front seat	___Front seat
	___Floor	___Floor
	___Back seat	___Back seat
17-top of clipboard front seat passenger side	X Other:	X Other: rear wall of rear cab-20

Other: Mercury

Sample Location of wipe:		
	X Dashboard-18	___Dashboard
	___Front seat	___Front seat
	___Floor	___Floor
	___Back seat	___Back seat
	___Other:	___Other:

(In-house decon)
At site from start (arrived before 2nd plane hit + there when towers collapsed)

Sample Date: 1-17-02

Sampled By: M. Thorsland/C. Jay

NYC-WTC_000356331